

## 1.10 Photographs

### Housing Authority

**We suggest that non-logo mud flaps should be used rather than advertise for local suppliers.**



**This is the area that could house the needed industrial pressure washer.**



**We found a clean air system. This represents an acceptable level of driver pre-trip and PM process.**



**This damaged cargo door was ordered for replacement.**




**The fuel tank vents are close to the garage bay door. We are concerned that possible conditions could allow vapors to waft into the garage ceilings where gas fired heaters operate.**



**Both mechanics are well trained and rightfully proud of their expertise.**



**An oil water separator was constructed into the buildings plan. This area could make an excellent work bay.**



**The large storage container hampers vehicle access into and out of the garage.**



**Tires left outside collect rain water that provides mosquito breeding areas. They also detract from an otherwise orderly garage area.**



**This vehicle appears too small for the attached load. It may not handle safely in an emergency stop.**



**Fleet appearance is well maintained. This accident which occurred on a Thursday was estimated for repair on Monday and scheduled for immediate repair.**

