

3940 Taz Hyde Road Culvert Replacement

Existing Conditions

Description:

The culvert structure consists of a 27' long 36" CMP culvert with no headwalls located approximately 50' north of the featured address, 3940 Taz Hyde Road. The corrugated metal pipe shows surface corrosion with areas of 100% section loss. The pipe has partially collapsed under the roadway and is restricting the channel flow. Additionally, the inlet is partially crushed, and the pavement shows an area of patched settlement/failure.

Spans: 1

Length: 27'

Width: 36"

Rise: 36"

Reasons for replacement:

- ✓ Embankment Erosion
- ✓ 100% Section Loss
- ✓ Pipe Collapse
- ✓ Patched Roadway Settlement/Failure



Crushed Inlet



Collapsed CMP



Patched Roadway Settlement/Failure

