

**Master RFS Detail Report**

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190169	09/27/18	083050G02100CO	<b>1025 MAXWELL AVE</b>	ACT ABATE		Violation Inspection - PS	10/12/2018
Original Complaint:						<u>Source:</u> OTHER SOURCE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188523	09/04/18	02900024200	<b>4114 KNIPFER RD</b>	ACT ABATE	01	Violation Inspection - PS	10/04/2018
Original Complaint:						<u>Source:</u> INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188536	09/04/18	05905023400	<b>3005 SUNNYVIEW DR</b>	ACT ABATE	01	Violation Inspection - PS	09/25/2018
Original Complaint: High grass & weeds						<u>Source:</u> PHONE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188568	09/04/18	05700000400	<b>5096 BULL RUN RD</b>	ACT ABATE	01	Violation Inspection - PS	10/06/2018
Original Complaint: Remodeling without permit, Added Apt. above garage. Buried propane tank under ground. No perr						<u>Source:</u> Codes Online	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188569	09/04/18	05700011000	<b>5110 BULL RUN RD</b>	ACT ABATE	01	Violation Inspection - PS	10/06/2018
Original Complaint: Boat and camper in front yard.						<u>Source:</u> Codes Online	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188572	09/04/18	05700002400	<b>5358 OLD HICKORY BLVD</b>	ACT ABATE	01	Violation Inspection - PS	10/06/2018
Original Complaint: Storing commercial equipment on property, Dilapidated barn.						<u>Source:</u> Codes Online	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188574	09/04/18	05600001500	<b>5315 OLD HICKORY BLVD</b>	ACT ABATE	01	Violation Inspection - PS	10/06/2018
Original Complaint: Dilapidated barn, Inoperable dump truck						<u>Source:</u> Codes Online	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188578	09/04/18	04700016100	<b>5515 OLD HICKORY BLVD</b>	ACT ABATE	01	Violation Inspection - PS	10/06/2018
Original Complaint: Inoperable vehicles. Storage container on property.						<u>Source:</u> Codes Online	

**Master RFS Detail Report**

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188579	09/04/18	05909000600	<b>3225 KINGS LN</b>	ACT ABATE	01	Violation Inspection - PS	10/12/2018
Original Complaint: Parking on grass, Inoperable vehicle, Dilapidated fence. Junk trash and debris						<u>Source: Codes Online</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188611	09/04/18	05500005900	<b>4169 BULL RUN RD</b>	ACT ABATE	01	Violation Inspection - PS	10/16/2018
Original Complaint: trailer dilapidated						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188649	09/05/18	06904021100	<b>3420 W HAMILTON AVE</b>	ACT ABATE	01	Violation Inspection - PS	10/19/2018
Original Complaint: HOW TAKEN: PHONE Tiffany McGarr. 615-238-7503. Doors won't lock. Baseboard heat doesn't work. Dilapidated window Electrical issues.						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188760	09/06/18	05913015700	<b>3313 KINGS LN</b>	ACT ABATE	01	Violation Inspection - PS	10/04/2018
Original Complaint: 2 brown couches in front yard						<u>Source: Codes Online</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188816	09/06/18	05700000500	<b>5100 BULL RUN RD</b>	ACT ABATE	01	Violation Inspection - PS	10/09/2018
Original Complaint:						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188835	09/07/18	01400014000	<b>7180 HARPER RD</b>	ACT ABATE	01	Violation Inspection - PS	10/29/2018
Original Complaint: Junk trash and debris. Dilapidated mailbox.						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188856	09/07/18	06900002402	<b>4007 DRAKES BRANCH RD</b>	TRANSFERRD	01		
Original Complaint: High grass/weeds						<u>Source: HUB</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188885	09/10/18	08012001800	<b>3207 PANORAMA DR</b>	ACT ABATE	01	Violation Inspection - PS	10/18/2018
Original Complaint: Junk, trash & debris						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188913	09/10/18	05812003600	<b>680 PUTNAM DR</b>	ACT ABATE	01	Violation Inspection - PS	09/21/2018
Original Complaint:						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189064	09/12/18	05900001600	<b>4580 CLARKSVILLE PIKE</b>	ACT ABATE	01	Violation Inspection - PS	10/29/2018
Original Complaint: Type: Property Violations - Tall Grass and Weeds						<u>Source: HUB</u>	

Description:  
big strip of grass not cut between the property line

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189728	09/19/18	01514005500	<b>7628 GERALD DR</b>	TRANSFERRD	01		
Original Complaint: Type: Property Violations - Tree Concerns						<u>Source: HUB</u>	

Description:  
Trees, vines, shrubs from neighboring farm land growing on power/cable lines weighing it down will soon affect use of my driveway. Have spoken with Comcast they do not remove growth from lines. spoke with land owner Ellis Jakes he stated he would not fix the problem.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189888	09/24/18	06903003000	<b>4005 FAIRVIEW DR</b>	ACT ABATE	01	Violation Inspection - PS	10/25/2018
Original Complaint: Type: Property Violations - Residential Complaint						<u>Source: HUB</u>	

Description:  
They constantly have cars,trucks, and even different types of equipment on lawn

Additional Comments:

**Master RFS Detail Report**

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189910	09/24/18	00800002000	<b>8081 WHITES CREEK PIKE</b>	ACT ABATE	01	Violation Inspection - PS	10/26/2018
Original Complaint: HOW TAKEN: PHONE auto repair business, doing it late night, starts around 7pm						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190045	09/25/18	06903002900	<b>4009 FAIRVIEW DR</b>	ACT ABATE	01	Violation Inspection - PS	10/25/2018
Original Complaint: IMV Boat Storage						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190047	09/25/18	06903002800	<b>4011 FAIRVIEW DR</b>	ACT ABATE	01	Violation Inspection - PS	10/25/2018
Original Complaint: IMV in yard						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190048	09/25/18	06903000800	<b>4006 FAIRVIEW DR</b>	ACT ABATE	01	Violation Inspection - PS	10/25/2018
Original Complaint: IMV in yard						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190050	09/25/18	08008025700	<b>3240 MEXICO DR</b>	ACT ABATE	01	Violation Inspection - PS	10/19/2018
Original Complaint: HIGH GRASS WEEDS						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190150	09/26/18	058100B00800CO	<b>3308 BROME LN</b>	ACT ABATE	01	Violation Inspection - PS	10/29/2018
Original Complaint: Type: Property Violations - Tall Grass and Weeds						<u>Source: HUB</u>	

Description:

Trash, Wood pallets, Broken bird Bath on the side of the house and they will not cut the grass in the backyard.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190239	09/28/18	02100005900	<b>6483 CLARKSVILLE PIKE</b>	ACT ABATE	01	Violation Inspection - PS	10/20/2018
Original Complaint: camper and IMV						<u>Source: EMAIL</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188500	09/04/18	06009000200	<b>2746 OLD MATTHEWS RD</b>	ACT ABATE	02	Violation Inspection - PS	10/12/2018
Original Complaint: Dilapidated house.						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188549	09/04/18	07101004000	<b>529 YOKLEY RD</b>	ACT ABATE	02	Violation Inspection - PS	10/19/2018
Original Complaint: Yolanda Johnson. 615-589-1593. Water coming in basement when rains.						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188651	09/05/18	08103016900	<b>1211 KELLOW ST</b>	ACT VEHROW	02	Admin Staff Review - PS	09/12/2018
Original Complaint: Inoperable Toyota Red Tercel.						<u>Source: Codes Online</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188665	09/05/18	07113000700	<b>0 CUMBERLAND BND</b>	ACT ABATE	02	Violation Inspection - PS	09/19/2018
Original Complaint: DEBRIS						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188672	09/05/18	05915000900	<b>709 MOORMANS ARM RD</b>	ACT HSGDEM	02	People Update - PS	09/11/2018
Original Complaint: Severe hoarding - is occupied, unsanitary conditions - dilapidated structure. Vicious dog on premises.						<u>Source: EMAIL</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188736	09/05/18	08103016900	<b>1211 KELLOW ST</b>	ACT ABATE	02	Violation Inspection - PS	10/05/2018
Original Complaint: imv						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188761	09/06/18	08102005200	<b>1730 MCKINNEY AVE</b>	ACT ABATE	02	Violation Inspection - PS	10/05/2018
Original Complaint: Junk trash and debris at alley.						<u>Source: Codes Online</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188763	09/06/18	08103002600	<b>2145 18TH AVE N</b>	ACT ABATE	02	Warrant Check - PS	11/06/2018
Original Complaint: Junk left at the curb						<u>Source: Codes Online</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188818	09/06/18	08102005500	<b>1742 MCKINNEY AVE</b>	ACT ABATE	02	Violation Inspection - PS	10/11/2018
Original Complaint: TRASH AT REAR BY ALLEY						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188855	09/07/18	06004000400	<b>333 HOMESTEAD RD</b>	ACT ABATE	02	Violation Inspection - PS	10/10/2018
Original Complaint: imv jtd parking on grass						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188869	09/07/18	081072K00100CO	<b>842 GOFF ST</b>	ACT ABATE	02	Violation Inspection - PS	09/24/2018
Original Complaint: High grass/weeds						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188886	09/10/18	08107004300	<b>1404 CASS ST</b>	ACT ABATE	02	Violation Inspection - PS	10/16/2018
Original Complaint: Type: Property Violations - Junk and Debris						<u>Source: HUB</u>	

Description:  
Always trash, furniture and garbage left here

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188890	09/10/18	07009011400	<b>3107 CLIFF DR</b>	TRANSFERRD	02		
Original Complaint: High grass/weeds						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188939	09/10/18	05911016300	<b>676 ROWAN DR</b>	PENDING	02	Env Court 1st Setting - PS	10/24/2018
Original Complaint: not owner occupied						<u>Source: EMAIL</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188958	09/10/18	06004000700	<b>343 HOMESTEAD RD</b>	ACT ABATE	02	Warrant Check - PS	11/12/2018
Original Complaint: high grass and weeds						<u>Source: INSPECTOR REPORTED</u>	

**Master RFS Detail Report**

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188959	09/10/18	06004000600	<b>339 HOMESTEAD RD</b>	ACT ABATE	02	Warrant Check - PS	11/12/2018
Original Complaint: high grass and weeds						<u>Source:</u> INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188960	09/10/18	06004000500	<b>335 HOMESTEAD RD</b>	ACT ABATE	02	Warrant Check - PS	11/12/2018
Original Complaint: high grass and weeds						<u>Source:</u> INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188967	09/10/18	081020Y00200CO	<b>2402 HYDE ST</b>	PENDING	02	Env Court 1st Setting - PS	10/31/2018
Original Complaint: not owner occupied						<u>Source:</u> EMAIL	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189004	09/11/18	08107004600	<b>2105 14TH AVE N</b>	ACT ABATE	02	Violation Inspection - PS	10/09/2018
Original Complaint: IMV/PKIN/DEBRIS						<u>Source:</u> INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189056	09/12/18	06013015400	<b>2749 COMBS DR</b>	ACT ABATE	02	Violation Inspection - PS	10/18/2018
Original Complaint: Junk, trash & debris						<u>Source:</u> PHONE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189127	09/13/18	07106007000	<b>1440 BRICK CHURCH PIKE</b>	ACT ABATE	02	Violation Inspection - PS	10/12/2018
Original Complaint: Type: Property Violations - Tall Grass and Weeds						<u>Source:</u> HUB	

Description:  
Overgrown eyesore-- allows trash to collect easily.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189169	09/13/18	06000000200	<b>509 EWING DR</b>	ACT ABATE	02	Violation Inspection - PS	10/11/2018
Original Complaint:						<u>Source:</u> INSPECTOR REPORTED	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189216	09/13/18	06014002601	<b>1973 SOUTHERLAND DR</b>	ACT ABATE	02	Violation Inspection - PS	10/26/2018

Original Complaint: Type: Property Violations - Dilapidated Structures Source: HUB

Description:  
The roof is leaking when it rains and mold has formed on interior walls. Management has known about it for months. Employees are working in unhealthy environment

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189311	09/14/18	07106008600	<b>304 W TRINITY LN</b>	ACT ABATE	02	Violation Inspection - PS	10/12/2018

Original Complaint: Type: Property Violations - Tall Grass and Weeds Source: HUB

Description:  
Abandoned daycare-- over grown weeds--

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189368	09/17/18	07102011000	<b>460 ROGER WILLIAMS AVE</b>	ACT ABATE	02	Violation Inspection - PS	10/18/2018

Original Complaint: High grass bushes blocking view Source: EMAIL

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189383	09/17/18	08108000100	<b>831 GOFF ST</b>	PENDING	02		

Original Complaint: Type: Property Violations - Short Term Rental Complaint Source: HUB

Description:  
Listing for 9 bedrooms and for 16+ guests.  
<https://www.airbnb.com/rooms/20980320?location=Nashville%2C%20TN&adults=14&s=uySF-U6s>

Additional Comments:

**Master RFS Detail Report**

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189389	09/17/18	08108000200	<b>829 GOFF ST</b>	PENDING	02	Initial Violation Inspection - PS	09/18/2018
Original Complaint: Type: Property Violations - Short Term Rental Complaint						<u>Source: HUB</u>	

Description:

This 4 bedroom house is listed for 19 Guests. They also illegally serve alcohol.  
<https://www.airbnb.com/rooms/21177218?location=Nashville%2C%20TN&adults=14&s=uySF-U6s>

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189461	09/17/18	08103024900	<b>0 10TH AVE N</b>	ACT ABATE	02	Violation Inspection - PS	10/18/2018
Original Complaint: Type: Public Safety - Abandoned Vehicles						<u>Source: HUB</u>	

Description:

Behind the Looby Library on Rosa Parks Blvd, there is a parking lot for a park and there is a 4 door Nissan Altima TN plate 4k4-7Uo that looks abandoned there. Thank you for your attention to this matter.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189602	09/18/18	05911001100	<b>706 ROWAN DR</b>	ACT ABATE	02	Violation Inspection - PS	10/26/2018
Original Complaint: Dilapidated home						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189603	09/18/18	05911001200	<b>704 ROWAN DR</b>	ACT ABATE	02	Violation Inspection - PS	10/26/2018
Original Complaint: Dilapidated home						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189653	09/19/18	06916019000	<b>1814 COUNTY HOSPITAL RD</b>	ACT ABATE	02	Violation Inspection - PS	11/05/2018
Original Complaint: Apt A. outlets are frying and causing fires, no fire detectors, roof is going to cave in. Arnetta Hayes 615-755-4792.						<u>Source: PHONE</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189791	09/20/18	07005002700	<b>2403 STIVERS ST</b>	ACT ABATE	02	Violation Inspection - PS	10/26/2018

Original Complaint: Type: Property Violations - Residential Complaint  
Source: HUB

Description:  
 Concert in residential neighborhood  
<https://www.eventbrite.com/e/flames-final-show-tickets-49974398772>

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189946	09/24/18	07013010100	<b>2136 CLIFF DR</b>	TRANSFERRD	02		

Original Complaint: Both windows leaking water/ mold on walls. 10th floor Unit #12/ Problem with sink.  
Source: PHONE

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190062	09/25/18	06004001200	<b>326 HOMESTEAD RD</b>	ACT ABATE	02	Violation Inspection - PS	10/25/2018

Original Complaint: inoperable vehicle, parking on grass  
Source: INSPECTOR REPORTED

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190092	09/26/18	07106007200	<b>230 W TRINITY LN</b>	ACT ABATE	02	Violation Inspection - PS	10/26/2018

Original Complaint: HOW TAKEN: EMAIL  
 ILLEGAL DUMPING ON PROPERTY/HIGH GRASS AND WEEDS  
Source: EMAIL

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190184	09/27/18	06007010000	<b>2910 RICH ACRES DR</b>	ACT ABATE	02	Violation Inspection - PS	10/22/2018

Original Complaint: junk trash and debris  
Source: INSPECTOR REPORTED

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190185	09/27/18	05910005300	<b>752 REVELS DR</b>	ACT ABATE	02	Violation Inspection - PS	11/01/2018

Original Complaint: Running business from house. Commercial equipment.  
Source: PHONE

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190186	09/27/18	06007009600	<b>2917 RICH ACRES DR</b>	ACT ABATE	02	Violation Inspection - PS	10/26/2018

Original Complaint: inoperable vehicles, parking on grass  
Source: INSPECTOR REPORTED

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188768	09/06/18	03200014600	<b>4370 BRICK CHURCH PIKE</b>	PENDING	03	Env Court 1st Setting - PS	10/24/2018
Original Complaint: host- no strp permit						<u>Source:</u> EMAIL	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188798	09/06/18	04116007300	<b>1200 EWING CREEK DR</b>	ACT ABATE	03	Violation Inspection - PS	10/08/2018
Original Complaint: inoperable vehicle						<u>Source:</u> INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188860	09/07/18	03213008700	<b>4383 SUMMERTIME DR</b>	ACT ABATE	03	Violation Inspection - PS	10/10/2018
Original Complaint: HOW TAKEN: PHONE Operating a business in a residential area - Auto Repair under the shed of back yard						<u>Source:</u> PHONE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188865	09/07/18	041150A02200CO	<b>1304 EWING CREEK DR</b>	ACT ABATE	03	Violation Inspection - PS	10/08/2018
Original Complaint: inoperable vehicle, parking on grass						<u>Source:</u> INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188900	09/10/18	03209009100	<b>2141 QUAIL RIDGE DR</b>	ACT ABATE	03	Violation Inspection - PS	10/26/2018
Original Complaint: Type: Property Violations - Junk and Debris						<u>Source:</u> HUB	

Description:  
Large amount of debris - old grills, boxes, yard furniture, etc littering the front yard.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189031	09/11/18	05010017000	<b>206 FAWNWOOD CT</b>	ACT ABATE	03	Violation Inspection - PS	10/12/2018
Original Complaint: Type: Property Violations - Junk and Debris						<u>Source:</u> HUB	

Description:  
Junk trash and debris, Inoperable vehicles.

Additional Comments:

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189062	09/12/18	05002007000	<b>3401 MEADOW CT</b>	ACT ABATE	03	Violation Inspection - PS	09/28/2018

Original Complaint: Type: Property Violations - Tall Grass and Weeds  
Source: HUB

Description:  
 Waist High Grass and Weeds

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189118	09/13/18	04115001400	<b>3905 SUSSEX DR</b>	ACT ABATE	03	Violation Inspection - PS	10/09/2018

Original Complaint: Type: Property Violations - Junk and Debris  
Source: HUB

Description:  
 3905 sussex drive nashville tn 37207

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189122	09/13/18	03209009100	<b>2141 QUAIL RIDGE DR</b>	ACT ABATE	03	Violation Inspection - PS	10/26/2018

Original Complaint: Abandoned vehicle parked on public right of way. White Ford Excursion, expired tags: G59-07F (Serial 2017), busted out rear window.  
Source: HUB

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189164	09/13/18	06001015600	<b>3184 EWINGDALE DR</b>	ACT ABATE	03	Violation Inspection - PS	09/28/2018

Original Complaint:  
Source: INSPECTOR REPORTED

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189204	09/13/18	06003017300	<b>3116 A BRICKDALE LN</b>	ACT ABATE	03	Violation Inspection - PS	10/12/2018

Original Complaint: Type: Property Violations - Cars Parked On Lawn  
Source: HUB

Description:  
 Side A. Parking on grass

Additional Comments:

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189211	09/13/18	05002007100	<b>3405 MEADOW CT</b>	ACT ABATE	03	Violation Inspection - PS	10/16/2018
Original Complaint: high grass and weeds						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189214	09/13/18	05014014900	<b>3128 WILMOTH RD</b>	ACT ABATE	03	Warrant Check - PS	11/26/2018
Original Complaint: Premise ID						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189277	09/14/18	03213008400	<b>4405 FALLING LEAF LN</b>	ACT ABATE	03	Violation Inspection - PS	10/19/2018
Original Complaint: Junk, trash & debris in the back yard						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189503	09/17/18	05014026800	<b>3222 MOOREWOOD DR</b>	ACT ABATE	03	Violation Inspection - PS	10/02/2018
Original Complaint: High grass and weeds						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189556	09/18/18	03300005100	<b>1229 OLD DICKERSON PIKE</b>	ACT ABATE	03	Violation Inspection - PS	10/26/2018
Original Complaint: Junk, trash, and debris						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189592	09/18/18	05010018200	<b>3202 WOODSTOCK DR</b>	ACT ABATE	03	Violation Inspection - PS	10/03/2018
Original Complaint: high grass and weeds						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189594	09/18/18	05002002400	<b>3704 WILLOW CREEK RD</b>	ACT ABATE	03	Violation Inspection - PS	10/03/2018
Original Complaint: high grass and weeds						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189762	09/20/18	03300008500	<b>1251 DICKERSON PIKE</b>	ACT ABATE	03	Violation Inspection - PS	10/26/2018
Original Complaint: High grass/weeds						<u>Source: PHONE</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189770	09/20/18	03209000800	<b>100 CRYSTAL CT</b>	ACT VEHROW	03	Violation Inspection CAR - PS	10/11/2018
Original Complaint: inoperable vehicle, invalid tags						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190051	09/25/18	00600006200	<b>2390 BAKER RD</b>	ACT ABATE	03	Violation Inspection - PS	10/29/2018
Original Complaint: dilapidated trailers						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190055	09/25/18	00600006000	<b>2404 BAKER RD</b>	ACT ABATE	03	Violation Inspection - PS	10/15/2018
Original Complaint: dilapidated trailer						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190070	09/25/18	03213001200	<b>4205 WINTERBROOK RD</b>	PENDING	03	Initial Violation Inspection - PS	09/26/2018
Original Complaint: Inoperable wrecked vehicle in back.						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190125	09/26/18	05006005000	<b>3633 VILLAGE TRL</b>	ACT ABATE	03	Violation Inspection - PS	10/11/2018
Original Complaint: high grass and weeds						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190126	09/26/18	05007000800	<b>3700 VILLAGE TRL</b>	ACT ABATE	03	Violation Inspection - PS	10/11/2018
Original Complaint: high grass and weeds						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190128	09/26/18	05007011900	<b>3704 VILLAGE TRL</b>	ACT ABATE	03	Violation Inspection - PS	10/11/2018
Original Complaint: high grass and weeds						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190129	09/26/18	05002000800	<b>3507 BRICK CHURCH PIKE</b>	ACT ABATE	03	Violation Inspection - PS	10/16/2018
Original Complaint: junk trash and debris						<u>Source: INSPECTOR REPORTED</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190187	09/27/18	05006003000	<b>3651 VILLAGE TRL</b>	ACT ABATE	03	Violation Inspection - PS	10/17/2018
Original Complaint: junk trash and debris						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190188	09/27/18	05006006500	<b>400 STANDING STONE CT</b>	ACT ABATE	03	Violation Inspection - PS	10/26/2018
Original Complaint: inoperable vehicle, parking on grass						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190189	09/27/18	06001015500	<b>3155 EWINGWOOD DR</b>	PENDING	03	Initial Violation Inspection - PS	09/28/2018
Original Complaint: broken down vehicle, champagne color suburban						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190190	09/27/18	06001015500	<b>3155 EWINGWOOD DR</b>	PENDING	03	Initial Violation Inspection - PS	09/28/2018
Original Complaint: silver Nissan, hood is messed up, tags expired						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190191	09/27/18	06001015500	<b>3155 EWINGWOOD DR</b>	PENDING	03	Initial Violation Inspection - PS	09/28/2018
Original Complaint: small chevy car, no tags						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190297	09/28/18	06002006700	<b>3139 BRICKDALE LN</b>	ACT ABATE	03	Violation Inspection - PS	11/01/2018
Original Complaint: Inoperable vehicle on property.						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188518	09/04/18	161150C34500CO	<b>2340 ZERMATT AVE</b>	ACT ABATE	04	Violation Inspection - PS	10/16/2018
Original Complaint: JTD in back						<u>Source: INSPECTOR REPORTED</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188934	09/10/18	180040A18400CO	<b>2316 FOREST LAKE DR</b>	ACT ABATE	04	Violation Inspection - PS	10/15/2018
Original Complaint: Top portion of house; Ms. Ashley Callis (615) 769-9989 single family dwelling turned into multiple family dwellings; electrical & plumbing problems						Source: PHONE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188988	09/11/18	161130B13100CO	<b>131 HONEY CREEK LN</b>	ACT ABATE	04	Violation Inspection - PS	09/25/2018
Original Complaint: high grass and weeds along fence line.						Source: PHONE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189081	09/12/18	172030B00700CO	<b>5329 WINDYPINE DR</b>	ACT ABATE	04	Violation Inspection - PS	10/22/2018
Original Complaint: HOW TAKEN: PHONE running a car repair/ car re-sale business, Inoperable vehicle on the property						Source: PHONE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189547	09/18/18	16109014400	<b>5533 THALMAN DR</b>	PENDING	04	Initial Violation Inspection - PS	09/19/2018
Original Complaint: Running a STR without a permit						Source: PHONE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189794	09/20/18	17208003900	<b>5913 NOLENSVILLE PIKE</b>	PENDING	04	Env Court 1st Setting - PS	10/31/2018
Original Complaint: commercial tow trucks park in and out thru out night. running tow business						Source: EMAIL	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189970	09/25/18	172030B00700CO	<b>5329 WINDYPINE DR</b>	ACT VEHROW	04	Violation Inspection CAR - PS	10/04/2018
Original Complaint: IMV on ROW Uplander L3 no month on tag						Source: INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189972	09/25/18	172030B00700CO	<b>5329 WINDYPINE DR</b>	ACT VEHROW	04	Violation Inspection CAR - PS	10/04/2018
Original Complaint: IMV on ROW BMW 650I no month on tag						Source: INSPECTOR REPORTED	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189973	09/25/18	172030B00600CO	<b>5333 WINDYPINE DR</b>	ACT VEHROW	04	Violation Inspection CAR - PS	10/04/2018
Original Complaint: IMV on ROW Blue Van						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189974	09/25/18	172030B00600CO	<b>5333 WINDYPINE DR</b>	ACT VEHROW	04	Violation Inspection CAR - PS	10/04/2018
Original Complaint: IMV on ROW Toyota Corolla S Orange/Reddish						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189991	09/25/18	16000010600	<b>527 OLD HICKORY BLVD</b>	PENDING	04	Initial Violation Inspection - PS	09/26/2018
Original Complaint: Type: Property Violations - Tall Grass and Weeds						<u>Source: HUB</u>	

Description:

The grass on this owned/vacant property 527 Old Hickory Blvd., Bwood, 37027 by Pamela Himebaugh is waist high on sidewalks/street. Do not keep it maintained. Looks terrible and it is visible from OHB. Please have owner cut this grass on OHB. Thank you.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189992	09/25/18	16100004200	<b>511 OLD HICKORY BLVD</b>	ACT ABATE	04	Violation Inspection - PS	10/15/2018
Original Complaint: Type: Property Violations - Tall Grass and Weeds						<u>Source: HUB</u>	

Description:

Grass on OHB front on this owned/vacant property is waist high, owners Roy Jones & Chancellor Allen never keep it cut. Please have owners cut this grass by sidewalk and keep it clean. Health hazard plus eyesore for the area. Thank you.

Additional Comments:

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190064	09/25/18	171020A12400CO	<b>272 GLENSTONE CIR</b>	PENDING	04	Initial Violation Inspection - PS	09/26/2018

Original Complaint: Type: Public Safety - Abandoned Vehicles Source: HUB

Description:

A blue/green Toyota camry has been abandoned in front of my townhouse for atleast 3 days. I was out of town - so it could be more days than that - I can only count from the time I returned on Saturday. No one in the neighborhood has claimed the car, it has not moved and I have put a note on it requesting it be moved. Plate #BMT-736. I am wondering if it is possibly stolen or abandonec

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190250	09/28/18	172120A17000CO	<b>517 BRADFORD HILLS PL</b>	PENDING	04	Initial Violation Inspection - PS	09/29/2018

Original Complaint: Type: Property Violations - Tall Grass and Weeds Source: HUB

Description:

Overgrown grass

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190251	09/28/18	172120A01100CO	<b>6032 BRADFORD HILLS DR</b>	PENDING	04	Initial Violation Inspection - PS	09/29/2018

Original Complaint: Type: Property Violations - Tall Grass and Weeds Source: HUB

Description:

Consistently tall grass. Never cuts around trees or mailbox, beds overgrown with weeds.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190253	09/28/18	172120B00800CO	<b>6064 BRADFORD HILLS DR</b>	PENDING	04	Initial Violation Inspection - PS	09/29/2018

Original Complaint: Type: Property Violations - Cars Parked On Lawn Source: HUB

Description:

Car parked on grass for longer than 1 week.

Additional Comments:

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188495	09/04/18	08203047600	<b>901 LISCHEY AVE</b>	ACT ABATE	05	Violation Inspection - PS	09/21/2018
Original Complaint: Parking in grass. Will need night inspection.						<u>Source: Codes Online</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188499	09/04/18	082040B00200CO	<b>1007 B N 5TH ST</b>	ACT ABATE	05	Violation Inspection - PS	10/05/2018
Original Complaint: Grass						<u>Source: Codes Online</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188531	09/04/18	08203052200	<b>911 N 5TH ST</b>	ACT ABATE	05	Warrant Check - PS	12/03/2018
Original Complaint: High grass/weeds						<u>Source: Codes Online</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188679	09/05/18	07112009100	<b>829 CHEROKEE AVE</b>	ACT ABATE	05	Warrant Check - PS	11/12/2018
Original Complaint: junk trash and debris						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188684	09/05/18	07111005100	<b>124 MERIDIAN CT</b>	ACT ABATE	05	Violation Inspection - PS	10/10/2018
Original Complaint: Woman living an older model red sedan parked in the driveway						<u>Source: HUB</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188729	09/05/18	08208008400	<b>706 N 9TH ST</b>	ACT VEHROW	05	Administrative Hearing Vehicle	10/03/2018
Original Complaint: Abandoned blue/gray minivan						<u>Source: HUB</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188730	09/05/18	08208015200	<b>703 N 9TH ST</b>	ACT VEHROW	05	Administrative Hearing Vehicle	10/03/2018
Original Complaint: Inoperable brown truck with riding mower in back.						<u>Source: HUB</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188738	09/05/18	08207044800	<b>606 N 5TH ST</b>	ACT ABATE	05	Violation Inspection - PS	09/14/2018
Original Complaint: HGW						<u>Source: INSPECTOR REPORTED</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188795	09/06/18	07108016500	<b>543 NORTON AVE</b>	ACT ABATE	05	Warrant Check - PS	11/05/2018
Original Complaint: high grass and weeds						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188805	09/06/18	08203016500	<b>1000 STOCKELL ST</b>	ACT VEHROW	05	Administrative Hearing Vehicle	10/03/2018
Original Complaint: Inoperable Ford Focus on row.						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188862	09/07/18	07116008300	<b>1312 MONTGOMERY AVE</b>	ACT ABATE	05	Violation Inspection - PS	10/08/2018
Original Complaint: inoperable vehicle, parking on grass						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188887	09/10/18	08215001600	<b>10 INTERSTATE DR</b>	ACT ABATE	05	Violation Inspection - PS	10/18/2018
Original Complaint: Rm 617-AC leaking causing carpet to be wet, mold and fungi; Huge hold in the wall; Marian Harney						<u>Source: PHONE</u>	
615-578-9701							

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188896	09/10/18	07116015600	<b>745 DOUGLAS AVE</b>	ACT ABATE	05	Violation Inspection - PS	10/12/2018
Original Complaint: Type: Property Violations - Graffiti on Private Property						<u>Source: HUB</u>	

Description:

Graffiti is covering the west side of the building facing the grass lots. Also, several homeless people have started squatting inside the vacant warehouse.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188924	09/10/18	08207025300	<b>216 BERRY ST</b>	TRANSFERRD	05		
Original Complaint: Type: Property Violations - Tall Grass and Weeds						<u>Source: HUB</u>	

Description:

High grass

Additional Comments:

**Master RFS Detail Report**

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189061	09/12/18	07111005100	<b>124 MERIDIAN CT</b>	ACT ABATE	05	Violation Inspection - PS	10/19/2018
Original Complaint:						<u>Source:</u> OTHER SOURCE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189090	09/12/18	08212018700	<b>207 MYRTLE ST</b>	ACT ABATE	05	Violation Inspection - PS	09/28/2018
Original Complaint: Type: Property Violations - Tall Grass and Weeds						<u>Source:</u> HUB	

Description:

Grass is grown up...Hedges are so high you cannot see to pull in and out of the neighbors driveway  
House is vacant and not being taken care of.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189098	09/12/18	08207033600	<b>331 GRACE ST</b>	ACT ABATE	05	Violation Inspection - PS	09/28/2018
Original Complaint: HOW TAKEN: HUB						<u>Source:</u> HUB	
Type: Property Violations - Junk and Debris							

Description:

I've submitted previous complaints about this property and the trash that accumulates on the property. NO WHERE in our neighborhood do residents keep the Metro trash container in the front yard! The residents don't bag the trash which has led to rats and flies. I cannot understand why codes fails repeatedly to address these violations. The 2 units have 6 Metro trash containers and only one is kept in the front yard. Also it's Tuesday (trash day) and the front yard container is full of unbagged trash. Please enforce the codes.

Thank you

Additional Comments: We sent this to PW but entered the complaint here for the loose trash.

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189152	09/13/18	08208035600	<b>934 MANSFIELD ST</b>	ACT ABATE	05	Violation Inspection - PS	09/28/2018
Original Complaint:						<u>Source:</u> INSPECTOR REPORTED	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189165	09/13/18	08208019500	<b>721 MYRTLE ST</b>	ACT ABATE	05	Violation Inspection - PS	10/05/2018
Original Complaint: Type: Property Violations - Cars Parked On Lawn						<u>Source:</u> HUB	

Description:

States that the neighbor has had a truck parked at this address on the lawn for years. The tenant has now placed a lot of trash in the truck and it is blowing everywhere. Also causing rodents.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189219	09/13/18	07205004300	<b>3004 AMBROSE AVE</b>	ACT ABATE	05	Violation Inspection - PS	10/02/2018
Original Complaint: Type: Property Violations - Tall Grass and Weeds						<u>Source:</u> HUB	

Description:

tall grass along roadway

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189296	09/14/18	08204005300	<b>1100 N 8TH ST</b>	ACT ABATE	05	Violation Inspection - PS	10/09/2018
Original Complaint: Type: Property Violations - Cars Parked On Lawn						<u>Source:</u> HUB	

Description:

There are at least 4 cars parked on the lawn at this property. In front of the house on the front lawn there is a gold sedan that hasn't moved in years. A window was busted out on it awhile back and now it is covered with a sheet with a brick.

On the back lawn there is a small red truck with junk in the bed, a white small car, and a Burgundy sedan.

Additional Comments:

**Master RFS Detail Report**

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189298	09/14/18	07112005200	<b>1835 JOY CIR</b>	ACT ABATE	05	Violation Inspection - PS	10/02/2018
Original Complaint: Type: Property Violations - Junk and Debris						<u>Source:</u> HUB	

Description:

Junk/Trash including furniture, vacuum, debris etc. in front of the property as well as on the right si (abandoned dog house and campershell).

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189322	09/14/18	08202004400	<b>928 DICKERSON PIKE</b>	ACT ABATE	05	Violation Inspection - PS	10/12/2018
Original Complaint: High grass/weeds. Vacant lot across from Sugga High Bakery. Right next to 1006 Whites creek pk.						<u>Source:</u> PHONE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189326	09/14/18	08208018400	<b>712 MYRTLE ST</b>	PENDING	05	Violation Inspection - PS	10/01/2018
Original Complaint: Type: Public Safety - Abandoned Vehicles						<u>Source:</u> HUB	

Description:

This vehicle has not moved from this location for 6+ months. It is a Ford Taurus, with Tan, White, a Blue body colored panels, and a bungee cord holding the trunk down. It has PA license plate JSS 5823.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189335	09/14/18	072060W01600CO	<b>1069 K E TRINITY LN</b>	ACT ABATE	05	Violation Inspection - PS	10/05/2018
Original Complaint: HOW TAKEN: EMAIL (HOTLINE TIP) NUISANCE: NOISE. NO STRP PERMIT NUMBER OR IMAGE IN WEBSITE ADVERTISEMENTS.						<u>Source:</u> EMAIL	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189355	09/14/18	08211000900	<b>660 JOSEPH AVE</b>	ACT ABATE	05	Violation Inspection - PS	10/19/2018
Original Complaint: Type: Property Violations - Dilapidated Structures						<u>Source: HUB</u>	

Description:  
Fence for the trash bins is in bad shape. Visible from I-65

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189356	09/14/18	08305008700	<b>710 GALLATIN AVE</b>	ACT ABATE	05	Violation Inspection - PS	10/19/2018
Original Complaint: Type: Property Violations - Graffiti on Private Property						<u>Source: HUB</u>	

Description:  
Graffiti covering trailer that is permanently parked in the rear of the parking lot.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189458	09/17/18	08203048400	<b>916 N 5TH ST</b>	ACT ABATE	05	Violation Inspection - PS	10/04/2018
Original Complaint: Type: Property Violations - Junk and Debris						<u>Source: HUB</u>	

Description:  
Tons of construction  
Stuff in the alley.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189466	09/17/18	07210006000	<b>2819 GALLATIN PIKE</b>	PENDING	05	Initial Violation Inspection - PS	09/18/2018
Original Complaint: Type: Property Violations - Cars Parked On Lawn						<u>Source: HUB</u>	

Description:  
Large potholes and damage on driveway, parking lot, and sidewalk

Additional Comments:

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189467	09/17/18	08203012200	<b>1023 N 2ND ST</b>	ACT ABATE	05	Violation Inspection - PS	10/19/2018
Original Complaint: Dumping junk, trash, and debris onto the alleyway						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189468	09/17/18	08203012400	<b>1017 N 2ND ST</b>	ACT ABATE	05	Violation Inspection - PS	10/19/2018
Original Complaint: Dumped junk, trash, and debris onto the alleyway						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189486	09/17/18	07205004300	<b>3004 AMBROSE AVE</b>	ACT ABATE	05	Violation Inspection - PS	10/02/2018
Original Complaint: premise id, junk trash and debris						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189565	09/18/18	07209000300	<b>849 CHEROKEE AVE</b>	ACT ABATE	05	Violation Inspection - PS	10/04/2018
Original Complaint: Type: Property Violations - Tall Grass and Weeds						<u>Source: HUB</u>	

Description:  
Very tall grass and trash

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189584	09/18/18	07104019700	<b>2107 JONES CIR</b>	PENDING	05	Env Court 1st Setting - PS	11/07/2018
Original Complaint: host- no strp permit						<u>Source: EMAIL</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189589	09/18/18	07108034700	<b>536 E TRINITY LN</b>	ACT ABATE	05	Violation Inspection - PS	10/03/2018
Original Complaint: High grass and weeds						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189591	09/18/18	07205005800	<b>0 E TRINITY LN</b>	ACT ABATE	05	Violation Inspection - PS	10/03/2018
Original Complaint: High grass and weeds						<u>Source: INSPECTOR REPORTED</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189601	09/18/18	07103013100	<b>201 QUEEN AVE</b>	ACT ABATE	05	Violation Inspection - PS	10/04/2018
Original Complaint: high grass weeds						<u>Source:</u> PHONE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189680	09/19/18	08203050600	<b>1028 N 5TH ST</b>	ACT VEHROW	05	Violation Inspection CAR - PS	10/01/2018
Original Complaint: Type: Public Safety - Abandoned Vehicles						<u>Source:</u> HUB	

Description:

Totalled BMW on the corner of Evanston and N 5th St has been unmoved for a month.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189700	09/19/18	07209000300	<b>849 CHEROKEE AVE</b>	ACT ABATE	05	Violation Inspection - PS	10/15/2018
Original Complaint: junk trash and debris						<u>Source:</u> INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189701	09/19/18	07112009600	<b>839 CHEROKEE AVE</b>	ACT ABATE	05	Violation Inspection - PS	10/04/2018
Original Complaint: high grass and weeds						<u>Source:</u> INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189703	09/19/18	07112009600	<b>839 CHEROKEE AVE</b>	ACT ABATE	05	Violation Inspection - PS	10/04/2018
Original Complaint: junk trash and debris						<u>Source:</u> INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189705	09/19/18	07103013100	<b>201 QUEEN AVE</b>	ACT ABATE	05	Violation Inspection - PS	10/04/2018
Original Complaint: parking on grass						<u>Source:</u> INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189719	09/19/18	08301019700	<b>1008 GRANADA CT</b>	ACT ABATE	05	Violation Inspection - PS	10/05/2018
Original Complaint: tall grass						<u>Source:</u> PHONE	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189780	09/20/18	08203012400	<b>1017 N 2ND ST</b>	ACT ABATE	05	Violation Inspection - PS	10/30/2018
Original Complaint: dilapidated structure						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189832	09/21/18	07112005100	<b>1839 JOY CIR</b>	ACT ABATE	05	Violation Inspection - PS	10/05/2018
Original Complaint: high grass and weeds						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189833	09/21/18	07112005100	<b>1839 JOY CIR</b>	ACT ABATE	05	Violation Inspection - PS	10/05/2018
Original Complaint: Junk trash and debris						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189868	09/24/18	07112033500	<b>1431 LISHEY AVE</b>	PENDING	05	Initial Violation Inspection - PS	09/25/2018
Original Complaint: Type: Property Violations - Short Term Rental Complaint						<u>Source: HUB</u>	

Description:

This Airbnb listing is for 7 bedrooms instead of the 4 allowed in Metro's ordinance.  
<https://www.airbnb.com/rooms/3107569>

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189883	09/24/18	08208017200	<b>414 MYRTLE ST</b>	PENDING	05	Initial Violation Inspection - PS	09/25/2018
Original Complaint: Abandoned vehicle on right of way.						<u>Source: Metro PD</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190049	09/25/18	07112008600	<b>823 CHEROKEE AVE</b>	ACT ABATE	05	Violation Inspection - PS	10/25/2018
Original Complaint: junk trash and debris, inoperable vehicles, parking on the grass						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190054	09/25/18	07112008600	<b>823 CHEROKEE AVE</b>	ACT ABATE	05	Violation Inspection - PS	10/15/2018
Original Complaint: high grass and weeds						<u>Source: INSPECTOR REPORTED</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190065	09/25/18	08203021600	<b>215 CLEVELAND ST</b>	ACT ABATE	05	Violation Inspection - PS	10/19/2018

Original Complaint: Type: Property Violations - Tall Grass and Weeds  
Source: HUB

Description:  
 Very tall grass

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190098	09/26/18	08301025300	<b>914 GALLATIN AVE</b>	ACT ABATE	05	Violation Inspection - PS	10/29/2018

Original Complaint: Type: Property Violations - Graffiti on Private Property  
Source: HUB

Description:  
 Graffiti on the exterior of the abandon former service station.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190130	09/26/18	08211000900	<b>590 JOSEPH AVE</b>	ACT ABATE	05	Violation Inspection - PS	11/02/2018

Original Complaint: Ronneshia Ennis. 615-720-2586. Missing bedroom doors, Ceiling leaking during rain. Garbage disposal not working.  
Source: PHONE

Description:  
 illegal use of land. mdha doesnt allow surface parking as a use. there are 18 wheelers parked the

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190143	09/26/18	08202005200	<b>900 DICKERSON PIKE</b>	ACT ABATE	05	Violation Inspection - PS	11/02/2018

Original Complaint: Type: Property Violations - Cars Parked On Lawn  
Source: HUB

Description:  
 illegal use of land. mdha doesnt allow surface parking as a use. there are 18 wheelers parked the

Additional Comments:

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190173	09/27/18	07107023200	<b>1801 MERIDIAN ST</b>	PENDING	05	Initial Violation Inspection - PS	09/28/2018

Original Complaint: Type: Property Violations - Junk and Debris  
Source: HUB

Description:  
 Junk trash and debris. Dump load of tires on property

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190183	09/27/18	07107018600	<b>1802 MERIDIAN ST</b>	ACT ABATE	05	Violation Inspection - PS	10/17/2018

Original Complaint: junk trash and debris  
Source: INSPECTOR REPORTED

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190192	09/27/18	08202005100	<b>902 DICKERSON PIKE</b>	ACT ABATE	05	Violation Inspection - PS	11/02/2018

Original Complaint: tractor trailer parking  
Source: INSPECTOR REPORTED

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190193	09/27/18	08208030900	<b>906 CHICAMAUGA AVE</b>	ACT VEHROW	05	Violation Inspection CAR - PS	10/11/2018

Original Complaint: Type: Public Safety - Abandoned Vehicles  
Source: HUB

Description:  
 Nissan Quest has been here for months on edge of drive way without licence plate

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190266	09/28/18	07111052300	<b>1409 A MERIDIAN ST</b>	ACT ABATE	05	Violation Inspection - PS	10/19/2018

Original Complaint: HOW TAKEN: EMAIL  
 (HOTLINE TIP) (1)SIMULTANEOUS RENTAL TO MORE THAN ONE PARTY UNDER SEPARATE CONTRACTS. (2) NO STRP PERMIT NUMBER OR IMAGE IN WEBSITE ADVERTISEMENTS.  
Source: EMAIL

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190275	09/28/18	08208034400	<b>944 MAXWELL AVE</b>	PENDING	05	Initial Violation Inspection - PS	09/29/2018

Original Complaint: Abandoned/inoperable Black 4 door vehicle with flat tires and rusty hood  
Source: PHONE

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190276	09/28/18	08305014300	<b>1011 MAXWELL AVE</b>	PENDING	05	Initial Violation Inspection - PS	09/29/2018
Original Complaint: Inoperable red Ford pickup truck						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188553	09/04/18	08305040200	<b>511 N 14TH ST</b>	ACT ABATE	06		
Original Complaint: Fence built not within setback.						<u>Source: Codes Online</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188567	09/04/18	08307033400	<b>2338 OAK CT</b>	ACT ABATE	06	Violation Inspection - PS	10/08/2018
Original Complaint: Inoperable vehicle without tag parked in the drive way						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188585	09/04/18	08313043000	<b>1601 LILLIAN ST</b>	ACT ABATE	06	Violation Inspection - PS	10/06/2018
Original Complaint: Fence built out of compliance.						<u>Source: Codes Online</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188586	09/04/18	08302002000	<b>1315 GREENWOOD AVE</b>	ACT ABATE	06	Violation Inspection - PS	10/06/2018
Original Complaint: Fence not to code						<u>Source: Codes Online</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188587	09/04/18	08314018100	<b>1618 FATHERLAND ST</b>	ACT ABATE	06	Violation Inspection - PS	10/06/2018
Original Complaint: Fence not to code						<u>Source: Codes Online</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188618	09/05/18	08315009300	<b>229 RIVERSIDE DR</b>	PENDING	06	Initial Violation Inspection - PS	09/06/2018
Original Complaint: HOW TAKEN: HUB High grass/weeds in the backyard						<u>Source: HUB</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188753	09/06/18	08216040600	<b>918 SHELBY AVE</b>	ACT ABATE	06	Violation Inspection - PS	09/28/2018
Original Complaint: Broken windows in building.						<u>Source: Codes Online</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188944	09/10/18	09304002100	<b>627 SHELBY AVE</b>	ACT ABATE	06	Violation Inspection - PS	10/15/2018
Original Complaint: Type: Property Violations - Dilapidated Structures						<u>Source: HUB</u>	

Description:  
Fence not built to code

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188945	09/10/18	08313022000	<b>1101 SHELBY AVE</b>	ACT ABATE	06	Violation Inspection - PS	10/15/2018
Original Complaint: Type: Property Violations - Dilapidated Structures						<u>Source: HUB</u>	

Description:  
Fence not built to codes

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188962	09/10/18	08306030400	<b>2101 EASTLAND AVE</b>	ACT ABATE	06	Violation Inspection - PS	10/11/2018
Original Complaint: Type: Property Violations - Junk and Debris						<u>Source: HUB</u>	

Description:  
Caller states dumpster is not fully inclosed. Roll-off dumpster is overflowing with trash. Vultures picking through trash.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188991	09/11/18	08312007700	<b>2600 BRITTANY CT</b>	PENDING	06	Initial Violation Inspection - PS	09/12/2018
Original Complaint: Type: Property Violations - Residential Complaint						<u>Source: HUB</u>	

Description:  
High grass. Needs cutting.

Additional Comments:

**Master RFS Detail Report**

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188992	09/11/18	08309000900	<b>1107 ORDWAY PL</b>	ACT ABATE	06	Violation Inspection - PS	09/28/2018
Original Complaint: Type: Property Violations - Junk and Debris						<u>Source:</u> HUB	

Description:

There are branches, construction materials and a ton of trash just hanging out on their property beside their garage. It is an eye sore for the neighbors.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189008	09/11/18	08302009000	<b>1407 SHARPE AVE</b>	PENDING	06	Env Court 1st Setting - PS	10/31/2018
Original Complaint: not owner occupied						<u>Source:</u> EMAIL	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189047	09/11/18	08303025100	<b>2230 CARTER AVE</b>	ACT ABATE	06	Violation Inspection - PS	10/16/2018
Original Complaint: EXTERIOR REPAIR, INOPERABLE/UNLICENSED MOTOR VEHICLES, INTERIOR REPAIR, JUN TRASH, AND DEBRIS						<u>Source:</u> EMAIL	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189065	09/12/18	08310026500	<b>203 N 18TH ST</b>	ACT ABATE	06	Violation Inspection - PS	10/13/2018
Original Complaint: Type: Property Violations - Dilapidated Structures						<u>Source:</u> HUB	

Description:

This house was left over 6 months ago in the middle of construction. It has now become an unsafe and overgrown property. Neighbors have complained of bugs and rodents overrunning the property. Please help!

Additional Comments:

**Master RFS Detail Report**

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189080	09/12/18	08405002000	<b>2605 TIFFANY DR</b>	PENDING	06	Initial Violation Inspection - PS	09/13/2018
Original Complaint: Type: Property Violations - Cars Parked On Lawn						<u>Source:</u> HUB	

Description:  
 This has turned into a real problem and hazard.  
 There is noise, smells, and fluids and chemicals running into the lawns

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189132	09/13/18	09308004600	<b>1012 OZARK ST</b>	ACT VEHROW	06	Administrative Hearing Vehicle	10/03/2018
Original Complaint: Type: Public Safety - Abandoned Vehicles						<u>Source:</u> HUB	

Description:  
 This truck has been setting in the same spot for years. It has rusting festering trash in the bed and cabin of the truck. There are a variety of plants growing in the cabin as well as from out of the hood of the vehicle. The side door window is either down or busted out. The neighborhood is doing its best to make Ozark Street more livable and walkable. We try to keep it clean despite multiple occasions of illegal dumping of bulk items and incidences such as various people thinking it is an okay spot to burn rubber coating off wires that were probably stolen from new buildings in order to make money at the scrap yard downtown. An abandoned decrepit vehicle like this invites more activity like this to happen.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189135	09/13/18	08313049500	<b>1511 SHELBY AVE</b>	ACT ABATE	06	Violation Inspection - PS	10/15/2018
Original Complaint: Type: Other - Other						<u>Source:</u> HUB	

Description:  
 fence not to codes

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189144	09/13/18	09401034400	<b>712 VILLAGE CT</b>	ACT ABATE	06	Violation Inspection - PS	09/28/2018
Original Complaint:						<u>Source:</u> INSPECTOR REPORTED	

**Master RFS Detail Report**

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189146	09/13/18	08306026700	<b>115 CHAPEL AVE</b>	ACT ABATE	06	Violation Inspection - PS	10/13/2018
Original Complaint: Type: Other - Other						<u>Source:</u> HUB	

Description:  
sign violation, 35 foot corner visibility, fence not to codes

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189147	09/13/18	09401034700	<b>706 VILLAGE CT</b>	ACT ABATE	06	Violation Inspection - PS	09/28/2018
Original Complaint:						<u>Source:</u> INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189149	09/13/18	09401003400	<b>520 S 14TH ST</b>	ACT ABATE	06	Violation Inspection - PS	10/05/2018
Original Complaint:						<u>Source:</u> INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189301	09/14/18	09308004100	<b>1000 S 11TH ST</b>	ACT ABATE	06	Violation Inspection - PS	10/11/2018
Original Complaint: Screws sticking out from fence						<u>Source:</u> PHONE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189354	09/14/18	08312002900	<b>2412 BARCLAY DR</b>	PENDING	06	Initial Violation Inspection - PS	09/15/2018
Original Complaint: Type: Property Violations - Tall Grass and Weeds						<u>Source:</u> HUB	

Description:  
Tall Grass in Front Yard, for weeks and Trash in front and in Backyard..

Additional Comments:

**Master RFS Detail Report**

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189373	09/17/18	08307002900	<b>839 PORTER RD</b>	ACT VEHROW	06	Violation Inspection CAR - PS	10/12/2018
Original Complaint: Type: Public Safety - Abandoned Vehicles						<u>Source: HUB</u>	

Description:

It's a black Mercury Grand Marquis. It's been here for over two weeks and I don't think anyone is coming for it. The drivers side window has been open during periods of hard rain.  
Please do not tow the Ford Fusion and the Honda Pilot.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189390	09/17/18	09304004300	<b>622 SHELBY AVE</b>	PENDING	06	Initial Violation Inspection - PS	09/18/2018
Original Complaint: Type: Property Violations - Short Term Rental Complaint						<u>Source: HUB</u>	

Description:

Listing is for 5 bedrooms and for 16 Guests. It also advertises for parties and events.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189462	09/17/18	08212035400	<b>947 WOODLAND ST</b>	ACT ABATE	06	Violation Inspection - PS	10/26/2018
Original Complaint: Type: Other - Other						<u>Source: HUB</u>	

Description:

Check the electrical systems at this building please the power and lights filler when you run equipment. board members are doing own electrical but are not licensed electricians how can that pass the electrical codes compliance.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189538	09/18/18	08301034701	<b>1106 SHARPE AVE</b>	ACT ABATE	06	Violation Inspection - PS	10/26/2018
Original Complaint: Type: Other - Other						<u>Source: HUB</u>	

Description:

fence not to codes

Additional Comments:

**Master RFS Detail Report**

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189612	09/18/18	08313004500	<b>1205 FATHERLAND ST</b>	PENDING	06	Env Court 1st Setting - PS	11/14/2018
Original Complaint: host- no strp permit						<u>Source:</u> EMAIL	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189622	09/18/18	08314013600	<b>1703 B FATHERLAND ST</b>	ACT ABATE	06	Violation Inspection - PS	10/09/2018
Original Complaint: HOW TAKEN: PHONE (HOTLINE CALL) NO STRP PERMIT NUMBER OR IMAGE IN THE WEBSITE ADVERTISEMENT						<u>Source:</u> PHONE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189761	09/20/18	08304021200	<b>514 ROSEBANK AVE</b>	ACT ABATE	06	Violation Inspection - PS	10/23/2018
Original Complaint: INOPERABLE/UNLICENSED VEHICLE - TREE DOWN						<u>Source:</u> INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189767	09/20/18	09402013500	<b>1813 ELECTRIC AVE</b>	ACT ABATE	06	Violation Inspection - PS	11/09/2018
Original Complaint: Type: Property Violations - Tall Grass and Weeds						<u>Source:</u> HUB	

Description:  
grass/weeds overgrown and above 12 inches. Consistent issue at this empty lot.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189792	09/20/18	08309015700	<b>1311 WOODLAND ST</b>	ACT ABATE	06	Violation Inspection - PS	10/26/2018
Original Complaint: Reported events and commercial activities occurring at this location. It is called Luck Mansion - secret concerts, selling clothes - many activities. Reported social media tells about his venues. Please see attached Link for his venue schedule: <a href="https://www.luckjournal.com/">https://www.luckjournal.com/</a>						<u>Source:</u> EMAIL	

Facebook Page: <https://www.facebook.com/lucktexasreunion/>

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189967	09/25/18	08301041700	<b>925 GALLATIN AVE</b>	ACT ABATE	06	Violation Inspection - PS	10/11/2018
Original Complaint: HOW TAKEN: INSPECTOR REPORTED PROHIBITED SIGNS ROW						<u>Source:</u> INSPECTOR REPORTED	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189969	09/25/18	08309021200	<b>1000 WOODLAND ST</b>	ACT ABATE	06	Violation Inspection - PS	10/26/2018

Original Complaint: Type: Property Violations - Junk and Debris Source: HUB

Description:

The Family Dollar parking lot is frequently covered in litter. This blows into Woodland St. and 10th St. This store does a terrible job at maintaining its property.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190096	09/26/18	09401027500	<b>518 S 15TH ST</b>	ACT VEHROW	06	Violation Inspection CAR - PS	10/11/2018

Original Complaint: Type: Public Safety - Abandoned Vehicles Source: HUB

Description:

There is a silver truck that's been parked at the corner for a couple years. The registration expired in 2017.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190097	09/26/18	08306035200	<b>508 N 17TH ST</b>	ACT ABATE	06	Abate Notice Generated - PS	10/01/2018

Original Complaint: Type: Property Violations - Tall Grass and Weeds Source: HUB

Description:

Tall grass and weeds in front yard

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190139	09/26/18	08302018600	<b>1612 DOUGLAS AVE</b>	ACT ABATE	06	Violation Inspection - PS	10/12/2018

Original Complaint: Type: Other - Other Source: HUB

Description:

Failure to maintain landscaping. The front of this house is being overtaken by shrubs and bushes.

Additional Comments:

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190174	09/27/18	08315003900	<b>2811 FORTLAND DR</b>	ACT ABATE	06	Violation Inspection - PS	10/11/2018
Original Complaint: HIGH GRASS AND WEEDS						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190175	09/27/18	08315003900	<b>2811 FORTLAND DR</b>	ACT ABATE	06	Violation Inspection - PS	10/31/2018
Original Complaint: INOPERABLE/UNLICENSED VEHICLE						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190260	09/28/18	09304004200	<b>624 SHELBY AVE</b>	PENDING	06	Initial Violation Inspection - PS	09/29/2018
Original Complaint: white van with flat tires						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190268	09/28/18	08314005800	<b>1711 RUSSELL ST</b>	PENDING	06	Initial Violation Inspection - PS	09/29/2018
Original Complaint: Dilapidated fence around swimming pool.						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190287	09/28/18	08313049500	<b>1511 SHELBY AVE</b>	PENDING	06	Initial Violation Inspection - PS	09/29/2018
Original Complaint: Renting property as a STR without a permit						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188524	09/04/18	07208008200	<b>2101 GENEIVA DR</b>	PENDING	07	Env Court 1st Setting - PS	10/17/2018
Original Complaint: no strp permit						<u>Source: EMAIL</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188582	09/04/18	05201018700	<b>220 ROBINWOOD AVE</b>	ACT ABATE	07	Violation Inspection - PS	10/18/2018
Original Complaint: junk trash debris, inoperable vehicle						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188701	09/05/18	08304027700	<b>2609 SOLON DR</b>	PENDING	07	Initial Violation Inspection - PS	09/06/2018
Original Complaint: High grass/weeds						<u>Source: PHONE</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188702	09/05/18	08304027600	<b>2605 SOLON DR</b>	PENDING	07	Initial Violation Inspection - PS	09/06/2018
Original Complaint: Inoperable vehicle (vehicle propped up on blocks)						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188742	09/05/18	06115011400	<b>1138 ARDEE AVE</b>	ACT ABATE	07	Violation Inspection - PS	09/20/2018
Original Complaint: HIGH, GRASS, AND WEEDS						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188743	09/05/18	06115011400	<b>1138 ARDEE AVE</b>	ACT ABATE	07	Violation Inspection - PS	10/10/2018
Original Complaint: SHED IN DISREPAIR						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188789	09/06/18	07208008300	<b>2103 GENEIVA DR</b>	ACT ABATE	07	Violation Inspection - PS	09/26/2018
Original Complaint: High grass/weeds						<u>Source: HUB</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188790	09/06/18	07208008200	<b>2101 GENEIVA DR</b>	ACT ABATE	07	Violation Inspection - PS	09/26/2018
Original Complaint: High grass/weeds						<u>Source: HUB</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188791	09/06/18	07208005200	<b>2117 GENEIVA DR</b>	ACT ABATE	07	Violation Inspection - PS	09/26/2018
Original Complaint: High grass/weeds						<u>Source: HUB</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188793	09/06/18	07207034800	<b>1316 LOVE JOY CT</b>	ACT ABATE	07	Violation Inspection - PS	10/01/2018
Original Complaint: Junk, trash, and debris						<u>Source: HUB</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188808	09/06/18	07215023500	<b>1500 PORTER RD</b>	ACT ABATE	07	Violation Inspection - PS	10/04/2018
Original Complaint: Q-02. Natasha Horton. 629-772-0872. Water leaking in the apt. Dilapidated windows.						<u>Source: PHONE</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188863	09/07/18	07313015900	<b>2709 MAILAN DR</b>	PENDING	07	Initial Violation Inspection - PS	09/08/2018
Original Complaint: Inoperable Mercury Sable on row.						<u>Source: Codes Online</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188898	09/10/18	08304027800	<b>2613 SOLON DR</b>	ACT ABATE	07	Violation Inspection - PS	09/26/2018
Original Complaint: High grass & weeds						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188948	09/10/18	08401000500	<b>2500 SHERIDAN RD</b>	ACT ABATE	07	Violation Inspection - PS	09/26/2018
Original Complaint: High grass & weeds						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188949	09/10/18	08401000500	<b>2500 SHERIDAN RD</b>	ACT ABATE	07	Violation Inspection - PS	09/26/2018
Original Complaint: Junk, trash & debris; Mr. Patrick Cole is in the nursing home according to caller Ms. Lisa Blunkall (615) 240-9237.						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189018	09/11/18	07313008500	<b>1722 WELCOME LN</b>	PENDING	07	Env Court 1st Setting - PS	10/31/2018
Original Complaint: not owner occupied						<u>Source: EMAIL</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189048	09/11/18	07204022500	<b>1521 MCGAVOCK PIKE</b>	ACT ABATE	07	Violation Inspection - PS	10/02/2018
Original Complaint: (HOTLINE TIP) NUISANCE NOISE. NO STRP PERMIT NUMBER OR IMAGE IN THE AirBnB ADVERTISEMENT.						<u>Source: EMAIL</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189058	09/12/18	07313013700	<b>1511 ROSEBANK AVE</b>	PENDING	07	Initial Violation Inspection - PS	09/13/2018
Original Complaint: Type: Property Violations - Fence Complaints						<u>Source: HUB</u>	

Description:  
fence not to code

Additional Comments:

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189079	09/12/18	07207034800	<b>1316 LOVE JOY CT</b>	ACT ABATE	07	Violation Inspection - PS	10/16/2018
Original Complaint: INOPERABLE/UNLICENSED VEHICLES - WORKING ON CARS - TENT - PARKING ON THE GRASS						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189134	09/13/18	07313013800	<b>1513 ROSEBANK AVE</b>	PENDING	07	Initial Violation Inspection - PS	09/14/2018
Original Complaint: Type: Property Violations - Fence Complaints						<u>Source: HUB</u>	

Description:  
fence not to code

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189148	09/13/18	083031100200CO	<b>2107 CREIGHTON AVE</b>	PENDING	07	Initial Violation Inspection - PS	09/14/2018
Original Complaint: Type: Property Violations - Fence Complaints						<u>Source: HUB</u>	

Description:  
fence not to code

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189242	09/13/18	07210034400	<b>1120 LITTON AVE</b>	PENDING	07	Initial Violation Inspection - PS	09/14/2018
Original Complaint: Apt 617 - Shikemia Johnson - 662-375-4376 - plumbing problems						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189460	09/17/18	07306001800	<b>2712 SHADOW LN</b>	PENDING	07	Initial Violation Inspection - PS	09/18/2018
Original Complaint: Type: Property Violations - Tall Grass and Weeds						<u>Source: HUB</u>	

Description:  
Rental property also parking in the yard not sure how many live there, trees becoming a problem, some neighbors have tried to contact the owner.

Additional Comments:

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189471	09/17/18	06115013900	<b>1215 SUNNYMEADE DR</b>	ACT ABATE	07	Violation Inspection - PS <u>Source: PHONE</u>	10/10/2018

Original Complaint: High grass/weeds

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189579	09/18/18	07309019600	<b>1819 WILLOW SPRINGS DR</b>	PENDING	07	Env Court 1st Setting - PS <u>Source: EMAIL</u>	11/07/2018

Original Complaint: host- no strp permit

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189631	09/18/18	07210031300	<b>1642 CHASE ST</b>	ACT ABATE	07	Violation Inspection - PS <u>Source: HUB</u>	10/15/2018

Original Complaint: Type: Property Violations - Junk and Debris

Description:  
Mattress in front yard for a couple weeks

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189649	09/19/18	07203011600	<b>1135 HOWARD AVE</b>	ACT ABATE	07	Violation Inspection - PS <u>Source: OTHER SOURCE</u>	10/10/2018

Original Complaint: high grass weeds

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189667	09/19/18	07203016000	<b>1320 MCCHESENEY AVE</b>	ACT ABATE	07	Violation Inspection - PS <u>Source: EMAIL</u>	10/03/2018

Original Complaint: HIGH GRASS AND WEEDS IN THE BACK YARD

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189712	09/19/18	07208014900	<b>2229 STRATFORD AVE</b>	ACT ABATE	07	Violation Inspection - PS <u>Source: PHONE</u>	10/15/2018

Original Complaint: Junk, trash, and debris

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189721	09/19/18	07305014700	<b>2205 COOPER LN</b>	PENDING	07	Initial Violation Inspection - PS	09/20/2018
Original Complaint: Type: Property Violations - Illegal Sign on Private Property						<u>Source: HUB</u>	

Description:

"Personal Lawn Care" company uses its commercial signs in residential zone, multiple properties (to be submitted next). They leave them up YEARLONG, and have not returned calls for us to alert the of illegal status of commercial signs.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189722	09/19/18	07204033300	<b>1916 RIVERWOOD DR</b>	PENDING	07	Initial Violation Inspection - PS	09/20/2018
Original Complaint: Type: Property Violations - Illegal Sign on Private Property						<u>Source: HUB</u>	

Description:

"Personal Lawn Care" company uses its commercial signs in residential zone, multiple properties (to be submitted next). They leave them up YEARLONG, and have not returned calls for us to alert the of illegal status of commercial signs.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189723	09/19/18	07204019600	<b>1400 ARDEE AVE</b>	PENDING	07	Initial Violation Inspection - PS	09/20/2018
Original Complaint: Type: Property Violations - Illegal Sign on Private Property						<u>Source: HUB</u>	

Description:

"Personal Lawn Care" company uses its commercial signs in residential zone, multiple properties (to be submitted next). They leave them up YEARLONG, and have not returned calls for us to alert the of illegal status of commercial signs. They also leave signs in b/t properties (probably to make reporting difficult). e.g., This one could be 1400 or 1402 Ardee

Additional Comments:

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189731	09/19/18	07203026000	<b>3516 GOLF ST</b>	ACT ABATE	07	Violation Inspection - PS	09/27/2018

Original Complaint: Type: Property Violations - Junk and Debris Source: HUB

Description:

Trash was picked up yesterday. Trash can is still out. Last week, it was out all week as well. I am concerned that this will become the habit.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189748	09/20/18	07210002100	<b>2907 DAVIS AVE</b>	PENDING	07	Initial Violation Inspection - PS	09/21/2018

Original Complaint: Type: Property Violations - Junk and Debris Source: HUB

Description:

There has been a large fabric arm chair in the front yard since the beginning of the year. You can tell that is trash that the owner just has decided not to remove.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189764	09/20/18	07208006700	<b>2124 GENEIVA DR</b>	PENDING	07	Initial Violation Inspection - PS	09/21/2018

Original Complaint: Type: Property Violations - Cars Parked On Lawn Source: HUB

Description:

There is an RV parked in the front lawn of the house at 2124 Geneva that makes it extremely dangerous for us to pull out of our driveway at 2122 Geneva Dr. It's a fully obstructed view.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189771	09/20/18	05209000802	<b>1119 FERNBANK DR</b>	ACT VEHROW	07	Violation Inspection CAR - PS	10/05/2018

Original Complaint: Abandoned vehicle (Maroon vehicle with expired tags) Source: PHONE

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189772	09/20/18	06115018000	<b>1134 SUNNYMEADE DR</b>	ACT ABATE	07	Violation Inspection - PS	10/10/2018

Original Complaint: High grass/weeds Source: PHONE

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189797	09/21/18	07305015700	<b>2316 DEMARIUS DR</b>	ACT ABATE	07	Violation Inspection - PS	10/10/2018
Original Complaint: High grass/weeds						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189837	09/21/18	07203026000	<b>3516 GOLF ST</b>	ACT ABATE	07	Violation Inspection - PS	10/10/2018
Original Complaint: High grass and weeds.						<u>Source: EMAIL</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190003	09/25/18	05108018300	<b>201 E WEBSTER ST</b>	ACT ABATE	07	Violation Inspection - PS	10/25/2018
Original Complaint: USE NOT PERMITTED						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190100	09/26/18	07207012700	<b>2310 RIVERSIDE DR</b>	PENDING	07	Initial Violation Inspection - PS	09/27/2018
Original Complaint: Type: Property Violations - Tall Grass and Weeds						<u>Source: HUB</u>	

Description:  
Grass over height limit; homeowner negligent.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190134	09/26/18	05112007800	<b>326 DUE WEST AVE E</b>	ACT ABATE	07	Violation Inspection - PS	10/18/2018
Original Complaint: Inoperable vehicles; junk, trash, and debris						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190142	09/26/18	07216009600	<b>1605 PEERMAN DR</b>	PENDING	07	Initial Violation Inspection - PS	09/27/2018
Original Complaint: Dumping sewage in the backyard; strong odor coming from home						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190165	09/27/18	05112008000	<b>300 BERKLEY DR</b>	ACT ABATE	07	Violation Inspection - PS	10/18/2018
Original Complaint: junk trash and water run off						<u>Source: PHONE</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190232	09/28/18	05209007600	<b>408 GRAPEVINE AVE</b>	ACT ABATE	07	Violation Inspection - PS	10/19/2018
Original Complaint: IMV, POG						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190234	09/28/18	05209007500	<b>404 GRAPEVINE AVE</b>	ACT ABATE	07	Violation Inspection - PS	10/19/2018
Original Complaint: pog, imv						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188551	09/04/18	05105000200	<b>721 DUE WEST AVE N</b>	ACT ABATE	08	Violation Inspection - PS	10/10/2018
Original Complaint: apt A210 - Tanasha - 615-582-6924 - leak in ceiling in bathroom around light fixture						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188552	09/04/18	06016029900	<b>715 JONES PARK CT</b>	ACT ABATE	08	Violation Inspection - PS	10/05/2018
Original Complaint: junk trash debris; inoperable vehicle in back yard						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188725	09/05/18	05102003400	<b>1002 S GRAYCROFT AVE</b>	ACT ABATE	08	Violation Inspection - PS	10/08/2018
Original Complaint: inoperable vehicle on property						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188746	09/06/18	06110015400	<b>902 VIRGINIA AVE</b>	ACT ABATE	08	Violation Inspection - PS	10/10/2018
Original Complaint: High grass						<u>Source: Codes Online</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188747	09/06/18	06110015000	<b>799 MATTHEWS AVE</b>	ACT ABATE	08	Violation Inspection - PS	10/10/2018
Original Complaint: High grass						<u>Source: Codes Online</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188748	09/06/18	07202008800	<b>3712 BURRUS ST</b>	ACT ABATE	08	Violation Inspection - PS	10/15/2018
Original Complaint: Junk trash and debris.						<u>Source: Codes Online</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188794	09/06/18	06107018800	<b>1023 MAPLEWOOD PL</b>	ACT ABATE	08	Violation Inspection - PS	10/01/2018
Original Complaint: Junk, trash, and debris						<u>Source:</u> HUB	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188796	09/06/18	06016032800	<b>2720 BULLOCK AVE</b>	ACT ABATE	08	Warrant Check - PS	11/26/2018
Original Complaint: high grass and weeds						<u>Source:</u> INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188844	09/07/18	04305000600	<b>200 NESBITT LN</b>	ACT ABATE	08	Violation Inspection - PS	10/15/2018
Original Complaint: lot 12 - Robert Ferguson - 615-596-3198 - plumbing problems; floors falling in						<u>Source:</u> PHONE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188846	09/07/18	06103014400	<b>4803 GALLATIN PIKE</b>	PENDING	08	Initial Violation Inspection - PS	09/08/2018
Original Complaint: Big sign that says truck for sale on property.						<u>Source:</u> HUB	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188858	09/07/18	06111004500	<b>914 VIRGINIA AVE</b>	ACT ABATE	08	Violation Inspection - PS	09/26/2018
Original Complaint: High grass & weeds						<u>Source:</u> PHONE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188859	09/07/18	06110014600	<b>807 MATTHEWS AVE</b>	ACT ABATE	08	Violation Inspection - PS	09/26/2018
Original Complaint: High grass & weeds						<u>Source:</u> PHONE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188882	09/10/18	06016003700	<b>2709 ALHAMBRA CIR</b>	ACT ABATE	08	Violation Inspection - PS	10/12/2018
Original Complaint: Junk, trash & debris; parking in the grass						<u>Source:</u> PHONE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188897	09/10/18	06000005100	<b>206 BEN ALLEN RD</b>	ACT ABATE	08	Violation Inspection - PS	10/16/2018
Original Complaint:						<u>Source:</u> HUB	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188916	09/10/18	06008004700	<b>3043 HILLSIDE RD</b>	ACT ABATE	08	Warrant Check - PS	11/12/2018
Original Complaint: Type: Property Violations - Junk and Debris						<u>Source: HUB</u>	

Description:  
Junk trash and debris

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188917	09/10/18	06008004700	<b>3043 HILLSIDE RD</b>	ACT ABATE	08	Warrant Check - PS	11/12/2018
Original Complaint: Type: Property Violations - Tall Grass and Weeds						<u>Source: HUB</u>	

Description:  
High grass/weeds

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188965	09/10/18	04208000400	<b>206 NESBITT LN</b>	ACT ABATE	08	Warrant Check - PS	11/12/2018
Original Complaint: high grass and weeds						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188966	09/10/18	04208000400	<b>206 NESBITT LN</b>	ACT ABATE	08	Warrant Check - PS	11/12/2018
Original Complaint: premise id						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189023	09/11/18	06016002900	<b>2707 BRUNSWICK DR</b>	ACT ABATE	08	Violation Inspection - PS	10/11/2018
Original Complaint: inoperable vehicles, parking on grass						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189114	09/12/18	06016032500	<b>2732 BULLOCK AVE</b>	ACT ABATE	08	Violation Inspection - PS	10/04/2018
Original Complaint: High grass & weeds						<u>Source: PHONE</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189172	09/13/18	06016011100	<b>2716 JONES AVE</b>	ACT ABATE	08	Violation Inspection - PS	10/04/2018
Original Complaint: Type: Property Violations - Tall Grass and Weeds						<u>Source: HUB</u>	

Description:  
tall grass and weeds behind the residence; cust says there are snakes

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189182	09/13/18	06114009900	<b>3829 BURRUS ST</b>	PENDING	08	Initial Violation Inspection - PS	09/14/2018
Original Complaint: Type: Property Violations - Fence Complaints						<u>Source: HUB</u>	

Description:  
Homeowner has concreted the entire front yard- did not see a permit either. Concrete was just poured.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189209	09/13/18	06008003000	<b>3036 HILLSIDE RD</b>	ACT ABATE	08	Violation Inspection - PS	10/04/2018
Original Complaint: high grass and weeds						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189270	09/14/18	05111006800	<b>1254 GALLATIN PIKE</b>	ACT ABATE	08	Violation Inspection - PS	10/15/2018
Original Complaint: Type: Property Violations - Illegal Sign on Private Property						<u>Source: HUB</u>	

Description:  
Put sign up for car lot without permit.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189302	09/14/18	06100000500	<b>0 ARROWHEAD DR</b>	ACT ABATE	08	Violation Inspection - PS	10/05/2018
Original Complaint: dumping junk trash and debris on property						<u>Source: Other Metro Agency</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189312	09/14/18	07202006300	<b>922 HOME RD</b>	PENDING	08	Initial Violation Inspection - PS	09/15/2018

Original Complaint: Type: Property Violations - Tall Grass and Weeds  
Source: HUB

Description:  
 Waist high weeds

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189331	09/14/18	05106001600	<b>909 FAIROAKS DR</b>	ACT ABATE	08	Violation Inspection - PS	10/02/2018

Original Complaint: Type: Property Violations - Tall Grass and Weeds  
Source: HUB

Description:  
 Grass and brush growing out over sidewalk. This house is a mess. As walkers and dog walkers this place has become a hazard. I do see that they are working on gutters and rotten roof but have let the whole place grow up. This only hurts the value of our homes. We as neighbors appreciate you working on this address and hopefully can get them to clean up.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189339	09/14/18	04204007800	<b>516 AMQUIWOOD CT</b>	ACT ABATE	08	Violation Inspection - PS	10/12/2018

Original Complaint: junk trash and debris, inoperable vehicle  
Source: INSPECTOR REPORTED

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189343	09/14/18	05004001300	<b>1036 DUE WEST AVE N</b>	ACT ABATE	08	Warrant Check - PS	11/26/2018

Original Complaint: high grass and weeds  
Source: INSPECTOR REPORTED

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189379	09/17/18	04210002000	<b>811 OLD HICKORY BLVD</b>	ACT ABATE	08	Violation Inspection - PS	10/08/2018

Original Complaint: Type: Property Violations - Dilapidated Structures  
Source: HUB

Description:  
 This house is increasingly in disrepair with overgrown fences and trash in easement.

Additional Comments:

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189491	09/17/18	07104030300	<b>2517 SLAYDON DR</b>	ACT VEHROW	08	Admin Staff Review - PS	10/03/2018
Original Complaint: inoperable vehicle- roadway						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189543	09/18/18	04204005700	<b>115 E CAMPBELL RD</b>	ACT ABATE	08	Violation Inspection - PS	10/04/2018
Original Complaint: Type: Property Violations - Tall Grass and Weeds						<u>Source: HUB</u>	

Description:  
grass is appx 10ft tall which is hiding trash and is drawing rodents.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189596	09/18/18	06105000800	<b>515 MAPLEWOOD LN</b>	PENDING	08	Env Court 1st Setting - PS	11/07/2018
Original Complaint: host- no strp permit						<u>Source: EMAIL</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189610	09/18/18	07104008000	<b>2607 JONES AVE</b>	ACT ABATE	08	Violation Inspection - PS	10/04/2018
Original Complaint: tall grass						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189652	09/19/18	04216014200	<b>616 GIBSON DR</b>	ACT ABATE	08	Violation Inspection - PS	10/05/2018
Original Complaint: Type: Property Violations - Residential Complaint						<u>Source: HUB</u>	

Description:  
Cars in yard, grass over 1 foot high, trees fallen and uncut. The yard stays in a continual mess an i  
an eyesore to the neighbors. Been going on quite some time. The home is in dis repair.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189706	09/19/18	07104008000	<b>2607 JONES AVE</b>	ACT ABATE	08	Violation Inspection - PS	10/04/2018
Original Complaint: parking on grass						<u>Source: INSPECTOR REPORTED</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189718	09/19/18	04204005700	<b>115 E CAMPBELL RD</b>	ACT ABATE	08	Violation Inspection - PS	10/19/2018
Original Complaint: inoperable vehicle, parking on grass and junk trash and debris						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189807	09/21/18	05104005400	<b>911 GIBSON DR</b>	ACT ABATE	08	Violation Inspection - PS	10/19/2018
Original Complaint: Type: Property Violations - Tree Concerns						<u>Source: HUB</u>	

Description:

Overgrown trees and yard appearance is disgusting. These people must go out of there way to be i tackiest place in the city. PLEASE FORCE THEM TO CLEAN IT UP!!

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189846	09/21/18	06106005400	<b>612 MAPLEWOOD LN</b>	PENDING	08	Initial Violation Inspection - PS	09/22/2018
Original Complaint: Type: Property Violations - Short Term Rental Complaint						<u>Source: HUB</u>	

Description:

Operating a Short Term Rental without permit. Not allowed by base zoning. Detached structure bu in 2015 (Permit CARN 201546914: parcel is zoned rs15 and contains 1.99 acres... not to be used f living or commercial purposes.). Listed on AirBnB: <https://www.airbnb.com/rooms/8098262?location=Nashville%2C%20TN%2C%20United%20States&adults=1&children=0&infants=0&guests&s=hd3vfEDt>

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189903	09/24/18	06012006900	<b>215 HART LN</b>	ACT ABATE	08	Violation Inspection - PS	10/09/2018
Original Complaint: high grass and weeds						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189904	09/24/18	04203005400	<b>912 N GRAYCROFT AVE</b>	ACT ABATE	08	Violation Inspection - PS	10/09/2018
Original Complaint: high grass and weeds						<u>Source: INSPECTOR REPORTED</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189917	09/24/18	07202001100	<b>1006 IVERSON AVE</b>	PENDING	08	Env Court 1st Setting - PS	11/14/2018
Original Complaint: operating a strp without a permit						<u>Source:</u> EMAIL	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189927	09/24/18	05111006800	<b>1256 GALLATIN PIKE S</b>	ACT ABATE	08	Violation Inspection - PS	10/15/2018
Original Complaint: expired bldg. permit						<u>Source:</u> INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190011	09/25/18	06111030200	<b>1006 CURDWOOD BLVD</b>	PENDING	08	Initial Violation Inspection - PS	09/26/2018
Original Complaint: Needs LL registration						<u>Source:</u> PHONE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190056	09/25/18	07104024800	<b>2411 OAKWOOD AVE</b>	ACT ABATE	08	Violation Inspection - PS	10/15/2018
Original Complaint: high grass and weeds						<u>Source:</u> INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190057	09/25/18	07104024700	<b>2503 ALLENWOOD DR</b>	ACT ABATE	08	Violation Inspection - PS	10/15/2018
Original Complaint: high grass and weeds						<u>Source:</u> INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190124	09/26/18	05102001000	<b>1018 CHADWELL DR</b>	ACT ABATE	08	Violation Inspection - PS	10/11/2018
Original Complaint: high grass and weeds						<u>Source:</u> INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190161	09/27/18	06101002900	<b>603 LEMONT DR</b>	ACT VEHROW	08	Violation Inspection CAR - PS	10/10/2018
Original Complaint: Type: Public Safety - Abandoned Vehicles						<u>Source:</u> HUB	

Description:  
Box truck parked on a thoroughfare since 9/23/18

Additional Comments:

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190236	09/28/18	04209009100	<b>901 WESTCHESTER DR</b>	PENDING	08	Initial Violation Inspection - PS	09/29/2018
Original Complaint: Aaron Bradberry 731-499-1298, Water leaks, Holes in ceiling, electrical issues						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188566	09/04/18	05206001300	<b>926 IDLEWILD DR</b>	ACT ABATE	09	Violation Inspection - PS	10/05/2018
Original Complaint: High grass/weeds						<u>Source: Codes Online</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188642	09/05/18	04306001400	<b>903 SNOW AVE</b>	ACT ABATE	09	Violation Inspection - PS	10/01/2018
Original Complaint: HGW						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188678	09/05/18	04314015300	<b>709 YOWELL AVE</b>	PENDING	09	Pre-Court Inspection - PS	10/23/2018
Original Complaint: WARRANT						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188766	09/06/18	05201011700	<b>233 NEELYS BEND RD</b>	ACT ABATE	09	Violation Inspection - PS	10/16/2018
Original Complaint: remodeling without permits; dumpster needs emptied						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188773	09/06/18	05202015300	<b>709 BLACKSTONE AVE</b>	ACT ABATE	09	Violation Inspection - PS	10/05/2018
Original Complaint: Junk trash and debris						<u>Source: Codes Online</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188812	09/06/18	04313036000	<b>232 ELM ST</b>	ACT ABATE	09	Violation Inspection - PS	10/18/2018
Original Complaint: Junk trash and debris in back yard						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188884	09/10/18	05208013100	<b>1173 SIOUX TER</b>	ACT ABATE	09	Violation Inspection - PS	10/05/2018
Original Complaint: HIGH GRASS WEEDS						<u>Source: PHONE</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188894	09/10/18	04311003200	<b>223 MCARTHUR DR</b>	ACT ABATE	09	Violation Inspection - PS	10/15/2018
Original Complaint: INOPERABLE/UNREGISTERED MOTOR VEHICLE,JUNK TRASH AND DEBRIS/PARKING ON GRASS						<u>Source:</u> INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188955	09/10/18	05206006100	<b>701 FLORENCE CIR</b>	ACT ABATE	09	Violation Inspection - PS	10/05/2018
Original Complaint: tall grass (across from 700 Florence)						<u>Source:</u> PHONE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189066	09/12/18	04301017500	<b>1317 PIERCE RD</b>	ACT ABATE	09	Violation Inspection - PS	10/11/2018
Original Complaint: LL. REGISTRATION						<u>Source:</u> INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189076	09/12/18	04316006200	<b>113 QUEEN ANNE DR</b>	ACT ABATE	09	Violation Inspection - PS	10/11/2018
Original Complaint: LL. REGISTRATION						<u>Source:</u> INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189385	09/17/18	04305013300	<b>502 ANDERSON LN</b>	ACT ABATE	09	Violation Inspection - PS	10/19/2018
Original Complaint: Junk, trash, and debris						<u>Source:</u> PHONE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189478	09/17/18	04313042100	<b>335 FOREST PARK RD</b>	ACT ABATE	09	Violation Inspection - PS	10/25/2018
Original Complaint: Apt 61-Pipe busted in bathroom sink; floors caving in contact Angie Bennett 615-586-9175						<u>Source:</u> PHONE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189726	09/19/18	05202028000	<b>571 NEELYS BEND RD</b>	ACT ABATE	09	Violation Inspection - PS	10/16/2018
Original Complaint:						<u>Source:</u> HUB	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189736	09/19/18	04306001400	<b>903 SNOW AVE</b>	ACT ABATE	09	Violation Inspection - PS	10/19/2018
Original Complaint: LANDLORD REG.						<u>Source:</u> INSPECTOR REPORTED	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189763	09/20/18	05208010000	<b>1205 SHAWNEE RD</b>	ACT ABATE	09	Violation Inspection - PS	10/08/2018
Original Complaint: High grass/weeds						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189786	09/20/18	053090B21900CO	<b>1140 PAWNEE TRL</b>	ACT ABATE	09	Violation Inspection - PS	11/01/2018
Original Complaint: LL. REGISTRATION						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189789	09/20/18	05203006900	<b>314 LARKIN SPRINGS RD</b>	ACT ABATE	09	Violation Inspection - PS	10/08/2018
Original Complaint: Type: Property Violations - Junk and Debris						<u>Source: HUB</u>	

Description:

Owner of property has not cut grass this summer. Therefore the grass is extremely high

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189790	09/20/18	04315029100	<b>224 LARKIN SPRINGS RD</b>	ACT ABATE	09	Violation Inspection - PS	10/15/2018
Original Complaint: Type: Property Violations - Residential Complaint						<u>Source: HUB</u>	

Description:

Resident has an old car that's been sitting for awhile and they, along with their many visitors park crossing the side walk, therefore causing walkers and possible those handicapped using electronic wheelchairs to have to enter the street to get by.

FYI 224 thru 216 Larkin springs will always have this problem. Property was built with extremely limited parking and no garages or turn around possibilities.

Sincerely,

Trying to keep property value up :)

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189795	09/20/18	04316006700	<b>123 QUEEN ANNE DR</b>	ACT ABATE	09	Violation Inspection - PS	10/15/2018
Original Complaint: JTD, POG, COMM. VEHICLE, BLDG. PERMIT						<u>Source: INSPECTOR REPORTED</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189809	09/21/18	04309017100	<b>257 DUPONT AVE</b>	ACT ABATE	09	Violation Inspection - PS	10/15/2018
Original Complaint: Type: Property Violations - Tall Grass and Weeds						<u>Source:</u> HUB	

Description:  
Grass has not been mowed in 4 weeks at least

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189896	09/24/18	04306008800	<b>323 NIX DR</b>	ACT ABATE	09	Violation Inspection - PS	10/16/2018
Original Complaint: Building/constructing without a permit; junk, trash, and debris						<u>Source:</u> PHONE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189921	09/24/18	04310011700	<b>196 NIX DR</b>	ACT ABATE	09	Violation Inspection - PS	10/09/2018
Original Complaint: tall grass						<u>Source:</u> PHONE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190132	09/26/18	04315021500	<b>1120 BUBBLING WELL RD</b>	ACT ABATE	09	Violation Inspection - PS	10/26/2018
Original Complaint: JTD, IMV/YARD,						<u>Source:</u> INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190133	09/26/18	04315021600	<b>1124 BUBBLING WELL RD</b>	ACT ABATE	09	Violation Inspection - PS	10/26/2018
Original Complaint: JTD, IMV/YARD, PREM. ID.						<u>Source:</u> INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190135	09/26/18	04313013500	<b>510 OLD HICKORY BLVD</b>	PENDING	09	Initial Violation Inspection - PS	09/27/2018
Original Complaint: Apt 501-Apartment has flooded; water damage- Jennifer 251-391-9332						<u>Source:</u> PHONE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190237	09/28/18	04301014600	<b>108 A SHANNON AVE</b>	ACT ABATE	09	Violation Inspection - PS	10/15/2018
Original Complaint: high grass and weeds						<u>Source:</u> INSPECTOR REPORTED	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190241	09/28/18	04301014600	<b>108 A SHANNON AVE</b>	ACT ABATE	09	Violation Inspection - PS	10/26/2018
Original Complaint: JUNK TRASH AND DEBRIS						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190267	09/28/18	052080A21700CO	<b>1100 SHAWNEE TRCE</b>	ACT ABATE	09	Violation Inspection - PS	10/22/2018
Original Complaint: Illegal dumping of junk, trash, and debris						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188530	09/04/18	03311004900	<b>821 HAMBLEN DR</b>	ACT ABATE	10	Violation Inspection - PS	10/05/2018
Original Complaint: Parking on grass, Built 2 barns without permits. Inoperable vehicles.						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188772	09/06/18	03402007400	<b>1800 GALLATIN PIKE N</b>	ACT ABATE	10	Violation Inspection - PS	10/15/2018
Original Complaint: HOW TAKEN: PHONE Junk trash and debris on Toys R Us and El Chico parking lots. Graffiti on Toys R Us building. Loading dock trash shute is not secure. People are going in and out of Toys R Us.						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188938	09/10/18	03413021000	<b>220 AURORA AVE</b>	ACT ABATE	10	Violation Inspection - PS	10/19/2018
Original Complaint: Type: Property Violations - Junk and Debris						<u>Source: HUB</u>	

Description:  
Parking on grass, Junk trash and debris

Additional Comments:

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188950	09/10/18	03311002000	<b>303 FAIRBANKS RD</b>	ACT ABATE	10	Violation Inspection - PS	10/12/2018

Original Complaint: Type: Property Violations - Junk and Debris Source: HUB

Description:

The people there has junk in the yard, they have a camper trailer way in the back they are tearing apart and burning and the fumes are toxic. Also a car is hidden in the back, the house is falling apart and the folks doing all this does not even live at this location. Lst request closed and not resolved.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189034	09/11/18	03406003500	<b>741 MYATT DR</b>	ACT ABATE	10	Violation Inspection - PS	10/09/2018

Original Complaint: tall grass Source: PHONE

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189429	09/17/18	03311003800	<b>721 HAMBLÉN DR</b>	ACT ABATE	10	Violation Inspection - PS	10/03/2018

Original Complaint: HOW TAKEN: PHONE Source: PHONE  
Vehicle parked on the grass (school bus)

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189532	09/17/18	03409002000	<b>1513 B MONTICELLO AVE</b>	TRANSFERRD	10		

Original Complaint: Tenants working on cars; multiple inoperable vehicles Source: PHONE

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189818	09/21/18	03413032500	<b>516 MACFIE CT</b>	ACT ABATE	10	Violation Inspection - PS	10/09/2018

Original Complaint: Type: Property Violations - Cars Parked On Lawn Source: HUB

Description:

The residents have 3 vehicles and one of them is always parked in the grass to the left of their driveway on the grass. Part of the grass they park in is on the other residents property.

Additional Comments:

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189892	09/24/18	03413022400	<b>233 EDGEMEADE DR</b>	ACT ABATE	10	Violation Inspection - PS	10/16/2018
Original Complaint: Type: Property Violations - Junk and Debris						<u>Source:</u> HUB	

Description:  
People have moved out and trash including a couch has been sitting by the road for 2 weeks.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190156	09/26/18	02613004200	<b>808 WREN RD</b>	TRANSFERRD	10		
Original Complaint: Amy Mangrum 615-902-5582. Plumbing issues.						<u>Source:</u> PHONE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188621	09/05/18	05308003400	<b>2203 ELLIOTT DR</b>	ACT ABATE	11	Warrant Check - PS	12/03/2018
Original Complaint: Vacant house, Junk trash and debris. Addition that may have not been permitted.						<u>Source:</u> Codes Online	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188680	09/05/18	04411001800	<b>112 ORCHARD DR</b>	ACT ABATE	11	Warrant Check - PS	12/03/2018
Original Complaint: HIGH GRASS						<u>Source:</u> INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188708	09/05/18	05303028200	<b>1503 BRYAN ST</b>	ACT ABATE	11	Violation Inspection - PS	09/28/2018
Original Complaint: Junk, trash, and debris						<u>Source:</u> HUB	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188709	09/05/18	05303028200	<b>1503 BRYAN ST</b>	ACT ABATE	11	Violation Inspection - PS	09/28/2018
Original Complaint: High grass/weeds						<u>Source:</u> HUB	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188734	09/05/18	07510005700	<b>8239 LUREE LN</b>	ACT ABATE	11	Violation Inspection - PS	10/29/2018
Original Complaint: Open storage of junk and debris (repeat violation), inoperable vehicles (repeat violation, parking on the grass (repeat violation), illegal use - motor homes being lived in. May be other violations.						<u>Source:</u> EMAIL	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188780	09/06/18	05303001900	<b>1210 ELLISTON ST</b>	ACT ABATE	11	Warrant Check - PS <u>Source: PHONE</u>	12/03/2018

Original Complaint: High grass/weeds in the backyard

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188819	09/06/18	04405018100	<b>100 BRIDGEWAY AVE</b>	ACT ABATE	11	Violation Inspection - PS <u>Source: PHONE</u>	09/27/2018

Original Complaint: jtd inv use

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188906	09/10/18	04304005000	<b>147 SCENIC VIEW RD</b>	ACT ABATE	11	Violation Inspection - PS <u>Source: PHONE</u>	10/15/2018

Original Complaint: HOW TAKEN: PHONE  
Junk, trash & debris; trash bags beside the house; mattress in the back yard

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188953	09/10/18	05308003600	<b>2204 ELLIOTT DR</b>	ACT ABATE	11	Violation Inspection - PS <u>Source: INSPECTOR REPORTED</u>	10/01/2018

Original Complaint: OPEN STORAGE

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188968	09/10/18	05303030200	<b>1511 ELLISTON ST</b>	ACT ABATE	11	Violation Inspection - PS <u>Source: PHONE</u>	10/04/2018

Original Complaint: Junk, trash, and debris in the front and back yard

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188969	09/10/18	05303030200	<b>1511 ELLISTON ST</b>	ACT ABATE	11	Violation Inspection - PS <u>Source: PHONE</u>	09/27/2018

Original Complaint: High grass/weeds

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188984	09/11/18	06509008300	<b>4872 WHITTIER DR</b>	ACT ABATE	11	Violation Inspection - PS <u>Source: PHONE</u>	10/02/2018

Original Complaint: junk trash and debris

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189024	09/11/18	06413004400	<b>4310 WOODS ST</b>	ACT ABATE	11	Violation Inspection - PS <u>Source: PHONE</u>	10/02/2018

Original Complaint: High grass & weeds

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189025	09/11/18	06413004600	<b>4318 WOODS ST</b>	ACT ABATE	11	Violation Inspection - PS	10/02/2018
Original Complaint: High grass & weeds - vacant lot						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189125	09/13/18	05413001100	<b>114 ANTHONY ST</b>	ACT ABATE	11	Violation Inspection - PS	10/18/2018
Original Complaint: Dilapidated house; junk, trash & debris - the smaller house						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189252	09/13/18	06409009500	<b>109 COMMERCE ST</b>	ACT ABATE	11	Violation Inspection - PS	10/18/2018
Original Complaint: Type: Property Violations - Junk and Debris						<u>Source: HUB</u>	

Description:

There are two broken down trucks, trash/ debris and very high grass in the backyard.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189387	09/17/18	04405021700	<b>117 BRIDGEWAY AVE</b>	ACT HSGDEM	11	People Update - PS	09/27/2018
Original Complaint: DEMO						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189404	09/17/18	07500003900	<b>454 HIGHLAND VIEW DR</b>	ACT ABATE	11	Violation Inspection - PS	10/22/2018
Original Complaint: Vehicles parked in the yard; inoperable vehicles in the backyard						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189405	09/17/18	07500003900	<b>454 HIGHLAND VIEW DR</b>	ACT ABATE	11	Violation Inspection - PS	10/08/2018
Original Complaint: High grass/weeds						<u>Source: PHONE</u>	

**Master RFS Detail Report**

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189455	09/17/18	08600001900	<b>304 OLD LEBANON DIRT RD</b>	PENDING	11	Initial Violation Inspection - PS	09/18/2018
Original Complaint: Type: Property Violations - Dilapidated Structures						<u>Source:</u> HUB	

Description:  
Red barn at the back of the property has a collapsing roof and is falling apart.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189551	09/18/18	044070A00700CO	<b>14 ROEHRIG CT</b>	ACT ABATE	11	Violation Inspection - PS	10/29/2018
Original Complaint: Type: Property Violations - Tall Grass and Weeds						<u>Source:</u> HUB	

Description:  
Grass is higher than 12 inches.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189674	09/19/18	05308009300	<b>303 28TH ST</b>	ACT ABATE	11	Violation Inspection - PS	10/19/2018
Original Complaint: No running water; strong odor coming from home						<u>Source:</u> PHONE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189676	09/19/18	05308009300	<b>303 28TH ST</b>	ACT ABATE	11	Violation Inspection - PS	10/05/2018
Original Complaint: High grass/weeds						<u>Source:</u> PHONE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189806	09/21/18	05312023700	<b>33 LAKESHORE CT</b>	ACT ABATE	11	Violation Inspection - PS	10/15/2018
Original Complaint: Type: Property Violations - Residential Complaint						<u>Source:</u> HUB	

Description:  
Cars that do not run and have no tags parked near road

Additional Comments:

**Master RFS Detail Report**

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189810	09/21/18	05316014300	<b>309 PITTS AVE</b>	ACT ABATE	11	Violation Inspection - PS	10/22/2018
Original Complaint: Type: Property Violations - Cars Parked On Lawn						<u>Source:</u> HUB	

Description:

This property has multiple (3 or more) vehicles parked and stored on the grass that gets worked on at various times. Most vehicles have grass growing up around them because they've been there so long. This property has long been an eyesore to the neighborhood with autos parked all over the year at different times, appliances stored outside, unkempt yard and recently has a dog kept (kennel or restraint?) that barks constantly and sounds distressed. There is a line of "privacy" bushes that line the front of the property facing Pitts. They are often untrimmed and overgrown. Is their proximity to the street a violation? Yard is often neglected.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189813	09/21/18	05307000600	<b>1800 OVERTON ST</b>	ACT ABATE	11	Violation Inspection - PS	10/15/2018
Original Complaint: Type: Property Violations - Cars Parked On Lawn						<u>Source:</u> HUB	

Description:

motor vehicle parked behind the house in the yard after sitting on the street in front of the house for months.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189841	09/21/18	04411000500	<b>1200 DONELSON AVE</b>	ACT ABATE	11	Violation Inspection - PS	10/05/2018
Original Complaint: OPEN STORAGE						<u>Source:</u> EMAIL	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189996	09/25/18	06412005500	<b>4709 KALAMATH DR</b>	ACT ABATE	11	Violation Inspection - PS	10/25/2018
Original Complaint: USE NOT PERMITTED - LIVING IN CAMPER						<u>Source:</u> INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189999	09/25/18	05312012100	<b>101 32ND ST</b>	ACT ABATE	11	Violation Inspection - PS	10/12/2018
Original Complaint: JTD HG&W						<u>Source:</u> INSPECTOR REPORTED	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190044	09/25/18	05303009700	<b>1406 BERRY ST</b>	ACT ABATE	11	Violation Inspection - PS	10/12/2018
Original Complaint: trash in trash bags around yard, in front yard and some on front porch, and side of the house						<u>Source</u> : PHONE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190068	09/25/18	05312001200	<b>2905 LAWRENCE CT</b>	ACT ABATE	11	Violation Inspection - PS	10/08/2018
Original Complaint: HIGH GRASS						<u>Source</u> : EMAIL	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190076	09/25/18	05303002000	<b>1212 ELLISTON ST</b>	ACT ABATE	11	Violation Inspection - PS	10/15/2018
Original Complaint: OPEN STORAGE						<u>Source</u> : INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190155	09/26/18	05303016700	<b>1412 HADLEY AVE</b>	ACT ABATE	11	Violation Inspection - PS	10/12/2018
Original Complaint: Type: Property Violations - Cars Parked On Lawn						<u>Source</u> : HUB	

Description:

The neighbors in the duplex (front and back entrances) at 1412 Hadley Avenue do have a problem with parking their cars on the lawn. This happens routinely, both on the side, the front and in the back yard. However, I am contacting you regarding untagged junk cars recently brought onto the property in the driveway area. I noticed a black Toyota MR2 or similar showed up a few days ago parked sideways in front of their garage. Between rain spells on Monday, I noticed two people who I did not recognize working on this black car. Last night, a truck with a trailer showed up about 5 pm with a green untagged Toyota MR2. It took them an hour and one-half just to get this piece of junk off the trailer onto the lawn in the vicinity of the driveway. Once again, I did not see either of the neighbors living there that I know. Regardless, our neighborhood is fixing to become a junk yard or mechanic's paradise. Eventually, I expect it will become entirely unsightly. Let's not wait that long. Thanks. (The green car can be clearly seen in the photo sitting on the grass. The black car is front of the garage door, mostly obscured in the photo.)

Additional Comments:

**Master RFS Detail Report**

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190246	09/28/18	06513000900	<b>4800 LEBANON PIKE</b>	PENDING	11	Initial Violation Inspection - PS	09/29/2018

Original Complaint: HOW TAKEN: HUB  
Type: Property Violations - Junk and Debris

Source: HUB

Description:  
Furniture has been dumped on the left side of the building (if you are looking at it from the front).

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188504	09/04/18	07511004200	<b>604 BATON ROUGE CT</b>	ACT ABATE	12	Violation Inspection - PS	10/29/2018

Original Complaint: Parking in grass

Source: Codes Online

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188571	09/04/18	098130A03600CO	<b>4800 CAPE HOPE PASS</b>	ACT ABATE	12	Violation Inspection - PS	10/29/2018

Original Complaint: Parking in grass

Source: Codes Online

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188605	09/04/18	086110B02700CO	<b>426 RAINTREE PL</b>	PENDING	12	Initial Violation Inspection - PS	09/05/2018

Original Complaint: Damaged gutters and roof

Source: Codes Online

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188668	09/05/18	09708010200	<b>4124 HELENA BAY CT</b>	ACT ABATE	12	Violation Inspection - PS	10/12/2018

Original Complaint: New Construction of a SFD - grass is high.

Source: SPE

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188927	09/10/18	08713005100	<b>4532 BROOKE VALLEY DR</b>	ACT ABATE	12	Violation Inspection - PS	10/29/2018

Original Complaint: Possibly running a car shop/car sales from residence

Source: PHONE

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189001	09/11/18	07515003600	<b>823 NETHERLANDS DR</b>	PENDING	12	Initial Violation Inspection - PS	09/12/2018

Original Complaint: parking on grass, junk and trash

Source: PHONE

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189010	09/11/18	08700015900	<b>782 OLD LEBANON DIRT RD</b>	PENDING	12	Initial Violation Inspection - PS	09/12/2018
Original Complaint: parking camper trailers in front yard for sale						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189043	09/11/18	09700008700	<b>6001 OLD HICKORY BLVD</b>	ACT ABATE	12	Violation Inspection - PS	10/29/2018
Original Complaint: Type: Property Violations - Junk and Debris						<u>Source: HUB</u>	

Description:  
dumping on back of property by dumpsters

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189075	09/12/18	07507025000	<b>204 RACHELS CT</b>	PENDING	12	Initial Violation Inspection - PS	09/13/2018
Original Complaint: 1995 ford ranger truck maroon, abandoned						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189110	09/12/18	075110A00200CO	<b>4205 RACHEL DONELSON PASS</b>	PENDING	12	Initial Violation Inspection - PS	09/13/2018
Original Complaint: Type: Public Safety - Abandoned Vehicles						<u>Source: HUB</u>	

Description:  
A small black car has been abandoned for several days on Rachel Donelson Pass between my house at 4205 and my nearest neighbor at 4217. The vehicle already has a green sticker applied to the rear window, it has been there for days and the left rear passenger window has been left down even in the rain. Please consider removing this abandoned vehicle from our neighborhood.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189457	09/17/18	07504020700	<b>4755 TRENTON DR</b>	PENDING	12	Initial Violation Inspection - PS	09/18/2018
Original Complaint: Junk, trash & debris - Mattresses						<u>Source: PHONE</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189561	09/18/18	07512000500	<b>812 LUXEMBURG DR</b>	PENDING	12	Initial Violation Inspection - PS	09/19/2018
Original Complaint: Type: Property Violations - Cars Parked On Lawn						<u>Source: HUB</u>	

Description:  
Parking in front yard

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189563	09/18/18	07512000300	<b>825 LUXEMBURG DR</b>	ACT ABATE	12	Violation Inspection - PS	10/29/2018
Original Complaint: Type: Property Violations - Tall Grass and Weeds						<u>Source: HUB</u>	

Description:  
Tall grass

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189585	09/18/18	07504018100	<b>544 RALIEGH DR</b>	ACT ABATE	12	Violation Inspection - PS	09/28/2018
Original Complaint: HIGH GRASS AND WEEDS						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189598	09/18/18	075120A11400CO	<b>504 SCOTTS CREEK TRL</b>	ACT VEHROW	12	Violation Inspection CAR - PS	10/05/2018
Original Complaint: Abandoned vehicle (Maroon GMC Envoy License plate # V7780P)						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189681	09/19/18	07504014900	<b>520 ST PAUL DR</b>	PENDING	12	Initial Violation Inspection - PS	09/20/2018
Original Complaint: High grass and weeds.						<u>Source: EMAIL</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189682	09/19/18	07503003500	<b>4509 ANDREW JACKSON PKWY</b>	PENDING	12	Initial Violation Inspection - PS	09/20/2018
Original Complaint: High grass and weeds - this is a repeat violator.						<u>Source: EMAIL</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189683	09/19/18	07503003500	<b>4509 ANDREW JACKSON PKWY</b>	PENDING	12	Initial Violation Inspection - PS	09/20/2018
Original Complaint: Parking on the grass.						<u>Source: EMAIL</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189684	09/19/18	07508009500	<b>552 AUGUSTA DR</b>	PENDING	12	Initial Violation Inspection - PS	09/20/2018
Original Complaint: High grass and weeds.						<u>Source: EMAIL</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189734	09/19/18	08713001100	<b>4432 GINA BROOKE DR</b>	PENDING	12	Initial Violation Inspection - PS	09/20/2018
Original Complaint: Type: Property Violations - Dilapidated Structures						<u>Source: HUB</u>	

Description:

Dilapidated Tent Structure out front, trash, beer cans, etc throughout the front of the duplex. The m sit outside and drink most days throughout the day. They also illegally work on cars in the middle of the street and do not properly dispose of oil and car waste. The property is embarrassing, an eye sore, and quite frankly, creepy that the men sit all day on their porch drinking. This is a rental property and we are unaware if the landlord knows what's going on. We are afraid to take pictures because they will see us.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189796	09/21/18	09700008700	<b>6001 OLD HICKORY BLVD</b>	PENDING	12	Initial Violation Inspection - PS	09/22/2018
Original Complaint: Apt. 337; Ms. Azarrea Cole (615) 299-6852 Leakage from the roof of the bedroom						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189824	09/21/18	07504022900	<b>4782 TRENTON DR</b>	PENDING	12	Initial Violation Inspection - PS	09/22/2018
Original Complaint: High grass/weeds						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190028	09/25/18	075120A12200CO	<b>433 SCOTTS CREEK TRL</b>	ACT VEHROW	12	Violation Inspection CAR - PS	10/05/2018
Original Complaint: ABANDONED FOODTRUCK ON ROW						<u>Source: PHONE</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190083	09/26/18	09708001600	<b>4012 LAKE PKWY</b>	PENDING	12	Initial Violation Inspection - PS	09/27/2018

Original Complaint: Junk trash and debris at street. Source: PHONE

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190104	09/26/18	098090A09300CO	<b>405 BREEZE PT</b>	PENDING	12	Initial Violation Inspection - PS	09/27/2018

Original Complaint: Type: Property Violations - Cars Parked On Lawn Source: HUB

Description:  
 blk. utility trailer parked on Breezepoint with propane tanks and smoker attached. No lights or reflectors or cones. Hazard can not see at night. Also walkers have to walk out into the middle of th street to go around it.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190140	09/26/18	07511003500	<b>621 BATON ROUGE CT</b>	PENDING	12	Initial Violation Inspection - PS	09/27/2018

Original Complaint: Type: Property Violations - Cars Parked On Lawn Source: HUB

Description:  
 This is a daily occurrence

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190292	09/28/18	08600018800	<b>5610 OLD HICKORY BLVD</b>	PENDING	12	Initial Violation Inspection - PS	09/29/2018

Original Complaint: Type: Streets, Roads & Sidewalks - Overgrowth on right of way Source: HUB

Description:  
 cut metro property so bushes aren't growing onto his property across from building F CALL HIM TC MEET

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188608	09/04/18	10713010600	<b>1203 THOMPSON PL</b>	ACT ABATE	13	Violation Inspection - PS	10/04/2018

Original Complaint: High grass & weeds Source: PHONE

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188800	09/06/18	12013000200	<b>922 CURREY RD</b>	ACT ABATE	13	Violation Inspection - PS	10/04/2018
Original Complaint: IMV, JTD, POG						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188813	09/06/18	10812023500	<b>3261 E LAKE DR</b>	PENDING	13	Initial Violation Inspection - PS	09/07/2018
Original Complaint: Renting without permit						<u>Source: Codes Online</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188842	09/07/18	10709000100	<b>1001 HAROLD DR</b>	ACT ABATE	13	Violation Inspection - PS	10/08/2018
Original Complaint: constructed a play house without permit.						<u>Source: Codes Online</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188866	09/07/18	10714012800	<b>1016 KIPLING DR</b>	ACT ABATE	13	Violation Inspection - PS	10/05/2018
Original Complaint: jtd, acc.str. pro metal, pog						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188867	09/07/18	10714012700	<b>1018 KIPLING DR</b>	ACT ABATE	13	Violation Inspection - PS	10/05/2018
Original Complaint: jtd, acc. str. pro wood						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188919	09/10/18	10808025900	<b>3073 REELFOOT DR</b>	ACT ABATE	13	Violation Inspection - PS	09/28/2018
Original Complaint: Type: Property Violations - Junk and Debris						<u>Source: HUB</u>	

Description:  
cust says the resident left junk and debris in the backyard

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188943	09/10/18	10714009900	<b>1000 GOODBAR DR</b>	ACT ABATE	13	Violation Inspection - PS	10/09/2018
Original Complaint: Junk, trash, and debris in the dtich						<u>Source: PHONE</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188993	09/11/18	12013007500	<b>1120 TARA ANN CT</b>	ACT ABATE	13	Violation Inspection - PS	10/11/2018

Original Complaint: HOW TAKEN: HUB  
Type: Property Violations - Junk and Debris

Source: HUB

Description:

Junk, trash in driveway and lawn area. House fire almost a year ago. Parking in grass

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188995	09/11/18	12013008200	<b>1104 TARA ANN CT</b>	ACT ABATE	13	Violation Inspection - PS	10/11/2018

Original Complaint: Type: Property Violations - Cars Parked On Lawn

Source: HUB

Description:

Trucks parked in grass...or half on driveway and half in dirt where there used to be grass. Broken down, inoperable vehicle parked in driveway with no tags. Masonry mixer tow-able in front yard. Constant infractions at this house.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189017	09/11/18	12013006100	<b>1206 CURREY RD</b>	ACT ABATE	13	Violation Inspection - PS	10/11/2018

Original Complaint: Type: Property Violations - Junk and Debris

Source: HUB

Description:

Inoperable vehicle parked in gravel parking area. White vehicle. Looked like a Ford of some type.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189028	09/11/18	10713011300	<b>1001 GOODBAR DR</b>	ACT ABATE	13	Violation Inspection - PS	10/11/2018

Original Complaint: Junk, trash & debris on the side of house leading to Thompson Place

Source: PHONE

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189038	09/11/18	12002014100	<b>1329 MARS DR</b>	TRANSFERRD	13		

Original Complaint: jtd

Source: NEIGHBORHOOD GROUP

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189039	09/11/18	12001011600	<b>1235 SATURN DR</b>	ACT ABATE	13	Violation Inspection - PS	10/09/2018
Original Complaint: pog						<u>Source: NEIGHBORHOOD GROUP</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189040	09/11/18	12002006800	<b>1206 SATURN DR</b>	ACT ABATE	13	Violation Inspection - PS	10/09/2018
Original Complaint: jtd, pog						<u>Source: NEIGHBORHOOD GROUP</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189041	09/11/18	12002007100	<b>1200 SATURN DR</b>	ACT ABATE	13	Violation Inspection - PS	10/09/2018
Original Complaint: jtd, pog						<u>Source: NEIGHBORHOOD GROUP</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189084	09/12/18	12013007900	<b>1106 TARA ANN CT</b>	ACT ABATE	13	Violation Inspection - PS	10/11/2018
Original Complaint: jtd, pog						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189085	09/12/18	12013009000	<b>1108 TARA ANN CT</b>	ACT ABATE	13	Violation Inspection - PS	10/11/2018
Original Complaint: jtd						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189086	09/12/18	12013007800	<b>1110 TARA ANN CT</b>	ACT ABATE	13	Violation Inspection - PS	10/11/2018
Original Complaint: jtd						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189087	09/12/18	12013008400	<b>1119 TARA ANN CT</b>	ACT ABATE	13	Violation Inspection - PS	10/11/2018
Original Complaint: pog						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189088	09/12/18	12013006600	<b>3483 MCGAVOCK PIKE</b>	ACT ABATE	13	Violation Inspection - PS	10/11/2018
Original Complaint: imv						<u>Source: INSPECTOR REPORTED</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189089	09/12/18	12013006000	<b>1204 CURREY RD</b>	ACT ABATE	13	Violation Inspection - PS	10/11/2018
Original Complaint: jtd						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189136	09/13/18	10808020500	<b>3149 E LAKE DR</b>	ACT ABATE	13	Violation Inspection - PS	10/02/2018
Original Complaint: JTD, Appliances in yard						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189137	09/13/18	10808015800	<b>3146 E LAKE DR</b>	ACT ABATE	13	Violation Inspection - PS	10/02/2018
Original Complaint: POG, IMV						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189138	09/13/18	108040A05400CO	<b>2908 BLACKWOOD DR</b>	ACT ABATE	13	Violation Inspection - PS	10/02/2018
Original Complaint: Furniture, JTD in Yard						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189221	09/13/18	10714011900	<b>1003 KIPLING DR</b>	ACT ABATE	13	Violation Inspection - PS	10/11/2018
Original Complaint: hw, jtd, pog						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189222	09/13/18	10714013000	<b>1012 KIPLING DR</b>	ACT ABATE	13	Violation Inspection - PS	10/11/2018
Original Complaint: jtd, wood, pog						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189226	09/13/18	10714006900	<b>925 KIPLING DR</b>	ACT ABATE	13	Violation Inspection - PS	10/11/2018
Original Complaint: jtd, wood, pog						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189230	09/13/18	108080B01700CO	<b>1107 QUAIL CT W</b>	ACT ABATE	13	Violation Inspection - PS	10/15/2018
Original Complaint: Inoperable Blue Honda Civic on property.						<u>Source: PHONE</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189315	09/14/18	10816010300	<b>3109 PRIEST WOODS DR</b>	PENDING	13	Env Court 1st Setting - PS	11/07/2018
Original Complaint: host- no strp permit						<u>Source:</u> EMAIL	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189441	09/17/18	12002008500	<b>1320 VENUS DR</b>	ACT ABATE	13	Violation Inspection - PS	10/16/2018
Original Complaint: Vehicles parked on grass						<u>Source:</u> PHONE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189448	09/17/18	108040A04700CO	<b>920 CARLISLE CT S</b>	ACT ABATE	13	Violation Inspection - PS	09/28/2018
Original Complaint: Type: Property Violations - Cars Parked On Lawn						<u>Source:</u> HUB	

Description:

Green Toyota Camry has been parked in the front yard next to the driveway for over a week. Pleas inform homeowner of violation.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189500	09/17/18	10713001900	<b>1004 PATRICIA DR</b>	ACT ABATE	13	Violation Inspection - PS	10/15/2018
Original Complaint: JTD, IMV, PRO WOOD						<u>Source:</u> INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189529	09/17/18	10713015900	<b>0 PATRICIA DR</b>	ACT ABATE	13	Violation Inspection - PS	10/15/2018
Original Complaint: jtd						<u>Source:</u> INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189535	09/17/18	12010007900	<b>216 PINEWAY DR</b>	ACT ABATE	13	Violation Inspection - PS	10/16/2018
Original Complaint: Sewage is backed up in the restrooms						<u>Source:</u> PHONE	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189678	09/19/18	10901001400	<b>300 CONIFER PL</b>	ACT ABATE	13	Violation Inspection - PS	10/18/2018
Original Complaint: Type: Property Violations - Tall Grass and Weeds						<u>Source:</u> HUB	

Description:

Grass is not being mowed. Polk salad plants 5 ft. tall. Bushes 10 ft. tall. Its a eyesore to the neighborhood. The house is occupied. Its been going like this all summer.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189814	09/21/18	12100002400	<b>2560 PULLEY RD</b>	ACT ABATE	13	Violation Inspection - PS	10/12/2018
Original Complaint: High Grass						<u>Source:</u> PHONE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189886	09/24/18	12001014900	<b>1110 MURFREESBORO PIKE</b>	ACT ABATE	13	Violation Inspection - PS	10/23/2018
Original Complaint: High grass/weeds						<u>Source:</u> PHONE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189887	09/24/18	10713008500	<b>1210 THOMPSON PL</b>	ACT ABATE	13	Violation Inspection - PS	10/23/2018
Original Complaint: HOW TAKEN: PHONE High grass/weeds growing on the fence						<u>Source:</u> PHONE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189975	09/25/18	09616020400	<b>737 FITZPATRICK RD</b>	ACT ABATE	13	Violation Inspection - PS	10/15/2018
Original Complaint: Mattresses @ ROW						<u>Source:</u> INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190005	09/25/18	10714010100	<b>926 GOODBAR DR</b>	ACT ABATE	13	Violation Inspection - PS	10/24/2018
Original Complaint: Junk, trash, and debris						<u>Source:</u> PHONE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190032	09/25/18	12002002300	<b>1025 BRILEY PKWY</b>	ACT ABATE	13	Violation Inspection - PS	10/23/2018
Original Complaint: building permit required-shed, wood						<u>Source:</u> INSPECTOR REPORTED	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190041	09/25/18	10713013100	<b>1108 MURFREESBORO PIKE</b>	ACT ABATE	13	Violation Inspection - PS	10/23/2018
Original Complaint: graffiti						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190046	09/25/18	12005004300	<b>1247 SATURN DR</b>	ACT ABATE	13	Violation Inspection - PS	10/23/2018
Original Complaint: pog						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190137	09/26/18	13401002700	<b>601 VINSON DR</b>	ACT ABATE	13	Violation Inspection - PS	10/25/2018
Original Complaint: Outdoor furniture stacked? Racks in drive, Old pool deck left up without pool there, windows on fen (I explained that this could possibly be considered art and caller was not happy with that explanation)						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190138	09/26/18	13401001700	<b>525 VINSON DR</b>	ACT ABATE	13	Violation Inspection - PS	10/25/2018
Original Complaint: remodeled interior without permits; added porch on front without permits; no landlord registration; possible overcrowding. possible pool violation (no alarm or self closing gate)						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190166	09/27/18	10713009900	<b>929 GOODBAR DR</b>	ACT ABATE	13	Violation Inspection - PS	10/24/2018
Original Complaint: pog						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190167	09/27/18	10713008200	<b>1214 THOMPSON PL</b>	ACT ABATE	13	Violation Inspection - PS	10/24/2018
Original Complaint: imv, pog						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190171	09/27/18	10803022000	<b>1219 CABANA CIR</b>	ACT ABATE	13	Violation Inspection - PS	10/22/2018
Original Complaint: OS, POG						<u>Source: INSPECTOR REPORTED</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190172	09/27/18	10803003700	<b>1218 CABANA CIR</b>	ACT ABATE	13	Violation Inspection - PS	10/18/2018
Original Complaint: JTD in Drive						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190180	09/27/18	10713003500	<b>891 KIPLING DR</b>	ACT ABATE	13	Violation Inspection - PS	10/26/2018
Original Complaint: Vehicles on the grass						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190195	09/27/18	10714012500	<b>1015 KIPLING DR</b>	ACT ABATE	13	Violation Inspection - PS	10/25/2018
Original Complaint:						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190197	09/27/18	10714007400	<b>906 ALADDIN DR</b>	ACT ABATE	13	Violation Inspection - PS	10/25/2018
Original Complaint: imv, jtd, bpr, pog, siding						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190198	09/27/18	10714007300	<b>908 ALADDIN DR</b>	ACT ABATE	13	Violation Inspection - PS	10/25/2018
Original Complaint: jtd, pog						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190199	09/27/18	10714007200	<b>910 ALADDIN DR</b>	ACT ABATE	13	Violation Inspection - PS	10/25/2018
Original Complaint: jtd, wood						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190200	09/27/18	12002000700	<b>1021 ALADDIN DR</b>	ACT ABATE	13	Violation Inspection - PS	10/25/2018
Original Complaint: pog						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190201	09/27/18	12002003300	<b>1305 KERMIT DR</b>	ACT ABATE	13	Violation Inspection - PS	10/25/2018
Original Complaint: pog						<u>Source: INSPECTOR REPORTED</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190202	09/27/18	10714006500	<b>917 KIPLING DR</b>	ACT ABATE	13	Violation Inspection - PS	10/25/2018
Original Complaint: pog						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190207	09/27/18	12002001100	<b>1310 KERMIT DR</b>	ACT ABATE	13	Violation Inspection - PS	10/25/2018
Original Complaint: pog						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190273	09/28/18	10808009300	<b>1004 ELM CT</b>	ACT ABATE	13	Violation Inspection - PS	10/15/2018
Original Complaint: HGW,JTD						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190291	09/28/18	10705019100	<b>818 PATRICIA DR</b>	ACT ABATE	13	Violation Inspection - PS	10/26/2018
Original Complaint: building permit required						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190293	09/28/18	10713009100	<b>904 CONNELLY DR</b>	ACT ABATE	13	Violation Inspection - PS	10/29/2018
Original Complaint: parking on grass, junk trash and debris						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190294	09/28/18	10800005001	<b>3108 ELM HILL PIKE</b>	PENDING	13	Initial Violation Inspection - PS	09/29/2018
Original Complaint: Type: Property Violations - Junk and Debris						<u>Source: HUB</u>	

Description:

Mattress, couch and other discarded household items sitting in front yard and on the curb by the road.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188538	09/04/18	09610002200	<b>521 COTTONWOOD DR</b>	ACT ABATE	14	Warrant Check - PS	12/03/2018
Original Complaint: High grass/weeds						<u>Source: Codes Online</u>	

**Master RFS Detail Report**

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188539	09/04/18	09610002200	<b>521 COTTONWOOD DR</b>	ACT ABATE	14	Violation Inspection - PS	09/28/2018
Original Complaint: Junk trash and debris						<u>Source:</u> Codes Online	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188588	09/04/18	09611011400	<b>627 GAILWOOD LN</b>	ACT ABATE	14	Warrant Check - PS	12/03/2018
Original Complaint: Grass						<u>Source:</u> Codes Online	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188626	09/05/18	08601006000	<b>117 ALOHA CT</b>	ACT ABATE	14	Violation Inspection - PS	10/29/2018
Original Complaint: Junk trash and debris in back yard. (lumber)						<u>Source:</u> Codes Online	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188627	09/05/18	08601005900	<b>113 ALOHA CT</b>	ACT ABATE	14	Violation Inspection - PS	10/29/2018
Original Complaint: Grass						<u>Source:</u> Codes Online	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188933	09/10/18	09610010900	<b>2938 LEATHERWOOD DR</b>	ACT ABATE	14	Violation Inspection - PS	10/11/2018
Original Complaint: Type: Property Violations - Junk and Debris						<u>Source:</u> HUB	

Description:

This property is 2938 Leatherwood Dr. nashville. It has an SUV that has NOT moved in years. It has flat tires. And there is junk around the yard and garage, also they have cats everywhere. Please help. They make the neighborhood look trashy. Thank you.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188999	09/11/18	08507009200	<b>3112 STAFFORD DR</b>	ACT ABATE	14	Violation Inspection - PS	10/05/2018
Original Complaint: Type: Property Violations - Cars Parked On Lawn						<u>Source:</u> HUB	

Description:

The individuals that live in this property park their vehicles on the front lawn daily, directly in front of the property's front door.

Additional Comments:

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189015	09/11/18	097020A01400CO	<b>1060 RIVERWOOD VILLAGE BLVD</b>	PENDING	14	Initial Violation Inspection - PS	09/12/2018

Original Complaint: Type: Property Violations - Junk and Debris  
 Source: HUB

Description:  
couch and rugs in driveway

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189033	09/11/18	08507006900	<b>216 DEDHAM DR</b>	ACT ABATE	14	Violation Inspection - PS	09/28/2018

Original Complaint: HOW TAKEN: HUB request here  
 Source: HUB

Lawn parking has become more prevalent in Stanford Estates lately. Just hoping a few notices, reminders or

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189181	09/13/18	08602005800	<b>7005 PANAMA DR</b>	PENDING	14	Initial Violation Inspection - PS	09/14/2018

Original Complaint: High grass/weeds  
 Source: PHONE

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189340	09/14/18	09606009000	<b>2916 MCCAMPBELL AVE</b>	PENDING	14	Env Court 1st Setting - PS	11/07/2018

Original Complaint: host- no strp permit  
 Source: EMAIL

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189449	09/17/18	08507010700	<b>3115 STAFFORD DR</b>	ACT ABATE	14	Violation Inspection - PS	10/12/2018

Original Complaint: Type: Property Violations - Cars Parked On Lawn  
 Source: HUB

Description:  
This property is never maintained. The owner has a large boat on the front yard together with a large trampoline. As if this wasn't enough, they usually maintain about 3 cars parked on the front yard and have now started parking even more, making the property look more like a junk car sales lot. In addition, the owner also keeps junk like old furniture in the carport of the property.

Additional Comments:

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189516	09/17/18	07509004200	<b>217 BONNAFIELD DR</b>	ACT ABATE	14	Violation Inspection - PS	10/29/2018
Original Complaint: Parking in the grass						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189577	09/18/18	09606007400	<b>2902 MCCAMPBELL AVE</b>	ACT ABATE	14	Violation Inspection - PS	10/09/2018
Original Complaint: Type: Property Violations - Tall Grass and Weeds						<u>Source: HUB</u>	

Description:  
Reporting tall grass and weeds in back yard.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189583	09/18/18	08600015200	<b>3800 CENTRAL PIKE</b>	ACT ABATE	14	Violation Inspection - PS	10/26/2018
Original Complaint: High grass/weeds						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189735	09/19/18	08510001400	<b>217 WALCOTT DR</b>	PENDING	14	Violation Inspection - PS	10/01/2018
Original Complaint: no license plate, silver 4 door chrysler like car.						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189848	09/21/18	07404005400	<b>8134 BONNAFAIR DR</b>	PENDING	14	Initial Violation Inspection - PS	09/22/2018
Original Complaint: Type: Property Violations - Tall Grass and Weeds						<u>Source: HUB</u>	

Description:  
Lawn has only been mowed once this year. Codes was contacted previously this summer the sam issue. It was only mowed after that report. I believe this is a rental property, but is currently occupied.

Additional Comments:

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189914	09/24/18	08610004100	<b>3517 MAGNUM DR</b>	PENDING	14	Initial Violation Inspection - PS	09/25/2018
Original Complaint: HOW TAKEN: PHONE Duplex 3519; Mr. Timothy Childs (615) 930-8258; holes (flooring & walls) throughout the house; trash under the house; no smoke dectors						<u>Source:</u> PHONE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189928	09/24/18	086140A12200CO	<b>122 THISTLE LN</b>	PENDING	14	Initial Violation Inspection - PS	09/25/2018
Original Complaint: Type: Property Violations - Cars Parked On Lawn						<u>Source:</u> HUB	
Description: Caller states inoperable car has been placed in a parking space at address.							
Additional Comments:							

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189945	09/24/18	09610020200	<b>2922 DUNMORE DR</b>	ACT ABATE	14	Violation Inspection - PS	10/09/2018
Original Complaint: IMV'S JTD HG&W						<u>Source:</u> INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190089	09/26/18	08507010200	<b>3105 STAFFORD DR</b>	ACT ABATE	14	Violation Inspection - PS	10/16/2018
Original Complaint: Type: Property Violations - Cars Parked On Lawn						<u>Source:</u> HUB	
Description: The owner of this home parks 2 to 3 cars on the front lawn daily. One of which is a black pickup truck and the other two are small sedans. Because of it, the front lawn is usually muddy and unfortunately very unattractive.							
Additional Comments:							

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190153	09/26/18	07416002000	<b>5017 BONNAMEADE DR</b>	PENDING	14	Initial Violation Inspection - PS	09/27/2018

Original Complaint: Type: Property Violations - Junk and Debris Source: HUB

Description:

There is an old mattress in the ditch. There is trash in the driveway and around the front of the hou:

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190227	09/28/18	09610002400	<b>3108 CROSSWOOD DR</b>	TRANSFERRD	14		

Original Complaint: Reported there is a dead large tree which is hollow inside and a neighbor fears it may fall on his house and vehicles. Source: SPE

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190290	09/28/18	07404007200	<b>8151 BONNAFAIR DR</b>	PENDING	14	Initial Violation Inspection - PS	09/29/2018

Original Complaint: fallen tree on fence and air conditioner unit Source: PHONE

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188540	09/04/18	06211004300	<b>2809 GAYWINDS CT</b>	ACT ABATE	15	Violation Inspection - PS	10/26/2018

Original Complaint: 3 Inoperable vehicles in driveway. Source: Codes Online

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188792	09/06/18	094080A00200CO	<b>245 B CLOVERNOOK DR</b>	ACT ABATE	15	Violation Inspection - PS	09/28/2018

Original Complaint: Junk, trash, and debris; inoperable vehicles Source: PHONE

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188861	09/07/18	07303003500	<b>2612 BROWNWOOD DR</b>	ACT ABATE	15	Violation Inspection - PS	10/16/2018

Original Complaint: Junk trash an ddebris Source: Codes Online

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188931	09/10/18	052130B34900CO	<b>2620 RIVER MEADE WAY</b>	ACT ABATE	15	Violation Inspection - PS	10/16/2018
Original Complaint: Type: Property Violations - Tall Grass and Weeds						<u>Source: HUB</u>	

Description:  
High grass/weeds

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188971	09/10/18	09613010600	<b>2831 TWIN LAWN DR</b>	PENDING	15	Env Court 1st Setting - PS	10/31/2018
Original Complaint: NOT OWNER OCCUPIED						<u>Source: EMAIL</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188973	09/10/18	09602001700	<b>2841 LEBANON PIKE</b>	ACT ABATE	15	Violation Inspection - PS	10/05/2018
Original Complaint: high grass weeds						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188990	09/11/18	08412001400	<b>3106 WINDEMERE CIR</b>	ACT ABATE	15	Violation Inspection - PS	10/18/2018
Original Complaint: Type: Property Violations - Residential Complaint						<u>Source: HUB</u>	

Description:  
A silver Dodge Grand Caravan that does not run is parked in the driveway at 3106 Windemere Circ  
It has been there for months. The minivan is full of trash and is not sanitary.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188996	09/11/18	09602004700	<b>124 STEWARTS FERRY PIKE</b>	ACT ABATE	15	Violation Inspection - PS	09/28/2018
Original Complaint: Type: Property Violations - Tall Grass and Weeds						<u>Source: HUB</u>	

Description:  
Grass not cut. Weeds almost 2 feet tall

Additional Comments:

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189011	09/11/18	09514010300	<b>2162 SANBORN DR</b>	ACT ABATE	15	Violation Inspection - PS	10/05/2018
Original Complaint: Junk, trash & debris						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189013	09/11/18	09514010300	<b>2162 SANBORN DR</b>	ACT ABATE	15	Violation Inspection - PS	09/28/2018
Original Complaint: High grass & weeds						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189129	09/13/18	09511001100	<b>404 WANDA DR</b>	ACT ABATE	15	Violation Inspection - PS	09/28/2018
Original Complaint: Type: Property Violations - Tall Grass and Weeds						<u>Source: HUB</u>	

Description:  
The grass at this house has not been mowed in over a month. The grass is now covering parts of driveway.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189145	09/13/18	07303005700	<b>2841 MCGAVOCK PIKE</b>	ACT ABATE	15	Violation Inspection - PS	10/18/2018
Original Complaint: Type: Other - Other						<u>Source: HUB</u>	

Description:  
remodeling /rehab without building permit. dumpster and port a john in driveway

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189292	09/14/18	07307001200	<b>2842 MCGAVOCK PIKE</b>	ACT ABATE	15	Violation Inspection - PS	10/19/2018
Original Complaint: Type: Other - Other						<u>Source: HUB</u>	

Description:  
running a business from house. hvac business . company vans parked at house. check link <http://www.buzzfile.com/business/Hvac-Digital-615-391-5278>  
state license #46611

Additional Comments:

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189309	09/14/18	07307006200	<b>2421 FAIRBROOK DR</b>	ACT ABATE	15	Violation Inspection - PS	10/19/2018
Original Complaint: Type: Other - Other						<u>Source:</u> HUB	

Description:  
major rehab without building permit. cabinets stored out front. living in RV in driveway.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189384	09/17/18	094080A00100CO	<b>245 A CLOVERNOOK DR</b>	ACT HSGDEM	15	Administrative Hearing - PS	11/08/2018
Original Complaint: CONFIRMED METH LAB - DEMO						<u>Source:</u> Metro PD	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189445	09/17/18	08415015400	<b>97 FAIRWAY DR</b>	ACT ABATE	15	Violation Inspection - PS	10/02/2018
Original Complaint: Type: Property Violations - Cars Parked On Lawn						<u>Source:</u> HUB	

Description:  
Daily parking on front lawn for 3+ months

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189469	09/17/18	09511008600	<b>412 ADAIR RD</b>	ACT ABATE	15	Violation Inspection - PS	10/08/2018
Original Complaint: Type: Property Violations - Tall Grass and Weeds						<u>Source:</u> HUB	

Description:  
Tall Grass no one has cut grass since May 2018.

Additional Comments:

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189546	09/18/18	08414015100	<b>119 DELLROSE DR</b>	ACT ABATE	15	Violation Inspection - PS	10/18/2018

Original Complaint: Type: Property Violations - Tall Grass and Weeds  
Source: HUB

Description:

GRASS HASN'T BEEN MOWED IN WEEKS. ALSO A DILAPIDATED STRUCTURE IN BACK YARD. THE WALL PANELS ARE ROTTING AND FALLING OFF. AN OLD HOT WATER HEATEF HAS BEEN IN THE DRIVEWAY FOR MORE THAN A YEAR

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189581	09/18/18	07312001400	<b>2919 MCGAVOCK PIKE</b>	ACT ABATE	15	Violation Inspection - PS	10/18/2018

Original Complaint: No electricity or running water  
Source: PHONE

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189624	09/18/18	052130B30200CO	<b>1208 ALANDEE ST</b>	ACT ABATE	15	Violation Inspection - PS	10/04/2018

Original Complaint: junk trash and debris  
Source: INSPECTOR REPORTED

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189665	09/19/18	08411010000	<b>2326 DENNYWOOD DR</b>	ACT ABATE	15	Violation Inspection - PS	10/09/2018

Original Complaint: High grass/weeds  
Source: PHONE

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189732	09/19/18	09602003100	<b>122 DONELSONWOOD DR</b>	ACT ABATE	15	Violation Inspection - PS	10/29/2018

Original Complaint: high grass weeds  
Source: PHONE

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189755	09/20/18	09511010500	<b>405 ADAIR RD</b>	ACT ABATE	15	Violation Inspection - PS	10/08/2018

Original Complaint: Type: Property Violations - Junk and Debris  
Source: HUB

Description:

Discarded furniture in front yard for over a week

Additional Comments:

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189773	09/20/18	06200027000	<b>2701 PENNINGTON BEND RD</b>	TRANSFERRD	15		

Original Complaint: HOW TAKEN: PHONE Source: PHONE  
 Added an addition to the ditch, or covered/paved over the ditch which is causing water runoff unto neighbor's yard

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189831	09/21/18	06200015100	<b>2444 MUSIC VALLEY DR</b>	ACT ABATE	15	Violation Inspection - PS	10/25/2018

Original Complaint: grand Ole Gold/ Go karts, Caller says property has broken/ rottedthrough the putt putt golf, felt like was dangerous Source: PHONE

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189866	09/24/18	06211003500	<b>2835 GAYWINDS CT</b>	ACT ABATE	15	Violation Inspection - PS	10/18/2018

Original Complaint: High grass/weeds Source: PHONE

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190008	09/25/18	07303002100	<b>2619 BROWNWOOD DR</b>	ACT ABATE	15	Violation Inspection - PS	10/15/2018

Original Complaint: Type: Property Violations - Tall Grass and Weeds Source: HUB

Description:  
High grass

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190075	09/25/18	09512015400	<b>2704 MCKEIGE DR</b>	ACT ABATE	15	Violation Inspection - PS	10/08/2018

Original Complaint: PARKING ON GRASS Source: INSPECTOR REPORTED

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190120	09/26/18	07307002700	<b>2412 KIMBERLY DR</b>	ACT ABATE	15	Violation Inspection - PS	10/18/2018

Original Complaint: Reported numerous vehicles parking in the yard every day - please see photos. Source: SPE

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190163	09/27/18	08412004700	<b>3117 KNOBVIEW DR</b>	ACT ABATE	15	Violation Inspection - PS	10/19/2018

Original Complaint: Type: Property Violations - Junk and Debris  
Source: HUB

Description:

A king size mattress and two twin box springs have been sitting in the driveway visible from the road for at least 8 weeks. The two box springs 2 weeks ago were moved to the roadside toward the neighbor's yard but of course trash has not picked them up. I've attached a photo.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188488	09/04/18	11902007900	<b>209 STIRTON RD</b>	ACT ABATE	16	Violation Inspection - PS	10/12/2018

Original Complaint: hw, jtd, pog, use not permitted  
Source: INSPECTOR REPORTED

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188489	09/04/18	11903006700	<b>119 DODGE DR</b>	ACT ABATE	16	Violation Inspection - PS	10/19/2018

Original Complaint: jtd, pog  
Source: INSPECTOR REPORTED

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188501	09/04/18	13302022400	<b>408 ELGIN ST</b>	ACT ABATE	16	Violation Inspection - PS	10/08/2018

Original Complaint: Inoperable vehicle in the back yard  
Source: PHONE

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188595	09/04/18	11908009000	<b>716 CURREY RD</b>	ACT ABATE	16	Violation Inspection - PS	10/02/2018

Original Complaint: pro wood  
Source: INSPECTOR REPORTED

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188597	09/04/18	11907000500	<b>716 OLD GLENROSE AVE</b>	ACT ABATE	16	Violation Inspection - PS	10/02/2018

Original Complaint: hw  
Source: INSPECTOR REPORTED

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188598	09/04/18	11908007600	<b>723 CURREY RD</b>	ACT ABATE	16	Violation Inspection - PS	10/02/2018

Original Complaint: use not permitted, building permit req'd  
Source: INSPECTOR REPORTED

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188750	09/06/18	11915001700	<b>3109 LAKE PARK DR</b>	ACT ABATE	16	Violation Inspection - PS	09/21/2018
Original Complaint: High grass/weeds						<u>Source:</u> Codes Online	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188778	09/06/18	11906011400	<b>63 VALERIA ST</b>	PENDING	16	Env Court 1st Setting - PS	10/24/2018
Original Complaint: host- no strp permit						<u>Source:</u> EMAIL	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188809	09/06/18	11901035200	<b>327 ORIEL AVE</b>	ACT ABATE	16	Violation Inspection - PS	09/28/2018
Original Complaint: Building structure without permit(s)						<u>Source:</u> PHONE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189042	09/11/18	11903012100	<b>289 BROWNING RD</b>	ACT ABATE	16	Violation Inspection - PS	10/09/2018
Original Complaint: jtd						<u>Source:</u> INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189044	09/11/18	13306025900	<b>3699 TIBBS DR</b>	ACT ABATE	16	Violation Inspection - PS	10/12/2018
Original Complaint: Type: Property Violations - Junk and Debris						<u>Source:</u> HUB	

Description:  
table, cushion, and some other wooden peice on the property for over a month.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189082	09/12/18	11905038100	<b>1010 CLEMMONS ST</b>	ACT ABATE	16	Violation Inspection - PS	10/02/2018
Original Complaint: Junk, trash & debris						<u>Source:</u> PHONE	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189184	09/13/18	11916004400	<b>913 DRUMMOND DR</b>	ACT ABATE	16	Violation Inspection - PS	10/05/2018

Original Complaint: Type: Property Violations - Cars Parked On Lawn Source: HUB

Description:  
Boat parked in grass. Covered with a blue tarp

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189185	09/13/18	11916007000	<b>914 DRUMMOND DR</b>	ACT ABATE	16	Violation Inspection - PS	10/25/2018

Original Complaint: Type: Property Violations - Cars Parked On Lawn Source: HUB

Description:  
Car parked in the front yard and there is also a white, inoperable vehicle stored on the property. Been there broken down for a long time.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189189	09/13/18	11916006300	<b>1028 DRUMMOND DR</b>	ACT ABATE	16	Violation Inspection - PS	10/19/2018

Original Complaint: Type: Property Violations - Cars Parked On Lawn Source: HUB

Description:  
Ford Ranger pickup truck parked in grass next to driveway in front. Black compact car parked in grass on other side of house is inoperable and has been parked there for years.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189190	09/13/18	11916005900	<b>1036 DRUMMOND DR</b>	ACT ABATE	16	Violation Inspection - PS	10/22/2018

Original Complaint: Type: Property Violations - Cars Parked On Lawn Source: HUB

Description:  
White inoperable vehicle parked in grass. Has been there for numerous months without moving.

Additional Comments:

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189191	09/13/18	11916005900	<b>1036 DRUMMOND DR</b>	ACT ABATE	16	Violation Inspection - PS	10/05/2018
Original Complaint: Type: Property Violations - Tall Grass and Weeds						<u>Source: HUB</u>	

Description:  
Backyard is overgrown, majorly

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189192	09/13/18	11916006400	<b>1026 DRUMMOND DR</b>	ACT ABATE	16	Violation Inspection - PS	10/22/2018
Original Complaint: Type: Property Violations - Cars Parked On Lawn						<u>Source: HUB</u>	

Description:  
Broken down, inoperable white van parked in the pack yard. This house is ridiculous.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189194	09/13/18	11916005400	<b>1005 DRUMMOND DR</b>	ACT ABATE	16	Violation Inspection - PS	10/05/2018
Original Complaint: Type: Property Violations - Cars Parked On Lawn						<u>Source: HUB</u>	

Description:  
White truck parked in the grass

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189293	09/14/18	11906026300	<b>104 GLENROSE CIR</b>	ACT ABATE	16	Violation Inspection - PS	10/04/2018
Original Complaint: IMV'S						<u>Source: INSPECTOR REPORTED</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189295	09/14/18	11916008900	<b>1001 DRUMMOND DR</b>	ACT ABATE	16	Violation Inspection - PS	10/19/2018
Original Complaint: Type: Other - Other						<u>Source: HUB</u>	

Description:  
Inoperable vehicle parked in grass next to the carport. Its a broke down pickup truck.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189374	09/17/18	13302026900	<b>195 CHILTON ST</b>	ACT ABATE	16	Violation Inspection - PS	10/05/2018
Original Complaint: Type: Property Violations - Tall Grass and Weeds						<u>Source: HUB</u>	

Description:  
Unkempt lawn: grass and weeds over 1 foot tall throughout front and back yards.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189504	09/17/18	11907000800	<b>724 OLD GLENROSE AVE</b>	ACT ABATE	16	Violation Inspection - PS	10/15/2018
Original Complaint: POG, JTD						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189506	09/17/18	11903004800	<b>124 STIRTON RD</b>	ACT ABATE	16	Violation Inspection - PS	10/15/2018
Original Complaint: POG						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189509	09/17/18	11903005000	<b>128 STIRTON RD</b>	ACT ABATE	16	Violation Inspection - PS	10/15/2018
Original Complaint: IMV, POG, JTD						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189512	09/17/18	11902007200	<b>200 STIRTON RD</b>	ACT ABATE	16	Violation Inspection - PS	10/15/2018
Original Complaint: JTD, HIGH WEEDS						<u>Source: INSPECTOR REPORTED</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189513	09/17/18	11903006400	<b>105 STIRTON RD</b>	ACT ABATE	16	Violation Inspection - PS	10/15/2018
Original Complaint: JTD						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189514	09/17/18	11903005900	<b>115 STIRTON RD</b>	ACT ABATE	16	Violation Inspection - PS	10/15/2018
Original Complaint: IMV, POG						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189515	09/17/18	11903004200	<b>112 STIRTON RD</b>	ACT ABATE	16	Violation Inspection - PS	10/15/2018
Original Complaint: IMV, POG, JTD						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189517	09/17/18	11903004500	<b>118 STIRTON RD</b>	ACT ABATE	16	Violation Inspection - PS	10/15/2018
Original Complaint: IMV, JTD						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189518	09/17/18	11903004600	<b>120 STIRTON RD</b>	ACT ABATE	16	Violation Inspection - PS	10/15/2018
Original Complaint: POG						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189519	09/17/18	11902008600	<b>227 STIRTON RD</b>	ACT ABATE	16	Violation Inspection - PS	10/15/2018
Original Complaint: JTD						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189520	09/17/18	11902008700	<b>219 GARWOOD DR</b>	ACT ABATE	16	Violation Inspection - PS	10/15/2018
Original Complaint: IMV, JTD, PRO WOOD						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189521	09/17/18	11902007600	<b>201 STIRTON RD</b>	ACT ABATE	16	Violation Inspection - PS	10/15/2018
Original Complaint: IMV, POG						<u>Source: INSPECTOR REPORTED</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189523	09/17/18	11902007700	<b>203 STIRTON RD</b>	ACT ABATE	16	Violation Inspection - PS	10/15/2018
Original Complaint: POG						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189533	09/17/18	11901048300	<b>2316 FOSTER AVE</b>	PENDING	16	Initial Violation Inspection - PS	09/18/2018
Original Complaint: Plumbing issues; electrical issues; huge holes in the walls; water leaks-contact Ashley Callis 615-769-9989						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189534	09/17/18	13302025500	<b>3312 B NOLENSVILLE PIKE</b>	ACT ABATE	16	PS - Memo Only	09/20/2018
Original Complaint: Furniture store has busted windows - many are covered with only cardboard and many are covered up with mattresses on the inside,						<u>Source: SPE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189573	09/18/18	10616002300	<b>921 CROWNHILL DR</b>	ACT ABATE	16	Violation Inspection - PS	10/18/2018
Original Complaint: Type: Property Violations - Tall Grass and Weeds						<u>Source: HUB</u>	
Description: Weeds over a foot							
Additional Comments:							

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189575	09/18/18	10616001600	<b>924 CROWNHILL DR</b>	ACT ABATE	16	Violation Inspection - PS	10/18/2018
Original Complaint: Type: Property Violations - Tall Grass and Weeds						<u>Source: HUB</u>	
Description: High weeds and grass							
Additional Comments:							

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189576	09/18/18	10615003100	<b>901 CROWNHILL DR</b>	ACT ABATE	16	Violation Inspection - PS	10/18/2018

Original Complaint: Type: Property Violations - Cars Parked On Lawn  
Source: HUB

Description:  
 Car parked in front yard since last week

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189618	09/18/18	10616002700	<b>406 FOOTHILL DR</b>	ACT ABATE	16	Violation Inspection - PS	10/16/2018

Original Complaint: jtd  
Source: INSPECTOR REPORTED

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189637	09/19/18	11914011100	<b>3002 SIMMONS AVE</b>	ACT ABATE	16	Violation Inspection - PS	10/22/2018

Original Complaint: HOW TAKEN: !!! SPE !!!  
 Reported someone may be residing in the shed on the property and an inoperable RV on the premises.  
Source: SPE

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189639	09/19/18	11914009900	<b>248 MORTON AVE</b>	ACT ABATE	16	Violation Inspection - PS	10/26/2018

Original Complaint: Vehicles parked in yard - no all have current tags  
Source: SPE

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189642	09/19/18	11914010000	<b>250 MORTON AVE</b>	ACT ABATE	16	Violation Inspection - PS	10/05/2018

Original Complaint: Vehicles parking in yard - do not have current tags  
Source: SPE

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189647	09/19/18	11914010700	<b>304 MORTON AVE</b>	ACT ABATE	16	Violation Inspection - PS	10/22/2018

Original Complaint: School bus and a UHaul is parked in rear yard area  
Source: SPE

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189661	09/19/18	11907001700	<b>386 WIMPOLE DR</b>	PENDING	16	Warrant Check - PS	11/12/2018

Original Complaint: repeat violator pog  
Source: INSPECTOR REPORTED

**Master RFS Detail Report**

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189768	09/20/18	11905006900	<b>220 ELBERTA ST</b>	ACT ABATE	16	Violation Inspection - PS	10/08/2018
Original Complaint: Type: Property Violations - Tall Grass and Weeds						<u>Source: HUB</u>	

Description:  
Grass is 3 feet tall- complaining about snakes

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189798	09/21/18	11905038100	<b>1010 CLEMMONS ST</b>	ACT ABATE	16	Violation Inspection - PS	10/12/2018
Original Complaint: LANDLORD REG.						<u>Source: INSPECTOR REPORTED</u>	

Description:  
No plates on red pickup truck parked on lawn. Old sofa & junk on front lawn. House rundown.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189820	09/21/18	13303001100	<b>3227 SOUTHLAKE DR</b>	ACT ABATE	16	Violation Inspection - PS	10/12/2018
Original Complaint: Type: Property Violations - Tall Grass and Weeds						<u>Source: HUB</u>	

Description:  
Refuses to cut 3 ft weeds/grass by street. Cuts lawn except the strip across front of property, feels it's Metro's responsibility. Backyard full of junk. Old red car in driveway without plates.

Additional Comments:

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189821	09/21/18	13303004900	<b>170 ANTIOCH PIKE</b>	ACT ABATE	16	Violation Inspection - PS	10/12/2018

Original Complaint: Type: Property Violations - Tall Grass and Weeds Source: HUB

Description:

House looks abandoned, yard & shrubs getting overgrown. Shrubs, vines growing over sidewalk o Southlake.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189860	09/24/18	11905005500	<b>231 PEACHTREE ST</b>	ACT ABATE	16	Violation Inspection - PS	10/11/2018

Original Complaint: Type: Property Violations - Tall Grass and Weeds Source: HUB

Description:

Tall grass and weeds, construction Rubble in back yard

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189918	09/24/18	11901049000	<b>109 VALERIA ST</b>	ACT ABATE	16	Violation Inspection - PS	10/15/2018

Original Complaint: HOW TAKEN: PHONE Source: PHONE  
SIMULTANEOUS RENTAL TO MORE THAN ONE PARTY UNDER SEPERATE CONTRACTS. NC  
PERMIT NUMBER OR IMAGE IN WEBSITE ADVERTISEMENTS.

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189995	09/25/18	11914033800	<b>201 MORTON AVE</b>	ACT ABATE	16	Violation Inspection - PS	10/25/2018

Original Complaint: JUNK TRASH AND DEBRIS Source: INSPECTOR REPORTED

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189997	09/25/18	11906031200	<b>212 JAY DR</b>	ACT ABATE	16	Violation Inspection - PS	10/11/2018

Original Complaint: JTD Source: INSPECTOR REPORTED

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190004	09/25/18	11910011300	<b>2806 ST EDWARDS DR</b>	ACT ABATE	16	Violation Inspection - PS	10/16/2018
Original Complaint: Type: Property Violations - Tall Grass and Weeds						<u>Source:</u> HUB	
Description: High grass/weeds							
Additional Comments:							

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190030	09/25/18	13301023600	<b>512 RAYMOND ST</b>	ACT ABATE	16	Violation Inspection - PS	10/15/2018
Original Complaint: mattress and chest of drawers near the property line of 512 and 514.						<u>Source:</u> PHONE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190203	09/27/18	11912008200	<b>33 CAMEO DR</b>	ACT ABATE	16	Violation Inspection - PS	10/12/2018
Original Complaint: HOW TAKEN: INSPECTOR REPORTED HGW						<u>Source:</u> INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190204	09/27/18	11912008300	<b>31 CAMEO DR</b>	ACT ABATE	16	Violation Inspection - PS	10/26/2018
Original Complaint: HOW TAKEN: INSPECTOR REPORTED IMV, JTD						<u>Source:</u> INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190206	09/27/18	11912001800	<b>30 CAMEO DR</b>	ACT ABATE	16	Violation Inspection - PS	10/12/2018
Original Complaint: HOW TAKEN: INSPECTOR REPORTED HGW, JTD						<u>Source:</u> INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190208	09/27/18	11903007700	<b>126 DODGE DR</b>	ACT ABATE	16	Violation Inspection - PS	10/25/2018
Original Complaint: jtd, bpr, wood						<u>Source:</u> INSPECTOR REPORTED	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190209	09/27/18	11912008600	<b>25 CAMEO DR</b>	ACT ABATE	16	Violation Inspection - PS	10/12/2018
Original Complaint: HOW TAKEN: INSPECTOR REPORTED HGW						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190211	09/27/18	11912002200	<b>22 CAMEO DR</b>	ACT ABATE	16	Violation Inspection - PS	10/12/2018
Original Complaint: HOW TAKEN: INSPECTOR REPORTED JTD						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190238	09/28/18	11905033600	<b>303 JOYNER AVE</b>	ACT ABATE	16	Violation Inspection - PS	10/19/2018
Original Complaint: junk and debris						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190280	09/28/18	12001014100	<b>1189 MURFREESBORO PIKE</b>	PENDING	16	Initial Violation Inspection - PS	09/29/2018
Original Complaint: Type: Property Violations - Junk and Debris						<u>Source: HUB</u>	

Description:

This gas station is full of trash around its entire area and has now begun to spill into the surrounding homes and apartments. Additionally, there is a problem with homeless sleeping near its dumpster and drugs being sold. It is near children's school bus stop and is not SAFE for kids to walk to that area. It would be greatly helpful for this gas station to be forced to maintain their business clean and most importantly safe from drugs and homeless.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188513	09/04/18	11804026000	<b>2226 CRUZEN ST</b>	ACT ABATE	17	Violation Inspection - PS	10/12/2018
Original Complaint: Inoperable vehicle in yard.						<u>Source: Codes Online</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188550	09/04/18	10505057500	<b>1021 SUMMIT AVE</b>	ACT ABATE	17	Violation Inspection - PS	10/17/2018
Original Complaint: Owner does not live at property. Advertising over bedroom limit.						<u>Source: Codes Online</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188661	09/05/18	10511002500	<b>506 SOUTHGATE AVE</b>	ACT ABATE	17	Pre-Court Inspection - PS	10/30/2018
Original Complaint: JTD, HGW						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188681	09/05/18	10613010400	<b>2023 HUTTON DR</b>	ACT ABATE	17	Violation Inspection - PS	10/03/2018
Original Complaint: Junk, trash & debris in the front & back yard; commercial vehicle in a residential area						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188726	09/05/18	10509018400	<b>1106 ACKLEN AVE</b>	ACT ABATE	17	Violation Inspection - PS	10/19/2018
Original Complaint: Junk, trash, and debris						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188727	09/05/18	10509017400	<b>1113 W GROVE AVE</b>	ACT ABATE	17	Violation Inspection - PS	10/23/2018
Original Complaint: Illegally dumping trash in the alleyway						<u>Source: HUB</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188751	09/06/18	10504000700	<b>14 PERKINS ST</b>	ACT ABATE	17	Violation Inspection - PS	10/19/2018
Original Complaint: High grass/weeds						<u>Source: HUB</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188889	09/10/18	10513015400	<b>1000 S DOUGLAS AVE</b>	ACT ABATE	17	Violation Inspection - PS	10/04/2018
Original Complaint:						<u>Source: HUB</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188923	09/10/18	10509031400	<b>1009 W GROVE AVE</b>	ACT ABATE	17	Violation Inspection - PS	10/23/2018
Original Complaint: Type: Property Violations - Cars Parked On Lawn						<u>Source: HUB</u>	

Description:  
 Caller states there are 2 cars parked in back yard of address 1009 West Grove Ave

Additional Comments:

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188951	09/10/18	10614002600	<b>1985 CARLOSS DR</b>	ACT ABATE	17	Violation Inspection - PS	10/08/2018

Original Complaint: imv Source: INSPECTOR REPORTED

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188998	09/11/18	10613005500	<b>2135 ROSEMARY LN</b>	ACT ABATE	17	Violation Inspection - PS	10/22/2018

Original Complaint: Type: Property Violations - Junk and Debris Source: HUB

Description:

Mattresses out front for 3 months, debris along side of house. And a dog chained without water or medical attention

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189069	09/12/18	10511000700	<b>610 SOUTHGATE AVE</b>	ACT ABATE	17	Violation Inspection - PS	10/26/2018

Original Complaint: Type: Property Violations - Tall Grass and Weeds Source: HUB

Description:

Overgrown bushes, some blocking ROW

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189092	09/12/18	10507031100	<b>623 MOORE AVE</b>	ACT ABATE	17	Violation Inspection - PS	10/22/2018

Original Complaint: Type: Property Violations - Tall Grass and Weeds Source: HUB

Description:

Tall grass

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189124	09/13/18	105054C00100CO	<b>1004 WADE AVE</b>	PENDING	17	Env Court 1st Setting - PS	10/31/2018

Original Complaint: operating without a strp permit Source: EMAIL

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189154	09/13/18	10509044200	<b>2039 ELLIOTT AVE</b>	PENDING	17	Env Court 1st Setting - PS	10/31/2018
Original Complaint: host-no strp permit						<u>Source: EMAIL</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189155	09/13/18	10504001900	<b>17 PERKINS ST</b>	ACT ABATE	17	Violation Inspection - PS	10/19/2018
Original Complaint: Type: Property Violations - Tall Grass and Weeds						<u>Source: HUB</u>	

Description:  
Tall grass on vacant lot

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189173	09/13/18	10507031100	<b>623 MOORE AVE</b>	ACT VEHROW	17	Violation Inspection CAR - PS	10/05/2018
Original Complaint: Type: Public Safety - Abandoned Vehicles						<u>Source: HUB</u>	

Description:  
Abandoned limo with expired tags - has been parked here for months

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189303	09/14/18	10502045100	<b>1022 9TH AVE S</b>	ACT ABATE	17	Violation Inspection - PS	10/19/2018
Original Complaint: Type: Property Violations - Tall Grass and Weeds						<u>Source: HUB</u>	

Description:  
Unmoved grass

Additional Comments:

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189310	09/14/18	10513036700	<b>911 WALDKIRCH AVE</b>	ACT ABATE	17	Violation Inspection - PS	10/26/2018

Original Complaint: Type: Property Violations - Junk and Debris Source: HUB

Description:

Construction debris and trash piled up in backyard just off the alley. Been there all summer - trash bags full of water breeding mosquitoes.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189323	09/14/18	10503014100	<b>21 WHARF AVE</b>	ACT ABATE	17	Violation Inspection - PS	10/22/2018

Original Complaint: Type: Property Violations - Tall Grass and Weeds Source: HUB

Description:

Overgrown vacant house

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189333	09/14/18	10513021200	<b>1110 CARUTHERS AVE</b>	PENDING	17	Violation Inspection - PS	10/25/2018

Original Complaint: Reported that the company responsible to trash removal from the dumpsters are again emptying th Source: SPE  
dumpsters at 4:00 AM in the mornings - repeat violator.

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189334	09/14/18	10509043200	<b>1904 ELLIOTT AVE</b>	PENDING	17	Env Court 1st Setting - PS	11/07/2018

Original Complaint: host- no strp permit Source: EMAIL

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189365	09/14/18	105014A04100CO	<b>1002 11TH AVE S</b>	ACT ABATE	17	Violation Inspection - PS	10/05/2018

Original Complaint: HOW TAKEN: PHONE  
(HOTLINE TIP) NUISANCE: NOISE. NO STRP PERMIT NUMBER OR IMAGE IN WEBSITE  
ADVERTISEMENT. Source: PHONE

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189367	09/17/18	105074S90000CO	<b>515 C MOORE AVE</b>	TRANSFERRD	17		
Original Complaint: Owners have sloped/raised the front yard and is causing water runoff						<u>Source:</u> WALK IN	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189392	09/17/18	10514018500	<b>823 HILLVIEW HTS</b>	PENDING	17	Initial Violation Inspection - PS	09/18/2018
Original Complaint: Type: Property Violations - Short Term Rental Complaint						<u>Source:</u> HUB	

Description:

This house doesn't appear to have a short term rental permit. Lot's of people coming and going tha don't appear to live there full time.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189395	09/17/18	105070I00100CO	<b>619 A MOORE AVE</b>	PENDING	17	Initial Violation Inspection - PS	09/18/2018
Original Complaint: Type: Property Violations - Short Term Rental Complaint						<u>Source:</u> HUB	

Description:

Continues to rent despite injunction

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189452	09/17/18	105054B00100CO	<b>1020 ARGYLE AVE</b>	ACT ABATE	17	Violation Inspection - PS	10/22/2018
Original Complaint: Type: Property Violations - Junk and Debris						<u>Source:</u> HUB	

Description:

For several weeks now, the tenants at 1020 Argyle Avenue have been disposing of their household waste incorrectly. They have been placing their trash in their recycling bins and vice versa. Becau the trash is sitting in the wrong bin and in the sun for weeks at a time, it has created a fly and maggot problem. Additionally, their recycling has accumulated to such an extent that it is now strewn about the back of the property and onto the right-of-way. This is making it difficult to get into and out of our parking spots.

Additional Comments:

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189524	09/17/18	10614003300	<b>96 SCOBAY DR</b>	ACT ABATE	17	Violation Inspection - PS	10/15/2018
Original Complaint: WOOD, JTD						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189567	09/18/18	10516003200	<b>521 WAYCROSS DR</b>	ACT ABATE	17	Violation Inspection - PS	10/29/2018
Original Complaint: Type: Property Violations - Tall Grass and Weeds						<u>Source: HUB</u>	

Description:  
Weeds and Grass waist high

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189627	09/18/18	11803003600	<b>560 ROSEDALE AVE</b>	PENDING	17	Env Court 1st Setting - PS	11/07/2018
Original Complaint: host- no strp permit						<u>Source: EMAIL</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189630	09/18/18	11808020800	<b>2614 WINFORD AVE</b>	ACT ABATE	17	Violation Inspection - PS	10/26/2018
Original Complaint: Type: Property Violations - Tall Grass and Weeds						<u>Source: HUB</u>	

Description:  
This property is across the street from. It is overgrown with weeds higher than 12"

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189702	09/19/18	10511002500	<b>506 SOUTHGATE AVE</b>	PENDING	17	Pre-Court Inspection - PS	10/30/2018
Original Complaint: JTD						<u>Source: INSPECTOR REPORTED</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189756	09/20/18	09315027500	<b>916 3RD AVE S</b>	ACT ABATE	17	Violation Inspection - PS	10/23/2018

Original Complaint: Type: Property Violations - Dilapidated Structures Source: HUB

Description:

This building has several broken windows and is a haven for drug activity, dice games, and gambler. Supposedly, a production company uses the facility (<https://www.productionhub.com/profile/russ-sturgeon-productions-rsvp>). The owner shows as Neld Sturgeon, but its unclear in any way how the structure is actively used. The owner needs to clean up the property and stop allowing drug activity to occur on the property. There is a strange window covering upstairs and what appears to be a ramp for trash (?) coming off of the awning.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189757	09/20/18	10503006600	<b>1100 3RD AVE S</b>	ACT ABATE	17	Violation Inspection - PS	10/23/2018

Original Complaint: Type: Property Violations - Tall Grass and Weeds Source: HUB

Description:

This is the second time this summer that I have reported this property for tall grass and weeds. It is vacant lot, and it also appears that there are vagrants spending significant time on the property, hiding in the trees. There is abundant trash and it looks like there may even be a couch back in the "jungle". The property owner needs to cut the grass, clean up the trash, and ensure that squatters are not using the property.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189874	09/24/18	10404021000	<b>1204 17TH AVE S</b>	PENDING	17	Initial Violation Inspection - PS	09/25/2018

Original Complaint: Type: Property Violations - Short Term Rental Complaint Source: HUB

Description:

Listing is for 26 guests=1 strike  
 Listing for 8 bedrooms=1 strike  
<https://www.vrbo.com/718133>

Additional Comments:

**Master RFS Detail Report**

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189875	09/24/18	10507042500	<b>1285 2ND AVE S</b>	PENDING	17	Initial Violation Inspection - PS	09/25/2018
Original Complaint: Type: Property Violations - Short Term Rental Complaint						<u>Source:</u> HUB	

Description:  
 24 guests are allowed to stay in this STR:  
<https://www.vrbo.com/1228983>

Additional Comments:

---

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189906	09/24/18	10614019100	<b>77 LYLE LN</b>	ACT ABATE	17	Violation Inspection - PS	10/22/2018
Original Complaint: imv, jtd, pog, acc.str, wood						<u>Source:</u> INSPECTOR REPORTED	

---

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189907	09/24/18	10614018400	<b>1901 S LYLE LN</b>	ACT ABATE	17	Violation Inspection - PS	10/22/2018
Original Complaint: imv, pog						<u>Source:</u> INSPECTOR REPORTED	

---

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189908	09/24/18	10614018400	<b>1903 S LYLE LN</b>	ACT ABATE	17	Violation Inspection - PS	10/22/2018
Original Complaint: jtd						<u>Source:</u> INSPECTOR REPORTED	

---

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189909	09/24/18	10614018500	<b>1905 S LYLE LN</b>	ACT ABATE	17	Violation Inspection - PS	10/22/2018
Original Complaint: jtd, pog, wood						<u>Source:</u> INSPECTOR REPORTED	

---

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189911	09/24/18	10614018600	<b>1909 S LYLE LN</b>	ACT ABATE	17	Violation Inspection - PS	10/22/2018
Original Complaint: jtd, pog, imv, wood						<u>Source:</u> INSPECTOR REPORTED	

---

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189913	09/24/18	10614018700	<b>1913 S LYLE LN</b>	ACT ABATE	17	Violation Inspection - PS	10/22/2018
Original Complaint: jtd						<u>Source:</u> INSPECTOR REPORTED	

**Master RFS Detail Report**

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189915	09/24/18	10614018800	<b>1917 S LYLE LN</b>	ACT ABATE	17	Violation Inspection - PS	10/22/2018
Original Complaint: imv, jtd, pog, wood						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190001	09/25/18	10504004900	<b>59 LINCOLN ST</b>	ACT ABATE	17	Violation Inspection - PS	10/30/2018
Original Complaint: High grass/weeds						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190009	09/25/18	10613022900	<b>106 SADLER CT</b>	ACT ABATE	17	Violation Inspection - PS	10/15/2018
Original Complaint: Type: Property Violations - Graffiti on Private Property						<u>Source: HUB</u>	

Description:  
Large white "X" on side of the house.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190181	09/27/18	10504008700	<b>54 TRIMBLE ST</b>	ACT ABATE	17	Violation Inspection - PS	10/30/2018
Original Complaint: Type: Property Violations - Junk and Debris						<u>Source: HUB</u>	

Description:  
Tons of trash, from big to little things. I think people are living there in tents.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190182	09/27/18	10504007400	<b>16 LEWIS ST</b>	ACT ABATE	17	Violation Inspection - PS	10/30/2018
Original Complaint: Type: Property Violations - Junk and Debris						<u>Source: HUB</u>	

Description:  
Trash all over the place. Looks like people are living on this empty lot.

Additional Comments:

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190254	09/28/18	10509032200	<b>1004 ACKLEN AVE</b>	ACT ABATE	17	Violation Inspection - PS	11/01/2018
Original Complaint: Type: Property Violations - Fence Complaints						<u>Source: HUB</u>	

Description:  
Tall privacy fence being built right to the front sidewalk. is this legal?

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190289	09/28/18	10513035500	<b>912 WALDKIRCH AVE</b>	ACT ABATE	17	Violation Inspection - PS	11/01/2018
Original Complaint: Type: Property Violations - Tall Grass and Weeds						<u>Source: HUB</u>	

Description:  
Tall grass

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190296	09/28/18	10614018900	<b>1921 S LYLE LN</b>	ACT ABATE	17	Violation Inspection - PS	10/26/2018
Original Complaint: wood, imv, acc str, gutters, jtd						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190298	09/28/18	11902026100	<b>2001 S LYLE LN</b>	ACT ABATE	17	Violation Inspection - PS	10/26/2018
Original Complaint:						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190299	09/28/18	11902026200	<b>2005 S LYLE LN</b>	ACT ABATE	17	Violation Inspection - PS	10/26/2018
Original Complaint: jtd						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190300	09/28/18	11902026300	<b>2009 S LYLE LN</b>	ACT ABATE	17	Violation Inspection - PS	10/26/2018
Original Complaint: jtd, imv, pog, gutters						<u>Source: INSPECTOR REPORTED</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190302	09/28/18	11902026400	<b>2013 S LYLE LN</b>	ACT ABATE	17	Violation Inspection - PS	10/26/2018
Original Complaint: wood, imv, pog, jtd						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188946	09/10/18	10416026400	<b>1721 BEECHWOOD AVE</b>	ACT ABATE	18	Violation Inspection - PS	10/25/2018
Original Complaint: Type: Property Violations - Dilapidated Structures						<u>Source: HUB</u>	

Description:  
Fence not built to code.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188947	09/10/18	10416017500	<b>1900 BEECHWOOD AVE</b>	ACT ABATE	18	Violation Inspection - PS	10/25/2018
Original Complaint: Type: Property Violations - Dilapidated Structures						<u>Source: HUB</u>	

Description:  
Fence not built to compliance

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188989	09/11/18	10406031200	<b>520 32ND AVE S</b>	PENDING	18	Violation Inspection - PS	10/02/2018
Original Complaint: Type: Property Violations - Residential Complaint						<u>Source: HUB</u>	

Description:  
House Zoned Single Family Dwelling is again rented as college dorm with multiple unrelated occupants, multiple SUV's, college noise

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189163	09/13/18	10415032100	<b>2510 WESTWOOD AVE</b>	PENDING	18	Env Court 1st Setting - PS	10/24/2018
Original Complaint: HOW TAKEN: Codes Online ADVERTISING and/or OPERATING A SHORT TERM RENTAL PROPERTY WITHOUT A PERMIT						<u>Source: Codes Online</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189193	09/13/18	11708017900	<b>1503 CLAYTON AVE</b>	ACT ABATE	18	Violation Inspection - PS	10/23/2018
Original Complaint: High Grass & Weeds						<u>Source:</u> PHONE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189527	09/17/18	104060V00200CO	<b>3102 B WELLINGTON AVE</b>	ACT ABATE	18	Violation Inspection - PS	10/08/2018
Original Complaint: HOW TAKEN: EMAIL (HOTLINE TIP) PARKING ISSUES. ADVERTISING EXCESS BEDROOMS IN WEBSITE ADVERTISEMENT (BOOKING.COM).						<u>Source:</u> EMAIL	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189609	09/18/18	10415014600	<b>2138 BLAIR BLVD</b>	PENDING	18	Env Court 1st Setting - PS	11/07/2018
Original Complaint: host- no strp permit						<u>Source:</u> EMAIL	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189727	09/19/18	10412023900	<b>1707 ACKLEN AVE</b>	ACT ABATE	18	Violation Inspection - PS	10/25/2018
Original Complaint: Type: Property Violations - Junk and Debris						<u>Source:</u> HUB	

Description:

The landowner of this apartment building has not emptied trash for more than two years-she has placed a green strap to prevent the use of the receptacles which are placed in an area where they cannot be emptied so that her tenants can have parking-I have contacted her multiple times during this time and she now refuses my calls and texts-her tenants recently filled my recycle can with five bags of trash because there is not enough cans (has one small dumpster) to put trash-it is nasty, smelly and attracts rats to our alley-she needs to remedy this trash situation now

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189816	09/21/18	104060A00300CO	<b>3415 WEST END AVE</b>	TRANSFERRD	18		
Original Complaint: HOW TAKEN: PHONE Electrical issues						<u>Source:</u> PHONE	

**Master RFS Detail Report**

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190157	09/26/18	10416014100	<b>1703 ASHWOOD AVE</b>	TRANSFERRD	18		

Original Complaint: Type: Property Violations - Residential Complaint

Source: HUB

Description:

House under renovation and construction. There are no silt fences. Mud and debris from worksite washes down Ashwood Ave into Belmont Blvd at a high volume. Please require builders to install s fences and to clear the alley of nails and other debris.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188548	09/04/18	082050M00100CO	<b>1813 A 3RD AVE N</b>	ACT ABATE	19	Violation Inspection - PS	10/12/2018

Original Complaint: Fence not built to code.

Source: Codes Online

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188610	09/04/18	09305402300	<b>167 ROSA L PARKS BLVD</b>	ACT ABATE	19	Violation Inspection - PS	10/02/2018

Original Complaint: installing roof top deck without permits

Source: PHONE

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188624	09/05/18	082050M00200CO	<b>1813 B 3RD AVE N</b>	ACT ABATE	19	Violation Inspection - PS	10/12/2018

Original Complaint: fence

Source: INSPECTOR REPORTED

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188633	09/05/18	082050N00100CO	<b>1811 A 3RD AVE N</b>	ACT ABATE	19	Violation Inspection - PS	10/12/2018

Original Complaint: fence

Source: INSPECTOR REPORTED

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188635	09/05/18	082050N00200CO	<b>1811 B 3RD AVE N</b>	ACT ABATE	19	Violation Inspection - PS	10/12/2018

Original Complaint: fence

Source: INSPECTOR REPORTED

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188698	09/05/18	08213030000	<b>310 JEFFERSON ST</b>	ACT ABATE	19	Violation Inspection - PS	10/04/2018

Original Complaint: Apt. 215 Ms. Tanya Pollard (906) 282-4742 Condensation from the A/C is causing mold

Source: PHONE

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188759	09/06/18	09413004000	<b>191 LITTLE GREEN ST</b>	PENDING	19	Env Court 1st Setting - PS	10/24/2018
Original Complaint: host- no strp permit						<u>Source:</u> EMAIL	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188779	09/06/18	08116071600	<b>927 JACKSON ST</b>	ACT ABATE	19	Violation Inspection - PS	10/08/2018
Original Complaint: Reported an older vehicle possibly a 1965 Monte Carlo has temporary tags which have expired.						<u>Source:</u> SPE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188781	09/06/18	08116071500	<b>929 JACKSON ST</b>	ACT ABATE	19	Violation Inspection - PS	10/08/2018
Original Complaint: Reported two vehicles parked in rear yard area - half on grass and half on gravel. Reported to be inoperable - owner/tenant is repairing on a daily basis - sometimes on private property and other times in the public right-of-way. Claims both vehicles are inoperable. One vehicle is reported to have a tarp over it.						<u>Source:</u> SPE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188883	09/10/18	08116016400	<b>1401 ARTHUR AVE</b>	ACT ABATE	19	Violation Inspection - PS	09/24/2018
Original Complaint: Type: Property Violations - Tall Grass and Weeds						<u>Source:</u> HUB	

Description:

New home build. Contractor laid "sod" after months of leaving debris piled on the corner. Owner mows his own grass but leaves the common area untouched.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188957	09/10/18	105010M00100CO	<b>101 13TH AVE CIR</b>	PENDING	19	Pre-Court Inspection - PS	10/30/2018
Original Complaint: HOW TAKEN: INSPECTOR REPORTED ADVERTISING EXCESS BEDROOMS AND EXCESS OCCUPANCY ON WEBSITE AD. REPEAT OFFENDER.						<u>Source:</u> INSPECTOR REPORTED	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189068	09/12/18	081160P00200CO	<b>1029 B MONROE ST</b>	ACT ABATE	19	Violation Inspection - PS	10/05/2018

Original Complaint: Type: Property Violations - Junk and Debris Source: HUB

Description:  
Trash and tall grass

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189094	09/12/18	08108027600	<b>1812 5TH AVE N</b>	ACT VEHROW	19	Administrative Hearing Vehicle	10/03/2018

Original Complaint: Type: Public Safety - Abandoned Vehicles Source: HUB

Description:  
This vehicle has been abandoned on 5th Avenue for since the beginning of the year.. The police w called months ago and a green sticker was placed on the vehicle. It's still sitting there with a flat tire and expired temporary tag. Other neighbors have submitted requests to have this vehicle removed. What do we have to do get this vehicle removed? It's an eyesore!

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189116	09/12/18	08112035200	<b>1606 7TH AVE N</b>	ACT ABATE	19	Violation Inspection - PS	10/03/2018

Original Complaint: HOW TAKEN: PHONE Source: PHONE  
(HOTLINE TIP) NUISANCE: NOISE AND TRESPASSING. NO STRP PERMIT NUMBER OR IMAC  
IN WEBSITE AD. ADVERTISING EXCESS BEDROOMS AND EXCESS OCCUPANCY.

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189241	09/13/18	105010W00100CO	<b>1213 A TREMONT ST</b>	PENDING	19	Env Court 1st Setting - PS	10/31/2018

Original Complaint: not owner occupied Source: EMAIL

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189391	09/17/18	09306307300	<b>422 BROADWAY</b>	PENDING	19	Initial Violation Inspection - PS	09/18/2018

Original Complaint: Type: Property Violations - Short Term Rental Complaint  
Source: HUB

Description:  
 3 Bedroom listing that Sleeps 13 over Tootsies. Doesn't appear to have STR permit.  
<https://www.vrbo.com/647166>

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189525	09/17/18	08213036400	<b>900 B LOCKLAYER ST</b>	PENDING	19	Initial Violation Inspection - PS	09/18/2018

Original Complaint: Repeat offender-Still renting property without a permit  
Source: PHONE

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189526	09/17/18	09306108600	<b>421 CHURCH ST</b>	PENDING	19	Env Court 1st Setting - PS	11/07/2018

Original Complaint: host- no strp permit  
Source: EMAIL

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189542	09/18/18	09313031200	<b>1316 HAWKINS ST</b>	ACT VEHROW	19	Prepare Affidavit - PS	09/28/2018

Original Complaint: Type: Public Safety - Abandoned Vehicles  
Source: HUB

Description:  
 Approximately 03 Black Mazda parked for 4 or 5 months without being moved or attended too.  
 Does not belong to any neighbor or anyone in the neighborhood

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189550	09/18/18	10602004300	<b>1100 ELM HILL PIKE</b>	PENDING	19	Initial Violation Inspection - PS	09/19/2018

Original Complaint: Leaks around windows, roof leaking, breaker box constantly going out due to replacing breakers wi wrong size. Tyler Cordell 615-364-2712  
Source: PHONE

**Master RFS Detail Report**

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189564	09/18/18	09216016800	<b>1812 BROADWAY</b>	ACT ABATE	19	Violation Inspection - PS	10/25/2018
Original Complaint: Type: Property Violations - Dilapidated Structures						<u>Source:</u> HUB	

Description:

Insane amount of litter throughout the yard of this empty home/business. Looks terrible in a tourist area of town. Please force owner to clean it up. Graffiti, litter, , weeds, homeless.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189613	09/18/18	09306210500	<b>215 CHURCH ST</b>	ACT ABATE	19	Violation Inspection - PS	10/25/2018
Original Complaint: Excessive trash and garbage dumped around dumpster.						<u>Source:</u> EMAIL	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189619	09/18/18	09208034900	<b>1413 HYNES ST</b>	ACT ABATE	19	Violation Inspection - PS	10/04/2018
Original Complaint: Type: Property Violations - Tall Grass and Weeds						<u>Source:</u> HUB	

Description:

The grass has not been cut the entire summer. It is about chest height now in some areas of the lot. There are people now hiding in the back of the lot and using drugs and drinking. I see people stumbling out of that area almost daily.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189623	09/18/18	08108046300	<b>1723 5TH AVE N</b>	ACT ABATE	19	Violation Inspection - PS	10/05/2018
Original Complaint: Type: Property Violations - Tree Concerns						<u>Source:</u> HUB	

Description:

Owner cut down a large tree several weeks ago and has yet to remove the tree. The branches are making travel through the alley difficult, providing cover for criminals to hide behind, and generally unsightly.

Additional Comments:

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189827	09/21/18	09306200200	<b>174 3RD AVE N</b>	ACT ABATE	19	Violation Inspection - PS	10/01/2018
Original Complaint: HOW TAKEN: INSPECTOR REPORTED INADEQUATE/ABSENT WASTE CONTAINERS						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189828	09/21/18	09306200200	<b>174 3RD AVE N</b>	ACT ABATE	19	Violation Inspection - PS	09/24/2018
Original Complaint: JTD, ILLEGAL DUMPING						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189829	09/21/18	09306203000	<b>212 COMMERCE ST</b>	ACT ABATE	19	Violation Inspection - PS	09/24/2018
Original Complaint: ILLEGAL DUMPING						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189865	09/24/18	08108016000	<b>1802 NASSAU ST</b>	ACT HSGDEM	19	People Update - PS	10/01/2018
Original Complaint: Unsecure vacant house with homeless individuals residing in the house						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189901	09/24/18	08116019900	<b>1013 MONROE ST</b>	ACT ABATE	19	Violation Inspection - PS	10/11/2018
Original Complaint: Type: Property Violations - Tall Grass and Weeds						<u>Source: HUB</u>	

Description:

Abandoned house with 18-24" grass, syringes, broken bottles, meth supplies - front & back yards.  
Broken back door with transients using as a squat house.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189993	09/25/18	08116029400	<b>1015 SCOVEL ST</b>	ACT ABATE	19	Violation Inspection - PS	10/09/2018
Original Complaint: Dorothy Childress. 615-584-7109. HVAC not working.						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190031	09/25/18	081084B02000CO	<b>1813 7TH AVE N</b>	ACT ABATE	19	Violation Inspection - PS	10/01/2018
Original Complaint: vehicle with flat tires; White vehicle						<u>Source: PHONE</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190176	09/27/18	10501057800	<b>1030 14TH AVE S</b>	ACT VEHROW	19	Violation Inspection CAR - PS	10/08/2018

Original Complaint: Type: Public Safety - Abandoned Vehicles Source: HUB

Description:

Seemingly abandoned Dodge pickup truck. Alabama plates expired six months ago. Truck sitting 18-24" from curb, blocking wheelchair ramp.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190233	09/28/18	08108016000	<b>1802 NASSAU ST</b>	ACT VEHROW	19	Violation Inspection CAR - PS	10/01/2018

Original Complaint: AMV Source: INSPECTOR REPORTED

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188937	09/10/18	10204012600	<b>6565 PREMIER DR</b>	ACT ABATE	20	Violation Inspection - PS	10/12/2018

Original Complaint: APT F4 - CASON DESPAIN - 615-587-5126 - HVAC NOT WORKING Source: PHONE

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188974	09/10/18	09111002300	<b>601 MORROW RD</b>	PENDING	20	Env Court 1st Setting - PS	10/31/2018

Original Complaint: operated after appeal filed, but before permit issued Source: EMAIL

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189279	09/14/18	102040B00100CO	<b>6525 MERCOMATIC CT</b>	ACT ABATE	20	Violation Inspection - PS	10/02/2018

Original Complaint: High grass & weeds Source: PHONE

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189280	09/14/18	102040B00200CO	<b>6527 MERCOMATIC CT</b>	ACT ABATE	20	Violation Inspection - PS	10/02/2018

Original Complaint: High grass & weeds Source: PHONE

**Master RFS Detail Report**

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189358	09/14/18	09106010400	<b>5806 CARL PL</b>	ACT ABATE	20	Violation Inspection - PS	10/08/2018
Original Complaint: Type: Property Violations - Tall Grass and Weeds						<u>Source: HUB</u>	

Description:  
The weeds at this house are waist high.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189380	09/17/18	09107006900	<b>1313 53RD AVE N</b>	ACT ABATE	20	Violation Inspection - PS	10/08/2018
Original Complaint: Type: Property Violations - Tall Grass and Weeds						<u>Source: HUB</u>	

Description:  
The home has been vacant for many months. Has weeds 6-7 feet tall throughout and garbage on property

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189574	09/18/18	10204014500	<b>420 WILCLAY DR</b>	ACT ABATE	20	Violation Inspection - PS	10/04/2018
Original Complaint: Junk, trash, and debris						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189625	09/18/18	10207011100	<b>6608 UPTON LN</b>	PENDING	20	Env Court 1st Setting - PS	11/07/2018
Original Complaint: host- no strp permit						<u>Source: EMAIL</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189632	09/19/18	09113008000	<b>505 EASTBORO DR</b>	ACT ABATE	20	Violation Inspection - PS	10/12/2018
Original Complaint: grass, j/t/d, imv						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189774	09/20/18	09113008300	<b>511 EASTBORO DR</b>	ACT ABATE	20	Violation Inspection - PS	10/11/2018
Original Complaint: IMV JTD HG&W						<u>Source: INSPECTOR REPORTED</u>	

**Master RFS Detail Report**

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189775	09/20/18	09106023000	<b>5600 LOUISIANA AVE</b>	ACT ABATE	20	Violation Inspection - PS	10/09/2018
Original Complaint: HG&W						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189808	09/21/18	09109006800	<b>6025 ROBERTSON AVE</b>	ACT ABATE	20	Violation Inspection - PS	10/09/2018
Original Complaint: Type: Property Violations - Tall Grass and Weeds						<u>Source: HUB</u>	

Description:  
The grass is 3-4 feet tall in both the front and back

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189840	09/21/18	091100L90000CO	<b>516 C SNYDER AVE</b>	ACT ABATE	20	Violation Inspection - PS	10/09/2018
Original Complaint: Type: Property Violations - Tall Grass and Weeds						<u>Source: HUB</u>	

Description:  
Very very high grass and weeds at this property for the past 3 months. Nothing is being done. Trash in yard. The house is right next to ours.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189853	09/21/18	09113001000	<b>6346 COLUMBIA AVE</b>	ACT ABATE	20	Violation Inspection - PS	10/11/2018
Original Complaint: parking on grass, j/t/d						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189885	09/24/18	10301014500	<b>6403 CHARLOTTE PIKE</b>	ACT ABATE	20	Violation Inspection - PS	10/15/2018
Original Complaint: building without permits						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189989	09/25/18	09101006800	<b>6100 TERRY DR</b>	ACT ABATE	20	Violation Inspection - PS	10/22/2018
Original Complaint: HOW TAKEN: PHONE Running a business from residence; commercial vehicles on the property						<u>Source: PHONE</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188554	09/04/18	08110034200	<b>1607 23RD AVE N</b>	ACT ABATE	21	Violation Inspection - PS	09/21/2018
Original Complaint: Junk trash and debris						<u>Source:</u> Codes Online	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188602	09/04/18	09209032600	<b>3312 C FELICIA ST</b>	ACT ABATE	21	Pre-Court Inspection - PS	11/13/2018
Original Complaint: grass						<u>Source:</u> INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188603	09/04/18	09209032600	<b>3312 C FELICIA ST</b>	ACT ABATE	21	Violation Inspection - PS	10/04/2018
Original Complaint: exterior						<u>Source:</u> INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188704	09/05/18	09202026100	<b>2618 EDEN ST</b>	ACT ABATE	21	Violation Inspection - PS	10/12/2018
Original Complaint: Junk, trash, and debris in backyard						<u>Source:</u> HUB	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188706	09/05/18	09209010800	<b>3225 INDIANA AVE</b>	ACT ABATE	21	Violation Inspection - PS	10/08/2018
Original Complaint: Abandoned/inoperable white nissan altima w/flat tire; Plate# R4850F						<u>Source:</u> HUB	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188757	09/06/18	09206053300	<b>722 LENA ST</b>	ACT ABATE	21	Violation Inspection - PS	10/08/2018
Original Complaint: Parking on grass, Junk trash and debris.						<u>Source:</u> Codes Online	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188758	09/06/18	09206045900	<b>2514 BATAVIA ST</b>	ACT HSGDEM	21	Administrative Hearing - PS	11/20/2018
Original Complaint: Dilapidated house. House is falling in.						<u>Source:</u> Codes Online	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188823	09/07/18	09206002200	<b>930 30TH AVE N</b>	ACT ABATE	21	Violation Inspection - PS	10/05/2018
Original Complaint: Inoperable vehicles on property. Car parts in yard, Junk trash and debris						<u>Source:</u> Codes Online	

**Master RFS Detail Report**

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188871	09/07/18	09207003200	<b>2129 HERMOSA ST</b>	ACT ABATE	21	Pre-Court Inspection - PS	11/20/2018
Original Complaint: imv on grass, grass						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188873	09/07/18	09206047700	<b>2517 BATAVIA ST</b>	ACT ABATE	21	Violation Inspection - PS	10/08/2018
Original Complaint: gutters, grass, junk						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189002	09/11/18	081070S00100CO	<b>1823 A 16TH AVE N</b>	ACT ABATE	21	Violation Inspection - PS	10/09/2018
Original Complaint: IMV						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189003	09/11/18	081070R00200CO	<b>1825 B 16TH AVE N</b>	ACT ABATE	21	Violation Inspection - PS	10/09/2018
Original Complaint: IMV						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189014	09/11/18	08107049400	<b>1919 9TH AVE N</b>	ACT ABATE	21	Pre-Court Inspection - PS	11/06/2018
Original Complaint: Junk, trash & debris; cut tree trunks on this property						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189016	09/11/18	08107024100	<b>1922 16TH AVE N</b>	ACT ABATE	21	Violation Inspection - PS	09/25/2018
Original Complaint: Type: Property Violations - Tall Grass and Weeds						<u>Source: HUB</u>	

Description:  
 THE BACKYARD OF THIS PROPERTY IS A TOTAL MESS OVERGROWN TREES, WEEDS, BRUSH, LITTER AND MORE. THEY ONLY CUT THE FRONT THE PART YOU CAN SEE

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189035	09/11/18	09206050800	<b>718 28TH AVE N</b>	ACT ABATE	21	Violation Inspection - PS	10/03/2018
Original Complaint: working on vehicles out the yard and on side of the road.						<u>Source: PHONE</u>	

**Master RFS Detail Report**

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189049	09/11/18	08107053700	<b>1833 10TH AVE N</b>	ACT ABATE	21	Violation Inspection - PS	10/16/2018
Original Complaint: IMV/PARKING/DEBRIS						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189050	09/11/18	08108011200	<b>1813 DELTA AVE</b>	ACT ABATE	21	Violation Inspection - PS	09/26/2018
Original Complaint: TRASH						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189071	09/12/18	09210013200	<b>2816 GEORGIA AVE</b>	ACT ABATE	21	Violation Inspection - PS	10/04/2018
Original Complaint: Junk, trash & debris						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189188	09/13/18	08115006900	<b>1516 22ND AVE N</b>	ACT ABATE	21	Violation Inspection - PS	10/12/2018
Original Complaint: High grass & weeds						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189208	09/13/18	09112023800	<b>600 41ST AVE N</b>	ACT ABATE	21	Violation Inspection - PS	10/02/2018
Original Complaint: Type: Property Violations - Junk and Debris						<u>Source: HUB</u>	

Description:  
Tenant evicted. Junk trash and debris on property.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189325	09/14/18	08111017900	<b>1711 17TH AVE N</b>	ACT ABATE	21	Violation Inspection - PS	10/05/2018
Original Complaint: Type: Property Violations - Dilapidated Structures						<u>Source: HUB</u>	

Description:  
Cracked Exposed Sewer Line. Sewage in yard and running into neighboring yard.

Additional Comments:

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189369	09/17/18	09206063200	<b>2428 BATAVIA ST</b>	ACT ABATE	21	Violation Inspection - PS	10/18/2018
Original Complaint: grass, dilapidated						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189446	09/17/18	09206035700	<b>730 29TH AVE N</b>	ACT ABATE	21	Violation Inspection - PS	10/08/2018
Original Complaint: Type: Property Violations - Junk and Debris						<u>Source: HUB</u>	

Description:  
Trash debris smell back yardlnjh

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189480	09/17/18	09209028800	<b>0 DELAWARE AVE</b>	ACT ABATE	21	Violation Inspection - PS	10/05/2018
Original Complaint: HGW, JTD						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189481	09/17/18	09209028700	<b>3311 DELAWARE AVE</b>	ACT ABATE	21	Violation Inspection - PS	10/05/2018
Original Complaint: HGW, JTD						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189482	09/17/18	09209028600	<b>3309 DELAWARE AVE</b>	ACT ABATE	21	Violation Inspection - PS	10/05/2018
Original Complaint: HGW, JTD						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189483	09/17/18	09209028502	<b>3307 DELAWARE AVE</b>	ACT ABATE	21	Violation Inspection - PS	10/05/2018
Original Complaint: JTD, HGW						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189484	09/17/18	09209028500	<b>0 DELAWARE AVE</b>	ACT ABATE	21	Violation Inspection - PS	10/05/2018
Original Complaint: JTD, HGW						<u>Source: INSPECTOR REPORTED</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189485	09/17/18	09209028501	<b>3303 DELAWARE AVE</b>	ACT ABATE	21	Violation Inspection - PS	10/05/2018
Original Complaint: JTD, HGW						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189487	09/17/18	09209028400	<b>0 DELAWARE AVE</b>	ACT ABATE	21	Violation Inspection - PS	10/05/2018
Original Complaint: HGW, JTD						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189488	09/17/18	09209028900	<b>619 33RD AVE N</b>	ACT ABATE	21	Violation Inspection - PS	10/05/2018
Original Complaint: HGW, JTD						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189489	09/17/18	09209029000	<b>617 33RD AVE N</b>	ACT ABATE	21	Violation Inspection - PS	10/05/2018
Original Complaint: HGW, JTD						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189490	09/17/18	09209029100	<b>613 33RD AVE N</b>	ACT ABATE	21	Violation Inspection - PS	10/05/2018
Original Complaint: HGW, JTD						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189492	09/17/18	09209029200	<b>611 33RD AVE N</b>	ACT ABATE	21	Violation Inspection - PS	10/05/2018
Original Complaint: JTD, HGW						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189493	09/17/18	09209029300	<b>609 B 33RD AVE N</b>	ACT ABATE	21	Violation Inspection - PS	10/05/2018
Original Complaint: HGW, JTD						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189495	09/17/18	09209038600	<b>3301 TREVOR ST</b>	ACT ABATE	21	Violation Inspection - PS	10/05/2018
Original Complaint: JTD, HGW						<u>Source: INSPECTOR REPORTED</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189496	09/17/18	09209028100	<b>3307 TREVOR ST</b>	ACT ABATE	21	Violation Inspection - PS	10/05/2018
Original Complaint: HGW, JTD						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189497	09/17/18	09209028000	<b>3309 TREVOR ST</b>	ACT ABATE	21	Violation Inspection - PS	10/05/2018
Original Complaint: JTD, HGW						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189498	09/17/18	09209027900	<b>3311 TREVOR ST</b>	ACT ABATE	21	Violation Inspection - PS	10/05/2018
Original Complaint: JTD, HGW						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189499	09/17/18	09209027800	<b>3313 TREVOR ST</b>	ACT ABATE	21	Violation Inspection - PS	10/05/2018
Original Complaint: HGW, JTD						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189501	09/17/18	09209027700	<b>3315 TREVOR ST</b>	ACT ABATE	21	Violation Inspection - PS	10/05/2018
Original Complaint: HGW, JTD						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189502	09/17/18	09209027600	<b>3317 TREVOR ST</b>	ACT ABATE	21	Violation Inspection - PS	10/05/2018
Original Complaint: JTD, HGW						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189505	09/17/18	09209028700	<b>3311 DELAWARE AVE</b>	ACT ABATE	21	Violation Inspection - PS	09/28/2018
Original Complaint: BOARDING OF VACANT BUILDING						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189507	09/17/18	09209028502	<b>3307 DELAWARE AVE</b>	ACT ABATE	21	Violation Inspection - PS	09/28/2018
Original Complaint: BOARDING OF VACANT BUILDING						<u>Source: INSPECTOR REPORTED</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189508	09/17/18	09209028501	<b>3303 DELAWARE AVE</b>	ACT ABATE	21	Violation Inspection - PS	09/28/2018
Original Complaint: BOARDING OF VACANT BUILDING						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189510	09/17/18	09209027800	<b>3313 TREVOR ST</b>	ACT ABATE	21	Violation Inspection - PS	09/28/2018
Original Complaint: BOARDING OF VACANT BUILDING						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189511	09/17/18	09209027600	<b>3317 TREVOR ST</b>	ACT ABATE	21	Violation Inspection - PS	09/28/2018
Original Complaint: BOARDING OF VACANT BUILDING						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189522	09/17/18	08110011900	<b>2501 A SANTI AVE</b>	ACT ABATE	21	Violation Inspection - PS	10/12/2018
Original Complaint: Dumping junk, trash, and debris in the alleyway; inoperable vehicles						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189536	09/18/18	081150C00400CO	<b>1511 A 21ST AVE N</b>	ACT ABATE	21	Abate Notice Generated - PS	09/18/2018
Original Complaint: trash						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189537	09/18/18	08111024800	<b>1710 17TH AVE N</b>	ACT ABATE	21	Violation Inspection - PS	10/15/2018
Original Complaint: IMV/PKING/GRASS/DEBRIS						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189569	09/18/18	09210012900	<b>2822 GEORGIA AVE</b>	ACT ABATE	21	Violation Inspection - PS	10/04/2018
Original Complaint: high grass weeds						<u>Source: PHONE</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189655	09/19/18	08106021200	<b>1906 SALEM MASON DR</b>	ACT ABATE	21	Violation Inspection - PS	10/05/2018
Original Complaint: Type: Property Violations - Tall Grass and Weeds						<u>Source</u> : HUB	

Description:  
Yard very overgrown. House seems abandoned.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189776	09/20/18	08112001800	<b>1704 10TH AVE N</b>	ACT ABATE	21	Violation Inspection - PS	10/11/2018
Original Complaint: high grass weeds						<u>Source</u> : PHONE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189871	09/24/18	08107049000	<b>1922 10TH AVE N</b>	ACT ABATE	21	Violation Inspection - PS	10/26/2018
Original Complaint: Type: Property Violations - Tall Grass and Weeds						<u>Source</u> : HUB	

Description:  
Property has abandoned cars with no license plats, grass overgrown and tree also has overgrown bushes with tree lambs on power lines

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189923	09/24/18	09202016300	<b>2711 MEHARRY BLVD</b>	ACT ABATE	21	Violation Inspection - PS	10/25/2018
Original Complaint: Inoperable vehicle with missing wheels						<u>Source</u> : PHONE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189924	09/24/18	09202016200	<b>2709 MEHARRY BLVD</b>	ACT ABATE	21	Violation Inspection - PS	10/25/2018
Original Complaint: Inoperable vehicle in the driveway						<u>Source</u> : PHONE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190002	09/25/18	08111051000	<b>1622 14TH AVE N</b>	ACT ABATE	21	Violation Inspection - PS	10/26/2018
Original Complaint: HOW TAKEN: PHONE						<u>Source</u> : PHONE	

Junk, trash, and debris; raw sewage coming from a busted sewer line in the rear of the house

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190017	09/25/18	09207021300	<b>2402 BOOKER ST</b>	ACT ABATE	21	Violation Inspection - PS	10/11/2018
Original Complaint: High grass/weeds						<u>Source: WALK IN</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190042	09/25/18	09206043700	<b>810 LENA ST</b>	ACT ABATE	21	Violation Inspection - PS	10/11/2018
Original Complaint: tall grass						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190043	09/25/18	09206043600	<b>812 LENA ST</b>	ACT ABATE	21	Violation Inspection - PS	10/11/2018
Original Complaint: tall grass						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190058	09/25/18	08110027800	<b>1720 23RD AVE N</b>	ACT ABATE	21	Violation Inspection - PS	10/09/2018
Original Complaint: Type: Property Violations - Junk and Debris						<u>Source: HUB</u>	

Description:

A shopping cart and mattress have been sitting behind the house in the alley for a while now.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190061	09/25/18	08110028600	<b>2208 OSAGE ST</b>	ACT ABATE	21	Violation Inspection - PS	10/11/2018
Original Complaint: Type: Property Violations - Junk and Debris						<u>Source: HUB</u>	

Description:

Reclining sofa dumped in alley behind house. Difficult to drive around.

Additional Comments:

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190099	09/26/18	08115047200	<b>1818 B SCOVEL ST</b>	ACT ABATE	21	Violation Inspection - PS	10/09/2018
Original Complaint: Type: Property Violations - Junk and Debris						<u>Source:</u> HUB	

Description:  
Junk and furniture

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190101	09/26/18	09206062900	<b>2434 BATAVIA ST</b>	ACT ABATE	21	Violation Inspection - PS	10/18/2018
Original Complaint: Type: Property Violations - Cars Parked On Lawn						<u>Source:</u> HUB	

Description:  
Many cars are parked on the lawns on this corner and across the street. Pictures attached.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190131	09/26/18	08111059800	<b>1604 WHELESS ST</b>	ACT ABATE	21	Violation Inspection - PS	10/09/2018
Original Complaint: High grass & weeds						<u>Source:</u> PHONE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190141	09/26/18	08116002000	<b>1405 14TH AVE N</b>	ACT ABATE	21	Violation Inspection - PS	10/11/2018
Original Complaint: HOW TAKEN: INSPECTOR REPORTED JTD						<u>Source:</u> INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190147	09/26/18	08116002100	<b>1407 14TH AVE N</b>	ACT ABATE	21	Violation Inspection - PS	10/11/2018
Original Complaint: HOW TAKEN: INSPECTOR REPORTED JTD						<u>Source:</u> INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190152	09/26/18	08115062900	<b>1408 16TH AVE N</b>	ACT ABATE	21	Violation Inspection - PS	10/11/2018
Original Complaint: HOW TAKEN: INSPECTOR REPORTED JTD						<u>Source:</u> INSPECTOR REPORTED	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190154	09/26/18	08116002400	<b>1501 14TH AVE N</b>	ACT ABATE	21	Violation Inspection - PS	10/11/2018
Original Complaint: HOW TAKEN: INSPECTOR REPORTED JTD						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190230	09/28/18	08100003100	<b>2600 W HEIMAN ST</b>	ACT ABATE	21	Violation Inspection - PS	10/29/2018
Original Complaint: plumbing						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190235	09/28/18	08111051000	<b>1622 14TH AVE N</b>	ACT VEHROW	21	Violation Inspection CAR - PS	10/01/2018
Original Complaint: AMV						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190259	09/28/18	08110020000	<b>1729 24TH AVE N</b>	PENDING	21	Initial Violation Inspection - PS	09/29/2018
Original Complaint: Illegal use - unpermitted boarding house - reported to have no running water and other utilities are suspect.						<u>Source: EMAIL</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190263	09/28/18	08115047000	<b>1820 SCOVEL ST</b>	ACT ABATE	21	Violation Inspection - PS	10/12/2018
Original Complaint: TRASH AT ALLEY						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190264	09/28/18	08110028800	<b>1743 22ND AVE N</b>	ACT ABATE	21	Violation Inspection - PS	10/12/2018
Original Complaint: TRASH AT ALLEY						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190265	09/28/18	08111001600	<b>1733 22ND AVE N</b>	ACT ABATE	21	Violation Inspection - PS	10/12/2018
Original Complaint: GRASS TRASH AT REAR						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190269	09/28/18	08106046500	<b>1721 ST LOUIS ST</b>	ACT HSGDEM	21	PS - Supervisor Review	09/29/2018
Original Complaint: DELAPIDATED STRUCTURE						<u>Source: INSPECTOR REPORTED</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190270	09/28/18	08106046400	<b>1723 ST LOUIS ST</b>	ACT HSGDEM	21	PS - Supervisor Review	09/29/2018
Original Complaint: DELAPIDATED STRUCTURE						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190279	09/28/18	081073B00200CO	<b>1912 B 16TH AVE N</b>	ACT ABATE	21	Violation Inspection - PS	10/26/2018
Original Complaint: no strp permit						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190303	09/28/18	09202037000	<b>2423 MEHARRY BLVD</b>	ACT ABATE	21	Violation Inspection - PS	10/16/2018
Original Complaint: j/t/d						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190304	09/28/18	09202037100	<b>2421 MEHARRY BLVD</b>	ACT ABATE	21	Violation Inspection - PS	10/16/2018
Original Complaint: j/t/d						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190305	09/28/18	09202038000	<b>2408 ALAMEDA ST</b>	ACT ABATE	21	Violation Inspection - PS	10/16/2018
Original Complaint: grass						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190306	09/28/18	09202044100	<b>2411 ALBION ST</b>	ACT ABATE	21	Violation Inspection - PS	10/29/2018
Original Complaint: imv/j/d/exterior						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188935	09/10/18	11400008700	<b>7661 CHARLOTTE PIKE</b>	ACT ABATE	22	Env Court 1st Setting - PS	11/07/2018
Original Complaint: HOW TAKEN: EMAIL ADVERTISING EXCESS BEDROOMS, AND EXCESS OCCUPANCY. PERMIT NUMBER IS NOT ACCURATE. (VRBO AD)						<u>Source: EMAIL</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189072	09/12/18	14210000400	<b>616 BELLEVUE RD N</b>	ACT ABATE	22	Env Court 1st Setting - PS	11/28/2018
Original Complaint: trailer at strp						<u>Source: EMAIL</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189306	09/14/18	12700005600	<b>8250 HIGHWAY 70 S</b>	ACT ABATE	22	Violation Inspection - PS	10/16/2018
Original Complaint: Abandoned vehicle (Black Honda) with no tags						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189370	09/17/18	142060C03900CO	<b>834 WILLIAMSBURG WEST DR</b>	ACT ABATE	22	Violation Inspection - PS	10/18/2018
Original Complaint: Multiple inoperable vehicles						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189371	09/17/18	142060C00700CO	<b>732 ALBAR DR</b>	ACT ABATE	22	Violation Inspection - PS	10/18/2018
Original Complaint: Multiple inoperable vehicles						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189626	09/18/18	12810013300	<b>102 COLT CT</b>	ACT ABATE	22	Violation Inspection - PS	10/09/2018
Original Complaint: high grass weeds						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189720	09/19/18	10213000400	<b>7115 CHARLOTTE PIKE</b>	ACT ABATE	22	Violation Inspection - PS	10/08/2018
Original Complaint: Type: Property Violations - Tall Grass and Weeds						<u>Source: HUB</u>	

Description:  
Grass over 12 inches tall. Please cut thank you.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189817	09/21/18	128160B07200CO	<b>548 SUMMIT OAKS CT</b>	ACT ABATE	22	Violation Inspection - PS	10/15/2018
Original Complaint: Renovated the basement of home into an in-law suite						<u>Source: PHONE</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189956	09/24/18	14200006700	<b>7385 OLD HARDING PIKE</b>	ACT ABATE	22	Violation Inspection - PS	10/25/2018
Original Complaint: use not permitted						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190205	09/27/18	14214005300	<b>554 BELLEVUE RD N</b>	ACT ABATE	22	Violation Inspection - PS	10/18/2018
Original Complaint: imvs						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190256	09/28/18	114140A07000CO	<b>232 DEER PT</b>	ACT VEHROW	22	Violation Inspection CAR - PS	10/11/2018
Original Complaint: Type: Public Safety - Abandoned Vehicles						<u>Source: HUB</u>	

Description:

The tenant of the house (232 Deer Pt. TN 37209) has parked their broken car (Plate# SJ6030) on the street for months; and double parking (5 cars) on the street. it cause issue when the garbage pick truck, school bus, USPS/Fedex trucks to maneuver on the cul-de-sac.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188596	09/04/18	10214010300	<b>1104 SHILOH DR</b>	PENDING	23	Env Court 1st Setting - PS	10/17/2018
Original Complaint: host- no str						<u>Source: EMAIL</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188713	09/05/18	10214011200	<b>941 BRESSLYN RD</b>	ACT ABATE	23	Pre-Court Inspection - PS	11/20/2018
Original Complaint: High grass/weeds						<u>Source: HUB</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189629	09/18/18	142040A90000CO	<b>214 OLD HICKORY BLVD</b>	TRANSFERRD	23		
Original Complaint: Units 79, 80, 81, 82-no access to water meter due to covering of dirt and gravel.						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188710	09/05/18	10409009100	<b>3604 RICHLAND AVE</b>	ACT VEHROW	24	Administrative Hearing Vehicle	10/03/2018
Original Complaint: Inoperable SAAB vehicle in front of house						<u>Source: HUB</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188845	09/07/18	09116034500	<b>4003 NEVADA AVE</b>	ACT ABATE	24	Violation Inspection - PS	10/11/2018
Original Complaint: Dilapidated house, Dilapidated hot tub in back yard						<u>Source: HUB</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188925	09/10/18	10306002800	<b>5538 OAKMONT CIR</b>	ACT ABATE	24	Violation Inspection - PS	10/15/2018
Original Complaint: HOW TAKEN: HUB Backyard structure is in disrepair and has been for years.						<u>Source: HUB</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189187	09/13/18	10401038500	<b>411 ACKLEN PARK DR</b>	ACT ABATE	24	Violation Inspection - PS	10/02/2018
Original Complaint: Type: Property Violations - Tall Grass and Weeds						<u>Source: HUB</u>	
Description: Can you check 411 Acklen Park Dr for high grass please							
Additional Comments:							

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189338	09/14/18	104090E00600CO	<b>3520 WEST END AVE</b>	PENDING	24	Env Court 1st Setting - PS	11/07/2018
Original Complaint: host- no strp permit						<u>Source: EMAIL</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189597	09/18/18	10401024600	<b>3600 NEBRASKA AVE</b>	ACT ABATE	24	Violation Inspection - PS	10/04/2018
Original Complaint: tall grass, Pub works has been notified, still nothing being corrected. Is there a way we can try to find owners to contacted, abandoned for over 5 years, neighbors are getting frustrated						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189599	09/18/18	10401024600	<b>3600 NEBRASKA AVE</b>	ACT ABATE	24	Violation Inspection - PS	10/04/2018
Original Complaint: furniture in the yard						<u>Source: PHONE</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189634	09/19/18	09115037100	<b>4701 DAKOTA AVE</b>	ACT ABATE	24	Violation Inspection - PS	10/05/2018

Original Complaint: Type: Property Violations - Tall Grass and Weeds  
Source: HUB

Description:

A developer bought this property, demolished the house and has not been back. The grass and weeds are overgrown and are an eyesore.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189751	09/20/18	09213026200	<b>278 38TH AVE N</b>	ACT ABATE	24	Violation Inspection - PS	10/22/2018

Original Complaint: dilapidated house; junk trash debris  
Source: PHONE

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189752	09/20/18	09213026200	<b>278 38TH AVE N</b>	ACT ABATE	24	Violation Inspection - PS	10/05/2018

Original Complaint: high grass weeds  
Source: PHONE

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189822	09/21/18	09213017500	<b>3315 PARK AVE</b>	ACT ABATE	24	Violation Inspection - PS	10/11/2018

Original Complaint: Type: Property Violations - Tall Grass and Weeds  
Source: HUB

Description:

Caller states the grass is over 3 FT tall and its causing snakes and rats .

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189944	09/24/18	10315003700	<b>4141 WOODLAWN DR</b>	ACT ABATE	24	Violation Inspection - PS	10/16/2018

Original Complaint: HOW TAKEN: EMAIL  
(HOTLINE TIP) NO STRP PERMIT NUMBER OR IMAGE IN THE WEBSITE ADVERTISEMENT.  
Source: EMAIL

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189958	09/24/18	10315003700	<b>4141 WOODLAWN DR</b>	ACT ABATE	24	Violation Inspection - PS	10/16/2018

Original Complaint: HOW TAKEN: EMAIL  
(HOTLINE TIP) NO STRP PERMIT NUMBER OR IMAGE IN THE WEBSITE ADVERTISEMENT.  
Source: EMAIL

**Master RFS Detail Report**

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190029	09/25/18	10315003700	<b>4141 WOODLAWN DR</b>	ACT ABATE	24	Violation Inspection - PS	10/16/2018
Original Complaint: HOW TAKEN: EMAIL						<u>Source:</u> EMAIL	
(HOTLINE TIP) (1)ADVERTISING EXCESS OCCUPANCY. PERMITTED FOR 8 OCCUPANTS,							
(2)ADVERTISING FOR 10 IN 2 OF 3 ADS. NO PERMIT NUMBER OR IMAGE IN 2 OF 3 ADS.							

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190033	09/25/18	10315003700	<b>4141 WOODLAWN DR</b>	ACT ABATE	24	Violation Inspection - PS	10/17/2018
Original Complaint: HOW TAKEN: EMAIL						<u>Source:</u> EMAIL	
(HOLINE TIP) (1) ADVERTISING EXCESS OCCUPANCY. PERMITTED FOR 8 OCCUPANTS,							
AVERTISING 10 IN 1 OF 2 ADS. (2)NO STRP PERMIT NUMBER OR IMAGE IN 1 OF 2 ADS.							

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190094	09/26/18	09116024600	<b>4209 NEVADA AVE</b>	ACT ABATE	24	Violation Inspection - PS	10/26/2018
Original Complaint: Type: Property Violations - Residential Complaint						<u>Source:</u> HUB	
Description:							
Inoperable vehicles on property. 2 vehicles.							
Additional Comments:							

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188720	09/05/18	11707004500	<b>2005 LOMBARDY AVE</b>	ACT ABATE	25	Violation Inspection - PS	11/01/2018
Original Complaint: HOW TAKEN: HUB						<u>Source:</u> HUB	
Overcrowding-being leased to more than 3 college students; they are constantly having loud parties from home							

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189218	09/13/18	13102007100	<b>1936 KIMBARK DR</b>	ACT ABATE	25	Violation Inspection - PS	10/30/2018
Original Complaint: Type: Property Violations - Junk and Debris						<u>Source:</u> HUB	
Description:							
Console Television has been sitting next to the road for the last month. No effort to remove it.							
Additional Comments:							

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189882	09/24/18	13103021500	<b>1611 SHACKLEFORD RD</b>	ACT ABATE	25	Violation Inspection - PS	10/26/2018
Original Complaint: High grass - dilapidated structure - trash in yard.						<u>Source: Metro PD</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189912	09/24/18	11813007500	<b>951 GRAYBAR LN</b>	ACT ABATE	25	Violation Inspection - PS	10/15/2018
Original Complaint: HOW TAKEN: INSPECTOR REPORTED ADVERTISING EXCESS BEDROOMS. PERMITTED FOR TWO, ADVERTISING THREE.						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189933	09/24/18	13107003000	<b>4504 SHYS HILL RD</b>	ACT ABATE	25	Violation Inspection - PS	10/26/2018
Original Complaint: Type: Property Violations - Noise Violations						<u>Source: HUB</u>	

Description:

They are manufacturing something in their garage. The neighborhood has been subjected to the sawing/sanding/riveting etc. for months. this isn't home improvement. There are multiple work truck in the driveway, many parked overnight. The delivery of supplies, UPS, Penske, Southern Freight i practically daily. Is there anything you can do to stop the noise?

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188506	09/04/18	14604005000	<b>4714 TROUSDALE DR</b>	PENDING	26	Env Court 1st Setting - PS	10/17/2018
Original Complaint: host- no strp permit						<u>Source: EMAIL</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188520	09/04/18	147020B11200CO	<b>550 HARDING PL</b>	ACT ABATE	26	Violation Inspection - PS	10/05/2018
Original Complaint: plumbing leak going down into other units						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188872	09/07/18	147020B90000CO	<b>550 HARDING PL</b>	ACT ABATE	26	Violation Inspection - PS	10/05/2018
Original Complaint: trash around dumpster at A building						<u>Source: PHONE</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188874	09/07/18	147020B90000CO	<b>550 HARDING PL</b>	ACT ABATE	26	Violation Inspection - PS	09/25/2018
Original Complaint: sewage on ground between B110 & C109						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188928	09/10/18	13300008400	<b>365 PARAGON MILLS RD</b>	ACT ABATE	26	Violation Inspection - PS	10/12/2018
Original Complaint: Type: Property Violations - Residential Complaint						<u>Source: HUB</u>	

Description:  
Having a yard sale every weekend

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188972	09/10/18	16003000600	<b>5411 ANCHORAGE DR</b>	ACT ABATE	26	Violation Inspection - PS	10/26/2018
Original Complaint: Inoperable vehicle in the backyard						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188994	09/11/18	147020B90000CO	<b>550 HARDING PL</b>	ACT ABATE	26	Violation Inspection - PS	10/15/2018
Original Complaint: potholes in the parking lot						<u>Source: HUB</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189000	09/11/18	13312017800	<b>417 DAWN DR</b>	ACT ABATE	26	Violation Inspection - PS	09/25/2018
Original Complaint: junk and debris						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189067	09/12/18	13315007700	<b>361 ELYSIAN FIELDS RD</b>	ACT ABATE	26	Violation Inspection - PS	10/11/2018
Original Complaint: Type: Property Violations - Tall Grass and Weeds						<u>Source: HUB</u>	

Description:  
property behind this address needs cut make sure they dont spray people got sick

Additional Comments:

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189077	09/12/18	13316012300	<b>295 PENFIELD DR</b>	ACT ABATE	26	Violation Inspection - PS	10/26/2018

Original Complaint: Type: Property Violations - Cars Parked On Lawn Source: HUB

Description:

There is an orange SUV that has been parked on the lawn for several months (never driven)

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189207	09/13/18	14607006100	<b>605 FARRELL PKWY</b>	ACT ABATE	26	Violation Inspection - PS	10/08/2018

Original Complaint: Type: Property Violations - Illegal Sign on Private Property Source: HUB

Description:

This banner sign has been in the resident's yard for over 6 months. It is a hateful sign and promote hatred towards Jews. The website they are promoting with this sign says that Jews have killed thousands of Palestinian children. We would like this sign removed. It is offensive and anti-Semitic.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189378	09/17/18	13308012200	<b>481 CATHY JO CIR</b>	ACT ABATE	26	Violation Inspection - PS	10/08/2018

Original Complaint: Type: Property Violations - Tall Grass and Weeds Source: HUB

Description:

The yard hasn't been mowed since before the house was purchased a month ago.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189420	09/17/18	133110A90000CO	<b>500 B PARAGON MILLS RD</b>	ACT ABATE	26	Violation Inspection - PS	10/26/2018

Original Complaint: Junk, trash, and debris next to the Canterbury Condos. Source: HUB

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189540	09/18/18	14706020200	<b>5005 EDMONDSON PIKE</b>	ACT ABATE	26	Violation Inspection - PS	10/26/2018
Original Complaint: Type: Property Violations - Junk and Debris						<u>Source: HUB</u>	

Description:  
lots of trash, trailers, junk and cars

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189541	09/18/18	14706020300	<b>5009 EDMONDSON PIKE</b>	ACT ABATE	26	Violation Inspection - PS	10/19/2018
Original Complaint: Type: Property Violations - Junk and Debris						<u>Source: HUB</u>	

Description:  
junk along side of the unit

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189697	09/19/18	13311004600	<b>3824 SAM BONEY DR</b>	ACT ABATE	26	Violation Inspection - PS	10/09/2018
Original Complaint: High grass/weeds						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189698	09/19/18	13315003300	<b>3850 SAM BONEY DR</b>	ACT ABATE	26	Violation Inspection - PS	10/09/2018
Original Complaint: High grass/weeds						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189769	09/20/18	13312003100	<b>434 BENITA DR</b>	ACT ABATE	26	Violation Inspection - PS	10/08/2018
Original Complaint: High grass/weeds						<u>Source: PHONE</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189787	09/20/18	14701005600	<b>652 HARDING PL</b>	ACT ABATE	26	Violation Inspection - PS	10/08/2018

Original Complaint: Type: Property Violations - Tall Grass and Weeds  
Source: HUB

Description:  
 Lawn overgrown. Very tall grass.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189804	09/21/18	13413009400	<b>4814 JEFFERY DR</b>	PENDING	26	Initial Violation Inspection - PS	09/22/2018

Original Complaint: HOW TAKEN: PHONE  
Source: PHONE  
 Commercial vehicle parked in a residential area; parking in the grass - Night Inspection Requested

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189898	09/24/18	13314007800	<b>455 ELYSIAN FIELDS RD</b>	ACT ABATE	26	Violation Inspection - PS	10/26/2018

Original Complaint: flag banners on ROW  
Source: PHONE

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190127	09/26/18	14608014000	<b>410 FIELDCREST DR</b>	PENDING	26	Initial Violation Inspection - PS	09/27/2018

Original Complaint: Junk, trash & debris  
Source: PHONE

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190274	09/28/18	133150B00100CO	<b>393 ELYSIAN FIELDS CT</b>	PENDING	26	Initial Violation Inspection - PS	09/29/2018

Original Complaint: Junk, trash, and debris scattered all over the parking lot  
Source: PHONE

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190283	09/28/18	133110A05800CO	<b>500 PARAGON MILLS RD</b>	PENDING	26	Initial Violation Inspection - PS	09/29/2018

Original Complaint: Type: Property Violations - Junk and Debris  
Source: HUB

Description:  
 This is the same place trash and debri was picked up last we-need cameras and more lights in this area this keeps happening

Additional Comments:

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188528	09/04/18	16108000900	<b>412 BREWER DR</b>	ACT ABATE	27	Violation Inspection - PS	09/25/2018
Original Complaint: Grass						<u>Source: Codes Online</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188700	09/05/18	14707024100	<b>4409 J J WATSON AVE</b>	ACT ABATE	27	Violation Inspection - PS	09/25/2018
Original Complaint: High grass/weeds						<u>Source: HUB</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188828	09/07/18	16209001100	<b>512 CEDAR DR</b>	ACT VEHROW	27	Administrative Hearing Vehicle	10/03/2018
Original Complaint: IMV on ROW Near 514 Cedar						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188829	09/07/18	16209001100	<b>512 CEDAR DR</b>	ACT ABATE	27	Violation Inspection - PS	10/08/2018
Original Complaint: Imv in driveway of 514 Cedar Dr						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188832	09/07/18	161100A12100CO	<b>5333 HUNTERS RDG</b>	ACT ABATE	27	Violation Inspection - PS	10/12/2018
Original Complaint: HOW TAKEN: INSPECTOR REPORTED IMV Blk Jeep no tags						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188921	09/10/18	16108000800	<b>414 BREWER DR</b>	ACT ABATE	27	Violation Inspection - PS	09/25/2018
Original Complaint: HIGH GRASS WEED						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189100	09/12/18	16100013400	<b>5646 AMALIE DR</b>	PENDING	27	Violation Inspection - PS	09/20/2018
Original Complaint: Type: Property Violations - Dilapidated Structures						<u>Source: HUB</u>	

Description:  
Steven Golda 951-264-8748. Water damage in walls. Walls are soaked in water.

Additional Comments:

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189130	09/13/18	16106006100	<b>654 HUNTINGTON PKWY</b>	ACT ABATE	27	Violation Inspection - PS	10/11/2018
Original Complaint: Type: Property Violations - Cars Parked On Lawn						<u>Source:</u> HUB	

Description:  
Car parked in front yard close to street and car parked in front yard close to house.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189257	09/14/18	16205005000	<b>359 OCALA DR</b>	ACT ABATE	27	Violation Inspection - PS	09/28/2018
Original Complaint: IMV'S POG						<u>Source:</u> INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189823	09/21/18	14714015000	<b>589 HILL CREEK DR</b>	ACT ABATE	27	Violation Inspection - PS	10/18/2018
Original Complaint: Type: Property Violations - Tall Grass and Weeds						<u>Source:</u> HUB	

Description:  
Please mow

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189826	09/21/18	14714014800	<b>593 HILL CREEK DR</b>	ACT ABATE	27	Violation Inspection - PS	10/18/2018
Original Complaint: Type: Property Violations - Tall Grass and Weeds						<u>Source:</u> HUB	

Description:  
Mow please

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190012	09/25/18	16205024200	<b>328 OCALA DR</b>	PENDING	27	Initial Violation Neighborhood	09/26/2018
Original Complaint: Junk trash and debris behind house.						<u>Source:</u> NEIGHBORHOOD NOTIFICATION	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190013	09/25/18	16205014100	<b>313 ASH GROVE DR</b>	PENDING	27	Initial Violation Neighborhood	09/26/2018
Original Complaint: Parking in grass						<u>Source: NEIGHBORHOOD NOTIFICATION</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190014	09/25/18	16205015300	<b>340 ASH GROVE DR</b>	PENDING	27	Initial Violation Neighborhood	09/26/2018
Original Complaint: Junk trash and debris						<u>Source: NEIGHBORHOOD NOTIFICATION</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190015	09/25/18	16108004900	<b>374 BREWER DR</b>	PENDING	27	Initial Violation Neighborhood	09/26/2018
Original Complaint: High grass/weeds						<u>Source: NEIGHBORHOOD NOTIFICATION</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190016	09/25/18	16209010800	<b>5517 EULALA DR</b>	PENDING	27	Initial Violation Neighborhood	09/26/2018
Original Complaint: High grass/weeds						<u>Source: NEIGHBORHOOD NOTIFICATION</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190018	09/25/18	16209008000	<b>5441 EULALA DR</b>	PENDING	27	Initial Violation Neighborhood	09/26/2018
Original Complaint: Parking in grass						<u>Source: NEIGHBORHOOD NOTIFICATION</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190022	09/25/18	16206021900	<b>239 TOWNES DR</b>	PENDING	27	Initial Violation Neighborhood	09/26/2018
Original Complaint: High grass/weeds						<u>Source: NEIGHBORHOOD NOTIFICATION</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190023	09/25/18	16206022200	<b>251 TOWNES DR</b>	PENDING	27	Initial Violation Neighborhood	09/26/2018
Original Complaint: High grass/weeds						<u>Source: NEIGHBORHOOD NOTIFICATION</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190024	09/25/18	16205007300	<b>5309 TOWNES CT</b>	PENDING	27	Initial Violation Neighborhood	09/26/2018
Original Complaint: High grass/weeds						<u>Source: NEIGHBORHOOD NOTIFICATION</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190025	09/25/18	16205006700	<b>5308 TOWNES CT</b>	PENDING	27	Initial Violation Neighborhood	09/26/2018
Original Complaint: High weeds						<u>Source: NEIGHBORHOOD NOTIFICATI</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190026	09/25/18	16201009800	<b>286 DELVIN DR</b>	PENDING	27	Initial Violation Neighborhood	09/26/2018
Original Complaint: Parking in grass, High grass/weeds						<u>Source: NEIGHBORHOOD NOTIFICATI</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190027	09/25/18	16206008700	<b>205 STERRY CT</b>	PENDING	27	Initial Violation Neighborhood	09/26/2018
Original Complaint: High grass/weeds						<u>Source: NEIGHBORHOOD NOTIFICATI</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190036	09/25/18	16206006000	<b>249 DELVIN DR</b>	PENDING	27	Initial Violation Neighborhood	09/26/2018
Original Complaint: Parking in grass						<u>Source: NEIGHBORHOOD NOTIFICATI</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190040	09/25/18	16205026300	<b>324 EULALA CIR</b>	PENDING	27	Initial Violation Neighborhood	09/26/2018
Original Complaint: High grass/weeds						<u>Source: NEIGHBORHOOD NOTIFICATI</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188543	09/04/18	149070C05000CO	<b>3321 CLAPHAM RD</b>	ACT ABATE	28	Violation Inspection - PS	09/25/2018
Original Complaint: Trash						<u>Source: Codes Online</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188545	09/04/18	149070C04200CO	<b>3285 CLAPHAM RD</b>	ACT ABATE	28	Violation Inspection - PS	09/25/2018
Original Complaint: Trailer in front yard						<u>Source: Codes Online</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188576	09/04/18	135100C08400CO	<b>3313 VINEWOOD CT</b>	ACT ABATE	28	Violation Inspection - PS	09/24/2018
Original Complaint: high grass weeds						<u>Source: INSPECTOR REPORTED</u>	

**Master RFS Detail Report**

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188591	09/04/18	135140A27200CO	<b>1017 BLUE MOUNTAIN LN</b>	ACT ABATE	28	Violation Inspection - PS	09/25/2018
Original Complaint: high grass weed						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188636	09/05/18	14816004800	<b>909 REEVES RD</b>	ACT ABATE	28	Violation Inspection - PS	10/01/2018
Original Complaint: AUDIT-INOPERABLE/UNREGISTERED MOTOR VEHICLE						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188639	09/05/18	14816007900	<b>915 REEVES RD</b>	ACT ABATE	28	Violation Inspection - PS	10/01/2018
Original Complaint: AUDIT-INOPERBLE/UNREGISTERED MOTOR VEHICLE						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188640	09/05/18	14816002300	<b>809 IRMA DR</b>	ACT ABATE	28	Violation Inspection - PS	09/20/2018
Original Complaint: HOW TAKEN: INSPECTOR REPORTED POG						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188648	09/05/18	14812011300	<b>820 IRMA DR</b>	ACT ABATE	28	Violation Inspection - PS	10/02/2018
Original Complaint: JTD HG&W						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188653	09/05/18	14800020700	<b>855 REEVES RD</b>	ACT ABATE	28	Violation Inspection - PS	10/01/2018
Original Complaint: AUDIT-JUNK TRASH AND DEBRIS						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188786	09/06/18	135140A23500CO	<b>1504 MOUNT MITCHELL CT</b>	ACT ABATE	28	Violation Inspection - PS	09/25/2018
Original Complaint: Junk in driveway						<u>Source: Codes Online</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188787	09/06/18	135140A23500CO	<b>1504 MOUNT MITCHELL CT</b>	ACT ABATE	28	Violation Inspection - PS	09/25/2018
Original Complaint: High grass/weeds						<u>Source: Codes Online</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188841	09/07/18	16302005600	<b>4429 WINTON DR</b>	ACT ABATE	28	Violation Inspection - PS	09/24/2018
Original Complaint: High grass/weeds						<u>Source:</u> Codes Online	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188976	09/11/18	14808003000	<b>4562 ARTELIA DR</b>	ACT ABATE	28	Env Court 1st Setting - PS	11/07/2018
Original Complaint: HOW TAKEN: INSPECTOR REPORTED HGW, JTD						<u>Source:</u> INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188977	09/11/18	14808002900	<b>4558 ARTELIA DR</b>	ACT ABATE	28	Env Court 1st Setting - PS	11/07/2018
Original Complaint: HOW TAKEN: INSPECTOR REPORTED JTD, PID						<u>Source:</u> INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188978	09/11/18	14808001600	<b>4547 ARTELIA DR</b>	ACT ABATE	28	Violation Inspection - PS	10/11/2018
Original Complaint: HOW TAKEN: INSPECTOR REPORTED IMV, JTD						<u>Source:</u> INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188985	09/11/18	163020A02700CO	<b>4908 ELLEN WAY</b>	ACT ABATE	28	Violation Inspection - PS	10/11/2018
Original Complaint: Type: Property Violations - Cars Parked On Lawn						<u>Source:</u> HUB	

Description:  
Truck parked in grass

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189009	09/11/18	149020A04300CO	<b>1104 WOBURN WAY</b>	ACT ABATE	28	Violation Inspection - PS	09/24/2018
Original Complaint: HIGH GRASS WEEDS						<u>Source:</u> INSPECTOR REPORTED	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189078	09/12/18	135140A08000CO	<b>405 BLACK MOUNTAIN DR</b>	ACT ABATE	28	Violation Inspection - PS	10/11/2018

Original Complaint: Type: Other - Other  
Source: HUB

Description:  
 Black SUV with expired tags parked in driveway

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189083	09/12/18	14812012800	<b>828 RICHARDS RD</b>	ACT ABATE	28	Violation Inspection - PS	10/11/2018

Original Complaint: HOW TAKEN: PHONE  
 junk trash and debris in front yard and by the garage, garage possible converted to living space?  
Source: PHONE

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189111	09/12/18	14808002000	<b>4531 ARTELIA DR</b>	ACT ABATE	28	Violation Inspection - PS	10/12/2018

Original Complaint: HOW TAKEN: INSPECTOR REPORTED  
 IMV, POG  
Source: INSPECTOR REPORTED

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189113	09/12/18	14808002100	<b>4527 ARTELIA DR</b>	ACT ABATE	28	Violation Inspection - PS	10/12/2018

Original Complaint: HOW TAKEN: INSPECTOR REPORTED  
 IMV  
Source: INSPECTOR REPORTED

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189115	09/12/18	14808002200	<b>4523 ARTELIA DR</b>	ACT ABATE	28	Violation Inspection - PS	10/12/2018

Original Complaint: HOW TAKEN: INSPECTOR REPORTED  
 IMV, POG, COMMERCIAL VEHICLE  
Source: INSPECTOR REPORTED

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189120	09/13/18	135140A01500CO	<b>748 PICCADILLY ROW</b>	ACT ABATE	28	Violation Inspection - PS	10/11/2018

Original Complaint: Inoperable vehicle in driveway (wrecked brown Nissan)  
Source: HUB

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189212	09/13/18	14909013900	<b>4826 APOLLO DR</b>	ACT ABATE	28	Violation Inspection - PS	09/28/2018
Original Complaint: NO PERMIT FOR CARPOT						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189248	09/13/18	14812024200	<b>4705 TERRAGON TRL</b>	ACT ABATE	28	Violation Inspection - PS	10/01/2018
Original Complaint: HOW TAKEN: INSPECTOR REPORTED HGW						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189250	09/13/18	14812024000	<b>4713 TERRAGON TRL</b>	ACT ABATE	28	Violation Inspection - PS	10/15/2018
Original Complaint: HOW TAKEN: INSPECTOR REPORTED IMV, POG						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189251	09/13/18	14808016800	<b>4708 TERRAGON TRL</b>	ACT ABATE	28	Violation Inspection - PS	10/15/2018
Original Complaint: HOW TAKEN: INSPECTOR REPORTED IMV, JTD						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189254	09/14/18	14808017800	<b>4721 TERRAGON TRL</b>	ACT ABATE	28	Violation Inspection - PS	10/15/2018
Original Complaint: HOW TAKEN: INSPECTOR REPORTED HGW, BUILDING PERMIT REQUIRED						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189262	09/14/18	14812024100	<b>4709 TERRAGON TRL</b>	PENDING	28	Env Court 1st Setting - PS	10/24/2018
Original Complaint: HOW TAKEN: INSPECTOR REPORTED JTD REPEAT OFFENDER						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189265	09/14/18	14913001700	<b>753 REEVES RD</b>	ACT ABATE	28	Violation Inspection - PS	10/01/2018
Original Complaint: AUDIT-PARKING ON GRASS						<u>Source: INSPECTOR REPORTED</u>	

**Master RFS Detail Report**

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189271	09/14/18	14913002200	<b>729 REEVES RD</b>	ACT ABATE	28	Violation Inspection - PS	10/18/2018
Original Complaint: AUDIT-JUNK TRASH AND DEBRIS, INOPERABLE/UNREGISTERED MOTOR VEHICLE						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189272	09/14/18	14913002300	<b>725 REEVES RD</b>	ACT ABATE	28	Violation Inspection - PS	10/01/2018
Original Complaint: HOW TAKEN: INSPECTOR REPORTED AUDIT-PARKING ON GRASS						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189273	09/14/18	14909015800	<b>4745 APOLLO DR</b>	ACT ABATE	28	Violation Inspection - PS	09/28/2018
Original Complaint: POG IMV						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189276	09/14/18	14909011700	<b>4741 APOLLO DR</b>	ACT ABATE	28	Violation Inspection - PS	09/28/2018
Original Complaint: PREMISES I D						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189278	09/14/18	14909012100	<b>4737 APOLLO DR</b>	ACT ABATE	28	Violation Inspection - PS	10/19/2018
Original Complaint: HG&W POG IMV JTD PREMISES I D						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189290	09/14/18	14909007000	<b>712 RICHARDS RD</b>	ACT ABATE	28	Violation Inspection - PS	10/01/2018
Original Complaint: AUDIT - JTD, POG						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189297	09/14/18	14909006800	<b>704 RICHARDS RD</b>	ACT ABATE	28	Violation Inspection - PS	10/01/2018
Original Complaint: AUDIT - JTD						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189300	09/14/18	14909001900	<b>721 RICHARDS RD</b>	ACT ABATE	28	Violation Inspection - PS	10/01/2018
Original Complaint: AUDIT - JTD						<u>Source: INSPECTOR REPORTED</u>	

**Master RFS Detail Report**

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189318	09/14/18	135140A27400CO	<b>1009 BLUE MOUNTAIN LN</b>	ACT ABATE	28	Violation Inspection - PS	10/11/2018
Original Complaint: Type: Other - Other						<u>Source:</u> HUB	

Description:  
Working on cars at a residence.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189361	09/14/18	14909007900	<b>100 APOLLO CT E</b>	ACT ABATE	28	Violation Inspection - PS	10/01/2018
Original Complaint: HG&W JTD						<u>Source:</u> INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189363	09/14/18	14909008700	<b>4716 APOLLO DR</b>	ACT ABATE	28	Violation Inspection - PS	10/05/2018
Original Complaint: IMV HG&W TRAILER JTD						<u>Source:</u> INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189377	09/17/18	14909009100	<b>213 MANATEE CT</b>	ACT ABATE	28	Violation Inspection - PS	10/08/2018
Original Complaint: IMV POG TRAILER IN YARD						<u>Source:</u> INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189393	09/17/18	14909002300	<b>701 RICHARDS RD</b>	ACT ABATE	28	Violation Inspection - PS	10/04/2018
Original Complaint: After Hours Evening Inspection Only - vehicle parking in the grass/yard areas.						<u>Source:</u> SPE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189394	09/17/18	14812008200	<b>829 RICHARDS RD</b>	ACT ABATE	28	Violation Inspection - PS	10/04/2018
Original Complaint: After Hours Evening Inspection Only - vehicles parking in the grass/yard areas.						<u>Source:</u> SPE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189398	09/17/18	14913002700	<b>709 REEVES RD</b>	ACT ABATE	28	Violation Inspection - PS	10/04/2018
Original Complaint: After Hours Evening Inspection Only - vehicles parking in the grass/yard areas.						<u>Source:</u> SPE	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189402	09/17/18	14913001100	<b>720 REEVES RD</b>	ACT ABATE	28	Violation Inspection - PS	10/04/2018
Original Complaint: After Hours Evening Inspection Only - vehicles parking in the grass/yard areas.						Source: SPE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189410	09/17/18	14816001300	<b>842 REEVES RD</b>	ACT ABATE	28	Violation Inspection - PS	10/12/2018
Original Complaint: HOW TAKEN: !!! SPE !!! After Hours Evening Inspection Only - vehicles parking in the grass/yard areas. Side yard. Also owner is constructing a metal carport without permits.						Source: SPE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189412	09/17/18	14909005100	<b>4712 BOWFIELD DR</b>	ACT ABATE	28	Violation Inspection - PS	10/04/2018
Original Complaint: After Hours Evening Inspection Only - vehicles parking in the grass/yard areas.						Source: SPE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189413	09/17/18	14909004800	<b>4724 BOWFIELD DR</b>	ACT ABATE	28	Violation Inspection - PS	10/04/2018
Original Complaint: After Hours Evening Inspection Only - vehicles parking in the grass/yard areas.						Source: SPE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189415	09/17/18	14913005300	<b>4764 BOWFIELD DR</b>	ACT ABATE	28	Violation Inspection - PS	10/04/2018
Original Complaint: After Hours Evening Inspection Only - vehicles parking in the grass/yard areas.						Source: SPE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189418	09/17/18	14909009900	<b>236 MANATEE CT</b>	ACT ABATE	28	Violation Inspection - PS	10/08/2018
Original Complaint: IMV HG&W						Source: INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189419	09/17/18	14913004700	<b>4788 BOWFIELD DR</b>	ACT ABATE	28	Violation Inspection - PS	10/04/2018
Original Complaint: After Hours Evening Inspection Only - vehicles parking in the grass/yard areas.						Source: SPE	

**Master RFS Detail Report**

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189422	09/17/18	14913003100	<b>4809 BOWFIELD DR</b>	ACT ABATE	28	Violation Inspection - PS	10/04/2018
Original Complaint: After Hours Evening Inspection Only - vehicles parking in the grass/yard areas.						<u>Source: SPE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189426	09/17/18	14909009800	<b>240 MANATEE CT</b>	ACT ABATE	28	Violation Inspection - PS	10/08/2018
Original Complaint: IMV POG						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189430	09/17/18	14812011800	<b>4731 MCBRIDE RD</b>	ACT ABATE	28	Violation Inspection - PS	10/04/2018
Original Complaint: After Hours Evening Inspection Only - vehicles parking in the grass/yard areas.						<u>Source: SPE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189431	09/17/18	14812010100	<b>4716 MCBRIDE RD</b>	ACT ABATE	28	Violation Inspection - PS	10/04/2018
Original Complaint: After Hours Evening Inspection Only - vehicles parking in the grass/yard areas.						<u>Source: SPE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189432	09/17/18	14816000600	<b>4743 MCBRIDE RD</b>	ACT ABATE	28	Violation Inspection - PS	10/04/2018
Original Complaint: After Hours Evening Inspection Only - vehicles parking in the grass/yard areas.						<u>Source: SPE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189434	09/17/18	14913000200	<b>804 IRMA DR</b>	ACT ABATE	28	Violation Inspection - PS	10/04/2018
Original Complaint: After Hours Evening Inspection Only - vehicles parking in the grass/yard areas.						<u>Source: SPE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189439	09/17/18	14812007400	<b>898 IRMA DR</b>	ACT ABATE	28	Violation Inspection - PS	10/22/2018
Original Complaint: After Hours Evening Inspection Only - vehicles parking in the grass/yard areas.						<u>Source: SPE</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189444	09/17/18	13500001500	<b>215 FRANKLIN LIMESTONE RD</b>	ACT ABATE	28	Violation Inspection - PS	10/15/2018

Original Complaint: Type: Property Violations - Cars Parked On Lawn Source: HUB

Description:

The residents at this location do a lot of mechanical work on vehicles and park some of those vehicles on the grass behind the Speedway Gas Station Property.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189463	09/17/18	14800014700	<b>850 RICHARDS RD</b>	ACT ABATE	28	Violation Inspection - PS	10/17/2018

Original Complaint: AUDIT - JTD, IMV/YARD Source: INSPECTOR REPORTED

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189477	09/17/18	14812008500	<b>817 A RICHARDS RD</b>	ACT ABATE	28	Violation Inspection - PS	10/01/2018

Original Complaint: AUDIT - JTD, HGW Source: INSPECTOR REPORTED

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189494	09/17/18	13500006000	<b>208 FRANKLIN LIMESTONE RD</b>	ACT ABATE	28	Violation Inspection - PS	10/15/2018

Original Complaint: OPEN STORAGE OF JUNK TRASH DEBRIS AND INOPERABLE VEHICLES PARKED IN GRASS Source: INSPECTOR REPORTED

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189552	09/18/18	148080A02700CO	<b>4841 TERRAGON TRL</b>	ACT ABATE	28	Violation Inspection - PS	10/11/2018

Original Complaint: Type: Property Violations - Tall Grass and Weeds Source: HUB

Description:

front lawn has tall grass

Additional Comments:

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189554	09/18/18	14905017800	<b>4804 TERRAGON TRL</b>	ACT ABATE	28	Violation Inspection - PS	10/11/2018
Original Complaint: Type: Property Violations - Tall Grass and Weeds						<u>Source: HUB</u>	

Description:  
4804 Terragon Trail has high grass in the front lawn

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189555	09/18/18	14905016700	<b>4761 TERRAGON TRL</b>	ACT ABATE	28	Violation Inspection - PS	10/11/2018
Original Complaint: Type: Property Violations - Tall Grass and Weeds						<u>Source: HUB</u>	

Description:  
4761 Terragon Trail has high frass in front lawn

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189557	09/18/18	14811000200	<b>925 RICHARDS RD</b>	ACT ABATE	28	Violation Inspection - PS	10/22/2018
Original Complaint: AUDIT - JTD, ACCESS. STRUCTURE						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189560	09/18/18	14905007700	<b>4885 BARCLAY SQUARE DR</b>	ACT ABATE	28	Violation Inspection - PS	10/11/2018
Original Complaint: Type: Property Violations - Cars Parked On Lawn						<u>Source: HUB</u>	

Description:  
4885 Barclay Square Drive - residents parking on the front lawn

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189566	09/18/18	14811000300	<b>919 RICHARDS RD</b>	ACT ABATE	28	Violation Inspection - PS	10/02/2018
Original Complaint: AUDIT - PREMISES ID.						<u>Source: INSPECTOR REPORTED</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189570	09/18/18	14812000700	<b>913 RICHARDS RD</b>	ACT ABATE	28	Violation Inspection - PS	10/02/2018
Original Complaint: AUDIT - JTD, IMV/YARD, POG						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189582	09/18/18	14905017200	<b>4741 TERRAGON TRL</b>	ACT ABATE	28	Violation Inspection - PS	10/01/2018
Original Complaint: HOW TAKEN: INSPECTOR REPORTED HGW, JTD						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189586	09/18/18	14808017600	<b>4740 TERRAGON TRL</b>	ACT ABATE	28	Violation Inspection - PS	10/01/2018
Original Complaint: HOW TAKEN: INSPECTOR REPORTED HGW, JTD						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189587	09/18/18	14905015300	<b>4744 TERRAGON TRL</b>	ACT ABATE	28	Violation Inspection - PS	10/15/2018
Original Complaint: HOW TAKEN: INSPECTOR REPORTED IMV						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189605	09/18/18	14808003100	<b>4566 ARTELIA DR</b>	ACT ABATE	28	Violation Inspection - PS	10/02/2018
Original Complaint: HOW TAKEN: INSPECTOR REPORTED HGW, PID						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189608	09/18/18	13505005800	<b>325 LADYBIRD DR</b>	PENDING	28	Warrant Check - PS	10/22/2018
Original Complaint: inoperable vehicle parked in driveway on jacks						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189638	09/19/18	14913002500	<b>717 REEVES RD</b>	ACT ABATE	28	Violation Inspection - PS	10/18/2018
Original Complaint: AUDIT-JUNK TRASH AND DEBRIS						<u>Source: INSPECTOR REPORTED</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189643	09/19/18	14913002600	<b>713 REEVES RD</b>	ACT ABATE	28	Violation Inspection - PS	10/18/2018
Original Complaint: AUDIT-INOPERABLE/UNREGISTERED MOTOR VEHICLE						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189648	09/19/18	14905015500	<b>4752 TERRAGON TRL</b>	ACT ABATE	28	Violation Inspection - PS	10/11/2018
Original Complaint: inoperable vehicle parked in the grass						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189650	09/19/18	14913002800	<b>705 REEVES RD</b>	ACT ABATE	28	Violation Inspection - PS	10/18/2018
Original Complaint: AUDIT-JUNK TRASH AND DEBRIS						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189658	09/19/18	14913001500	<b>704 REEVES RD</b>	ACT ABATE	28	Violation Inspection - PS	10/18/2018
Original Complaint: AUDIT-PARKING ON GRASS						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189675	09/19/18	14913001200	<b>716 REEVES RD</b>	ACT ABATE	28	Violation Inspection - PS	10/02/2018
Original Complaint: AUDIT-HIGH GRASS AND WEEDS						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189686	09/19/18	14909013100	<b>105 APOLLO CT W</b>	ACT ABATE	28	Violation Inspection - PS	10/04/2018
Original Complaint: AUDIT-PREMISES ID						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189690	09/19/18	14909012700	<b>121 APOLLO CT W</b>	ACT ABATE	28	Violation Inspection - PS	10/11/2018
Original Complaint: AUDIT-IMV JTD POG						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189691	09/19/18	14909012600	<b>125 APOLLO CT W</b>	ACT ABATE	28	Violation Inspection - PS	10/11/2018
Original Complaint: AUDIT-IMV POG PREMISES I D						<u>Source: INSPECTOR REPORTED</u>	

**Master RFS Detail Report**

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189696	09/19/18	14816003900	<b>823 REEVES RD</b>	ACT ABATE	28	Violation Inspection - PS	10/16/2018
Original Complaint: Reported owner has up to 20 persons residing in the dwelling; reported a trailer parked in rear yard <u>Source:</u> SPE area; plastic has been placed with gravel on top to expand the existing driveway.							

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189699	09/19/18	14909010800	<b>200 MANATEE CT</b>	ACT ABATE	28	Violation Inspection - PS	10/11/2018
Original Complaint: AUDIT-H,G&W JTD						<u>Source:</u> INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189704	09/19/18	14909011000	<b>4732 APOLLO DR</b>	ACT ABATE	28	Violation Inspection - PS	10/11/2018
Original Complaint: AUDIT-POG H,G&W						<u>Source:</u> INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189707	09/19/18	14800016100	<b>860 RICHARDS RD</b>	ACT ABATE	28	Violation Inspection - PS	10/16/2018
Original Complaint: Overgrowth of weeds behind 4611-4619 Artelia Dr						<u>Source:</u> PHONE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189738	09/19/18	14812008500	<b>817 A RICHARDS RD</b>	ACT ABATE	28	Violation Inspection - PS	10/04/2018
Original Complaint: After Hours Evening Inspection Only - vehicle parking in the grass/yard areas.						<u>Source:</u> SPE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189739	09/19/18	14812005700	<b>4706 DREWRY DR</b>	ACT ABATE	28	Violation Inspection - PS	10/04/2018
Original Complaint: After Hours Evening Inspection Only - vehicle parking in the grass/yard areas.						<u>Source:</u> SPE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189740	09/19/18	14812012400	<b>4709 MCBRIDE RD</b>	ACT ABATE	28	Violation Inspection - PS	10/04/2018
Original Complaint: After Hours Evening Inspection Only - vehicle parking in the grass/yard areas.						<u>Source:</u> SPE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189742	09/19/18	14812009500	<b>4713 RICHARDS CT</b>	ACT ABATE	28	Violation Inspection - PS	10/04/2018
Original Complaint: After Hours Evening Inspection Only - vehicle parking in the grass/yard areas.						<u>Source:</u> SPE	

**Master RFS Detail Report**

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189743	09/19/18	14812009200	<b>4726 RICHARDS CT</b>	ACT ABATE	28	Violation Inspection - PS	10/04/2018
Original Complaint: After Hours Evening Inspection Only - vehicle parking in the grass/yard areas.						<u>Source: SPE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189747	09/20/18	149020D00300CO	<b>712 BISHOPSGATE RD</b>	ACT VEHROW	28	PS - Memo Only	09/21/2018
Original Complaint: Type: Public Safety - Abandoned Vehicles						<u>Source: HUB</u>	

Description:  
red GMC SUV

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189800	09/21/18	14909011100	<b>4736 APOLLO DR</b>	ACT ABATE	28	Violation Inspection - PS	10/05/2018
Original Complaint: HG&W IMV JTD						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189802	09/21/18	14909011200	<b>4740 APOLLO DR</b>	ACT ABATE	28	Violation Inspection - PS	10/09/2018
Original Complaint: IMV JTD POG HG&W						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189803	09/21/18	14909011300	<b>4744 APOLLO DR</b>	ACT ABATE	28	Violation Inspection - PS	10/09/2018
Original Complaint: POG JTD HG&W						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189825	09/21/18	135140A13700CO	<b>505 BLACK MOUNTAIN CT</b>	ACT ABATE	28	Violation Inspection - PS	10/08/2018
Original Complaint: HIGH GRASS WEEDS						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189857	09/24/18	14905015600	<b>4756 TERRAGON TRL</b>	ACT ABATE	28	Violation Inspection - PS	10/08/2018
Original Complaint: HOW TAKEN: INSPECTOR REPORTED JTD						<u>Source: INSPECTOR REPORTED</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189858	09/24/18	14905015900	<b>4768 TERRAGON TRL</b>	ACT ABATE	28	Violation Inspection - PS	10/08/2018
Original Complaint: HOW TAKEN: INSPECTOR REPORTED POG						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189859	09/24/18	14905016400	<b>4773 TERRAGON TRL</b>	ACT ABATE	28	Violation Inspection - PS	10/23/2018
Original Complaint: HOW TAKEN: INSPECTOR REPORTED IMV						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189863	09/24/18	135140A19700CO	<b>1008 BLUE MOUNTAIN LN</b>	ACT ABATE	28	Violation Inspection - PS	10/16/2018
Original Complaint: Type: Other - Other						<u>Source: HUB</u>	
Description: House has "For Rent" in yard but owner has not filed landlord registration information							
Additional Comments:							

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189902	09/24/18	14812009100	<b>4722 RICHARDS CT</b>	ACT ABATE	28	Violation Inspection - PS	10/15/2018
Original Complaint: AUDIT - IMV/YARD						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189905	09/24/18	14807004100	<b>219 OVERBY DR</b>	ACT ABATE	28	Violation Inspection - PS	10/18/2018
Original Complaint: Junk, trash & debris						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189922	09/24/18	14905016200	<b>4781 TERRAGON TRL</b>	ACT ABATE	28	Violation Inspection - PS	10/09/2018
Original Complaint: HOW TAKEN: INSPECTOR REPORTED JTD, HGW						<u>Source: INSPECTOR REPORTED</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189925	09/24/18	14808019400	<b>4821 TERRAGON TRL</b>	ACT ABATE	28	Violation Inspection - PS	10/25/2018
Original Complaint: HOW TAKEN: INSPECTOR REPORTED IMV, JTD						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189929	09/24/18	14808018800	<b>4820 TERRAGON TRL</b>	ACT ABATE	28	Violation Inspection - PS	10/09/2018
Original Complaint: HOW TAKEN: INSPECTOR REPORTED HGW						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189932	09/24/18	14808019600	<b>4829 TERRAGON TRL</b>	ACT ABATE	28	Violation Inspection - PS	10/09/2018
Original Complaint: HOW TAKEN: INSPECTOR REPORTED JTD						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189934	09/24/18	16301000600	<b>4213 KEVINWOOD CT</b>	ACT ABATE	28	Violation Inspection - PS	10/23/2018
Original Complaint: Type: Property Violations - Junk and Debris						<u>Source: HUB</u>	

Description:  
caller states there is trash and old furniture littering the property

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189935	09/24/18	16301002100	<b>4212 KEVINWOOD CT</b>	ACT ABATE	28	Violation Inspection - PS	10/23/2018
Original Complaint: Type: Property Violations - Junk and Debris						<u>Source: HUB</u>	

Description:  
Caller states there is furniture, restaurant equipment, cars with no tags are all in front of house.

Additional Comments:

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189936	09/24/18	16301001700	<b>4228 KEVINWOOD CT</b>	ACT ABATE	28	Violation Inspection - PS	10/23/2018
Original Complaint: Type: Property Violations - Cars Parked on Lawn						<u>Source</u> : HUB	

Description:

Caller states there are cars parked all over property with missing parts, no tags.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189937	09/24/18	148080A04200CO	<b>4832 TERRAGON TRL</b>	ACT ABATE	28	Violation Inspection - PS	10/09/2018
Original Complaint: HOW TAKEN: INSPECTOR REPORTED JTD						<u>Source</u> : INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189987	09/25/18	14816008000	<b>884 REEVES RD</b>	ACT ABATE	28	Violation Inspection - PS	10/15/2018
Original Complaint: AUDIT-PREMISES ID						<u>Source</u> : INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190072	09/25/18	14909015900	<b>4752 APOLLO DR</b>	ACT ABATE	28	Violation Inspection - PS	10/04/2018
Original Complaint: AUDIT-HG&W						<u>Source</u> : INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190073	09/25/18	14909016000	<b>4756 APOLLO DR</b>	ACT ABATE	28	Violation Inspection - PS	10/04/2018
Original Complaint: AUDIT-JTD						<u>Source</u> : INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190078	09/26/18	14909016200	<b>4764 APOLLO DR</b>	ACT ABATE	28	Violation Inspection - PS	10/11/2018
Original Complaint: AUDIT-HG&W						<u>Source</u> : INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190080	09/26/18	14905004900	<b>4772 APOLLO DR</b>	ACT ABATE	28	Violation Inspection - PS	10/08/2018
Original Complaint: AUDIT-HG&W						<u>Source</u> : INSPECTOR REPORTED	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190082	09/26/18	14905004700	<b>4780 APOLLO DR</b>	ACT ABATE	28	Violation Inspection - PS	10/05/2018
Original Complaint: AUDIT-POG						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190091	09/26/18	14905002300	<b>4810 APOLLO DR</b>	ACT ABATE	28	Violation Inspection - PS	10/12/2018
Original Complaint: AUDIT-HG&W JTD						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190093	09/26/18	14913001000	<b>726 REEVES RD</b>	ACT ABATE	28	Violation Inspection - PS	10/15/2018
Original Complaint: AUDIT-HIGH GRASS AND WEEDS						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190103	09/26/18	14905002400	<b>4814 APOLLO DR</b>	ACT ABATE	28	Violation Inspection - PS	10/18/2018
Original Complaint: AUDIT-IMV JTD						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190105	09/26/18	14913000700	<b>736 REEVES RD</b>	ACT ABATE	28	Violation Inspection - PS	10/26/2018
Original Complaint: AUDIT-INOPERABLE MOTOR VEHICLE/JUNK TRASH AND DEBRIS						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190107	09/26/18	14913000500	<b>744 REEVES RD</b>	ACT ABATE	28	Violation Inspection - PS	10/26/2018
Original Complaint: AUDIT-NO CAUSE FOR ACTION						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190112	09/26/18	14909013800	<b>4822 APOLLO DR</b>	ACT ABATE	28	Violation Inspection - PS	10/18/2018
Original Complaint: AUDIT-IMV JTD						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190113	09/26/18	14816002100	<b>806 REEVES RD</b>	ACT ABATE	28	Violation Inspection - PS	10/26/2018
Original Complaint: AUDIT-JUNK TRASH AND DEBRIS						<u>Source: INSPECTOR REPORTED</u>	

**Master RFS Detail Report**

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190116	09/26/18	14909013900	<b>4826 APOLLO DR</b>	ACT ABATE	28	Violation Inspection - PS	10/22/2018
Original Complaint: AUDIT-HG&W REPAIR & OR DEMOLISH ACCESSORY STRUCTURE						<u>Source:</u> INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190151	09/26/18	14909011800	<b>212 APOLLO CIR</b>	ACT ABATE	28	Violation Inspection - PS	10/12/2018
Original Complaint: AUDIT-PREMISES I D POG						<u>Source:</u> INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190244	09/28/18	14800008601	<b>944 RICHARDS RD</b>	ACT ABATE	28	Violation Inspection - PS	10/12/2018
Original Complaint: AUDIT - PREM. ID.						<u>Source:</u> INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190245	09/28/18	14800019800	<b>946 RICHARDS RD</b>	ACT ABATE	28	Violation Inspection - PS	10/12/2018
Original Complaint: AUDIT - PREMISES ID., JTD, IMV/YARD						<u>Source:</u> INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190249	09/28/18	14800017800	<b>929 RICHARDS RD</b>	ACT ABATE	28	Violation Inspection - PS	10/19/2018
Original Complaint: AUDIT - JTD, IMV/YARD						<u>Source:</u> INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190257	09/28/18	14800029500	<b>931 RICHARDS RD</b>	ACT ABATE	28	Violation Inspection - PS	10/19/2018
Original Complaint: AUDIT - JTD						<u>Source:</u> INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190271	09/28/18	14909012300	<b>4729 APOLLO DR</b>	ACT ABATE	28	Violation Inspection - PS	10/15/2018
Original Complaint: AUUDT-JTD HG&W						<u>Source:</u> INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190284	09/28/18	149070C03000CO	<b>3316 CLAPHAM RD</b>	PENDING	28	Initial Violation Inspection - PS	09/29/2018
Original Complaint: Vehicles parked on the grass; junk, trash, and debris						<u>Source:</u> PHONE	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190285	09/28/18	149030A09800CO	<b>2921 SPLIT OAK TRL</b>	PENDING	28	Initial Violation Inspection - PS	09/29/2018
Original Complaint: HOW TAKEN: PHONE Vehicles parked in the grass						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190286	09/28/18	149070C05300CO	<b>3037 SPLIT OAK TRL</b>	PENDING	28	Initial Violation Inspection - PS	09/29/2018
Original Complaint: Commercial vehicles at a residential home						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188580	09/04/18	15001010900	<b>514 RURAL HILL RD</b>	ACT ABATE	29	Violation Inspection - PS	09/20/2018
Original Complaint: tall grass						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188777	09/06/18	149030F03400CO	<b>2630 LAKEVILLA DR</b>	ACT VEHROW	29	Administrative Hearing Vehicle	10/03/2018
Original Complaint: Inoperable Blue Honda on row.						<u>Source: Codes Online</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188954	09/10/18	15001011000	<b>516 RURAL HILL RD</b>	ACT ABATE	29	Violation Inspection - PS	09/20/2018
Original Complaint: POG						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189091	09/12/18	149030I00100CO	<b>2560 WILLOWBRANCH DR</b>	ACT ABATE	29	Violation Inspection - PS	10/05/2018
Original Complaint: Type: Property Violations - Tall Grass and Weeds						<u>Source: HUB</u>	

Description:  
Very tall grass

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189126	09/13/18	14903000400	<b>2447 BROADVIEW DR</b>	ACT ABATE	29	Violation Inspection - PS	10/02/2018
Original Complaint: IMV in Rear						<u>Source: INSPECTOR REPORTED</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189275	09/14/18	14904010600	<b>2629 EDGE O LAKE DR</b>	ACT ABATE	29	Violation Inspection - PS	10/15/2018
Original Complaint: Junk, trash & debris front & back yard						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189307	09/14/18	13606001300	<b>217 CLEARLAKE DR W</b>	ACT ABATE	29	Violation Inspection - PS	10/12/2018
Original Complaint: HOW TAKEN: PHONE Junk, trash, and debris; inoperable vehicle						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189327	09/14/18	13613010600	<b>3000 GOODWIN DR</b>	ACT ABATE	29	Violation Inspection - PS	10/15/2018
Original Complaint: Type: Property Violations - Junk and Debris						<u>Source: HUB</u>	
Description: washing machine has been in backyard for 3 weeks.							
Additional Comments:							

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189453	09/17/18	14903002600	<b>2509 SLEEPY HOLLOW DR</b>	ACT ABATE	29	Violation Inspection - PS	10/12/2018
Original Complaint: Type: Property Violations - Tall Grass and Weeds						<u>Source: HUB</u>	
Description: Every summer for the past 7 years. Garbage everywhere, non-functional pool in the back yard and non functional water feature in the front yard, 6 ft tall weeds in the back yard. The mosquitos are ridiculous and we can't use our back yard because of it. Please make this stop permanently.							
Additional Comments:							

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189528	09/17/18	135160A01500CO	<b>920 FLINTLOCK PL</b>	ACT ABATE	29	Violation Inspection - PS	10/04/2018
Original Complaint: Grass is over 3 foot tall.						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189715	09/19/18	13606001300	<b>217 CLEARLAKE DR W</b>	ACT ABATE	29	Violation Inspection - PS	10/15/2018
Original Complaint: Dilapidated Deck						<u>Source: INSPECTOR REPORTED</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189744	09/19/18	15002005800	<b>525 MOSS LANDING DR</b>	PENDING	29	Env Court 1st Setting - PS	11/07/2018
Original Complaint: POG, HGW						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189765	09/20/18	15005025300	<b>2929 MOSSDALE DR</b>	ACT ABATE	29	Violation Inspection - PS	10/15/2018
Original Complaint: Privacy fence-nails are sticking out of the fence						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189815	09/21/18	15001005000	<b>2739 MOSSDALE DR</b>	ACT ABATE	29	Violation Inspection - PS	10/10/2018
Original Complaint: HG, IMV in Ditch						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189834	09/21/18	15002003600	<b>594 MOSS LANDING DR</b>	ACT ABATE	29	Violation Inspection - PS	10/01/2018
Original Complaint: POG						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189864	09/24/18	150090A11700CO	<b>1116 TRACETON CIR</b>	ACT ABATE	29	Violation Inspection - PS	10/15/2018
Original Complaint: Type: Property Violations - Junk and Debris						<u>Source: HUB</u>	

Description:  
 They continually overfill trash container  
 Pic attached was taken after trash pick up on fri. They pickedup all they cpuld but as u can see ca  
 is still full and bags on driveway and garbage spilled onto the street creatong health hazard

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189891	09/24/18	15002024500	<b>1114 MARY EVELYN CT</b>	ACT ABATE	29	Violation Inspection - PS	10/19/2018
Original Complaint: Type: Property Violations - Junk and Debris						<u>Source: HUB</u>	

Description:  
 Sofa has been set out by curb for over 3 weeks

Additional Comments:

**Master RFS Detail Report**

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189957	09/24/18	14903013900	<b>2604 LAKEVILLA DR</b>	ACT VEHROW	29	Violation Inspection CAR - PS	09/28/2018
Original Complaint: AMV on ROW						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189966	09/25/18	150090A11900CO	<b>1108 TRACETON CIR</b>	ACT ABATE	29	Violation Inspection - PS	10/15/2018
Original Complaint: JTD @ Roadside						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189971	09/25/18	150090A11200CO	<b>1117 TRACETON CIR</b>	ACT ABATE	29	Violation Inspection - PS	10/19/2018
Original Complaint: IMV in Grass/Drive						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189976	09/25/18	15002050400	<b>754 HOLDER DR</b>	ACT ABATE	29	Violation Inspection - PS	10/15/2018
Original Complaint: Furniture @ ROW						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189977	09/25/18	15002013200	<b>740 HOLDER DR</b>	ACT ABATE	29	Violation Inspection - PS	10/05/2018
Original Complaint: at 742, POG						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189978	09/25/18	15002013700	<b>760 HOLDER DR</b>	ACT ABATE	29	Violation Inspection - PS	10/15/2018
Original Complaint: Furniture # ROW						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189979	09/25/18	14903014200	<b>2609 LAKEVILLA DR</b>	ACT ABATE	29	Violation Inspection - PS	10/10/2018
Original Complaint: HGW						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189980	09/25/18	14903014400	<b>2601 LAKEVILLA DR</b>	ACT ABATE	29	Violation Inspection - PS	10/15/2018
Original Complaint: HGW, JTD						<u>Source: INSPECTOR REPORTED</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189981	09/25/18	14903013800	<b>2531 WILLOWBRANCH DR</b>	ACT ABATE	29	Violation Inspection - PS	10/10/2018
Original Complaint: HGW						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189990	09/25/18	149040B00200CO	<b>2562 WILLOWBRANCH DR</b>	PENDING	29	Warrant Check - PS	11/14/2018
Original Complaint: High grass/weeds						<u>Source: Codes Online</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190164	09/27/18	15002037600	<b>809 LAKE TERRACE DR</b>	ACT ABATE	29	Violation Inspection - PS	10/15/2018
Original Complaint: Furniture, JTD on Property						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190272	09/28/18	13613010300	<b>3105 WILDWOOD DR</b>	ACT ABATE	29	Violation Inspection - PS	10/15/2018
Original Complaint: HGW						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190277	09/28/18	14904003900	<b>454 RURAL HILL RD</b>	ACT ABATE	29	Violation Inspection - PS	10/18/2018
Original Complaint: JTD in yard and drive						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190282	09/28/18	15009005300	<b>2536 FOREST VIEW DR</b>	PENDING	29	Initial Violation Inspection - PS	09/29/2018
Original Complaint: Type: Property Violations - Cars Parked on Lawn						<u>Source: HUB</u>	

Description:

Attached is a photo of neighbors yard who continually park cars all over their front yard. They have long driveway and a big turnaround in the back, so they have room to park back there. I have repor this before but seems it has done no good. First request had wrong address.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188547	09/04/18	14708005400	<b>4825 HUMBER DR</b>	ACT ABATE	30	Violation Inspection - PS	10/11/2018
Original Complaint: Overcrowding. House in disrepair.						<u>Source: Codes Online</u>	

**Master RFS Detail Report**

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188564	09/04/18	16204004700	<b>4929 SHIHMEN DR</b>	ACT ABATE	30	Violation Inspection - PS	09/25/2018
Original Complaint: High grass/weeds						<u>Source: Codes Online</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188581	09/04/18	16204006500	<b>117 TOMARAND RD</b>	ACT ABATE	30	Violation Inspection - PS	09/25/2018
Original Complaint: High grass & weeds - vacant house						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188685	09/05/18	16203001500	<b>4941 CIMARRON WAY</b>	ACT ABATE	30	Violation Inspection - PS	09/25/2018
Original Complaint: Junk, trash & debris						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188686	09/05/18	16203001800	<b>4929 CIMARRON WAY</b>	ACT ABATE	30	Violation Inspection - PS	09/25/2018
Original Complaint: Junk, trash & debris						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188687	09/05/18	16203003500	<b>4906 CIMARRON WAY</b>	ACT ABATE	30	Violation Inspection - PS	09/25/2018
Original Complaint: Junk, trash & debris						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188688	09/05/18	16203036100	<b>4952 ALGONQUIN TRL</b>	ACT ABATE	30	Violation Inspection - PS	09/25/2018
Original Complaint: Junk, trash & debris						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188689	09/05/18	16203037700	<b>4936 ALGONQUIN TRL</b>	ACT ABATE	30	Violation Inspection - PS	09/25/2018
Original Complaint: Junk, trash & debris						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188694	09/05/18	14708010500	<b>4848 TORBAY DR</b>	ACT ABATE	30	Violation Inspection - PS	10/11/2018
Original Complaint: High grass/weeds						<u>Source: HUB</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188732	09/05/18	14815018100	<b>237 PANAMINT DR</b>	ACT ABATE	30	Violation Inspection - PS <u>Source: PHONE</u>	09/25/2018

Original Complaint: Dilapidated home

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188735	09/05/18	14712008500	<b>4732 NOLENSVILLE PIKE</b>	ACT ABATE	30	Violation Inspection - PS <u>Source: WALK IN</u>	09/25/2018

Original Complaint: HOW TAKEN: WALK IN  
Junk, trash, and debris; restaurant behind building illegally; do not have a permit for use of bldg.; also, the downspout is causing water runoff onto next door business

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188785	09/06/18	16207002100	<b>75 BENZING RD</b>	ACT ABATE	30	Violation Inspection - PS <u>Source: PHONE</u>	09/24/2018

Original Complaint: High grass & weeds

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188838	09/07/18	16203001400	<b>4945 CIMARRON WAY</b>	ACT ABATE	30	Violation Inspection - PS <u>Source: INSPECTOR REPORTED</u>	09/25/2018

Original Complaint: parking on the grass

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188839	09/07/18	16203001600	<b>4937 CIMARRON WAY</b>	ACT ABATE	30	Violation Inspection - PS <u>Source: INSPECTOR REPORTED</u>	09/25/2018

Original Complaint: inoperable vehicle parked in grass

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188851	09/07/18	16204007000	<b>4165 APACHE TRL</b>	ACT ABATE	30	Violation Inspection - PS <u>Source: INSPECTOR REPORTED</u>	09/25/2018

Original Complaint: OPEN STORAGE OF JUNK, TRASH, DEBRIS AND INOPERABLE UNLICENSED VEHICLES PARKED IN GRASS AND DRIVEWAY

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188852	09/07/18	16204006900	<b>4161 APACHE TRL</b>	ACT ABATE	30	Violation Inspection - PS <u>Source: INSPECTOR REPORTED</u>	09/25/2018

Original Complaint: OPEN STORAGE OF JUNK, TRASH, DEBRIS AND INOPERABLE VEHICLES PARKED IN GRAS

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188853	09/07/18	16204007100	<b>4169 APACHE TRL</b>	ACT ABATE	30	Violation Inspection - PS	09/25/2018
Original Complaint: OPEN STORAGE OF JUNK, TRASH, DEBRIS AND INOPERABLE VEHICLES PARKED IN THE GRASS						<u>Source:</u> INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188854	09/07/18	16204007200	<b>4173 APACHE TRL</b>	ACT ABATE	30	Violation Inspection - PS	09/25/2018
Original Complaint: OPEN STORAGE OF JUNK, TRASH, DEBRIS AND INOPERABLE VEHICLES PARKED IN THE GRASS						<u>Source:</u> INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188870	09/07/18	16204007200	<b>4173 APACHE TRL</b>	ACT ABATE	30	Violation Inspection - PS	09/25/2018
Original Complaint: no landlord registration						<u>Source:</u> INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188912	09/10/18	16204004200	<b>4909 SHIHMEN DR</b>	ACT ABATE	30	Violation Inspection - PS	10/04/2018
Original Complaint: Type: Property Violations - Dilapidated Structures						<u>Source:</u> HUB	

Description:

House is in state of disrepair. Paint chipping on bricks and trim. Junk scattered throughout yard. High weeds in part of yard.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188983	09/11/18	14805012300	<b>308 MARGO LN</b>	ACT VEHROW	30	Violation Inspection CAR - PS	09/17/2018
Original Complaint: abandoned van on right of way - missing tire						<u>Source:</u> PHONE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189045	09/11/18	16207002200	<b>77 BENZING RD</b>	ACT ABATE	30	Violation Inspection - PS	10/25/2018
Original Complaint: HIGH GRASS WEEDS						<u>Source:</u> INSPECTOR REPORTED	

**Master RFS Detail Report**

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189112	09/12/18	14806008100	<b>3803 SYFERT LN</b>	ACT ABATE	30	Violation Inspection - PS	10/05/2018
Original Complaint: Type: Property Violations - Illegal Sign on Private Property						<u>Source:</u> HUB	

Description:  
House church sign

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189133	09/13/18	14805017400	<b>350 LEO LN</b>	ACT ABATE	30	Violation Inspection - PS	10/11/2018
Original Complaint: Type: Property Violations - Junk and Debris						<u>Source:</u> HUB	

Description:  
Construction material and used windows stacked in driveway. Two inoperable vehicles parked in driveway. They havent moved in at least 8 months and are now being used as junk holders. Also, gray flatbed pickup is parked on street in front without license plates

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189160	09/13/18	14805017400	<b>350 LEO LN</b>	PENDING	30	Violation Inspection - PS	09/17/2018
Original Complaint: Type: Other - Other						<u>Source:</u> HUB	

Description:  
A gray flatbed pickup is parked on street in front without license plates. Two inoperable vehicles stored in driveway. A black compact car and the other looks like a truck maybe. Lots of junk piled around.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189161	09/13/18	14809005500	<b>343 MARGO LN</b>	ACT ABATE	30	Violation Inspection - PS	10/11/2018
Original Complaint: Type: Property Violations - Cars Parked On Lawn						<u>Source:</u> HUB	

Description:  
White Kia parked in grass next to drive

Additional Comments:

**Master RFS Detail Report**

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189166	09/13/18	13413024600	<b>98 WALLACE RD</b>	ACT ABATE	30	Violation Inspection - PS	10/11/2018
Original Complaint: Type: Property Violations - Junk and Debris						<u>Source: HUB</u>	

Description:

This lot has been vacant for several months. The grass/weeds have been allowed to grown out of control - 3-4ft in height. Several homeless people have been hanging out on this lot and leaving behind all their trash. We have had to call Metro Police to have loiterers removed on several occasions. At least one of the men who had been drinking asked one of my employees "how much" and then got mad when she ignored him. We have seen drug deals and prostitution hook-ups. I do not know who owns this property, but we are tired of dealing with their mess.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189229	09/13/18	14813018800	<b>5014 PACKARD DR</b>	ACT ABATE	30	Violation Inspection - PS	10/11/2018
Original Complaint: Type: Property Violations - Cars Parked On Lawn						<u>Source: HUB</u>	

Description:

White Dodge car parked in front yard all the time.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189447	09/17/18	14814032100	<b>4014 SHUFELD CT</b>	ACT ABATE	30	PS - Memo Only	09/18/2018
Original Complaint: Type: Property Violations - Cars Parked On Lawn						<u>Source: HUB</u>	

Description:

Inoperable vehicle is being stored on the grass in the backyard. Photo attached

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189472	09/17/18	14806001400	<b>3817 E RIDGE DR</b>	ACT ABATE	30	Violation Inspection - PS	09/11/2018
Original Complaint: High grass/weeds						<u>Source: PHONE</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189753	09/20/18	16203027600	<b>4934 BARELLA DR</b>	ACT ABATE	30	Violation Inspection - PS	10/23/2018
Original Complaint: High grass/weeds						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189845	09/21/18	14810009300	<b>3929 KEELEY DR</b>	ACT ABATE	30	Violation Inspection - PS	10/18/2018
Original Complaint: Type: Property Violations - Cars Parked On Lawn						<u>Source: HUB</u>	

Description:  
there are several cars parked in back with weeds all around them, so I guess they are not working cars. Overgrown grass as well.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189870	09/24/18	14716016700	<b>5010 PEARSON PL</b>	ACT ABATE	30	Violation Inspection - PS	10/18/2018
Original Complaint: Type: Property Violations - Tall Grass and Weeds						<u>Source: HUB</u>	

Description:  
Grass is very high in the front yard and has not been mowed in the backyard for Weeks.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189897	09/24/18	16200000200	<b>248 TUSCULUM RD</b>	ACT ABATE	30	Violation Inspection - PS	10/18/2018
Original Complaint: High grass/weeds						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190021	09/25/18	16206028500	<b>186 TOWNES DR</b>	PENDING	30	Initial Violation Neighborhood	09/26/2018
Original Complaint: Parking in grass						<u>Source: NEIGHBORHOOD NOTIFICATION</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190035	09/25/18	16206030800	<b>191 OLD TUSCULUM RD</b>	PENDING	30	Initial Violation Neighborhood	09/26/2018
Original Complaint: High grass/weeds						<u>Source: NEIGHBORHOOD NOTIFICATION</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190037	09/25/18	16206024200	<b>213 DELVIN DR</b>	PENDING	30	Initial Violation Neighborhood	09/26/2018
Original Complaint: High grass/weeds						<u>Source: NEIGHBORHOOD NOTIFICATION</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190038	09/25/18	16206023900	<b>220 DELVIN DR</b>	PENDING	30	Initial Violation Neighborhood	09/26/2018
Original Complaint: High grass/weeds						<u>Source: NEIGHBORHOOD NOTIFICATION</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190039	09/25/18	16206031000	<b>226 DELVIN DR</b>	PENDING	30	Initial Violation Neighborhood	09/26/2018
Original Complaint: Parking in grass						<u>Source: NEIGHBORHOOD NOTIFICATION</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188505	09/04/18	16213019200	<b>917 ILAWOOD DR</b>	ACT ABATE	31	Violation Inspection - PS	10/08/2018
Original Complaint: IMV-Truck in driveway						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188508	09/04/18	16213019100	<b>913 ILAWOOD DR</b>	ACT ABATE	31	Violation Inspection - PS	10/08/2018
Original Complaint: POG,IMV Bk Lexus						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188510	09/04/18	16213011200	<b>405 CEDARMONT DR</b>	ACT ABATE	31	Violation Inspection - PS	10/05/2018
Original Complaint: POG						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188515	09/04/18	17301013300	<b>600 CEDARMONT DR</b>	ACT ABATE	31	Violation Inspection - PS	10/04/2018
Original Complaint: POG						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188519	09/04/18	173010A00200CO	<b>513 CEDARMONT DR</b>	ACT ABATE	31	Violation Inspection - PS	10/08/2018
Original Complaint: High grass						<u>Source: INSPECTOR REPORTED</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188522	09/04/18	16213011100	<b>401 CEDARMONT DR</b>	ACT ABATE	31	Violation Inspection - PS	10/08/2018
Original Complaint: JTD wood in back,imv						<u>Source: INSPECTOR REPORTED</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188717	09/05/18	17301008400	<b>235 CEDARVIEW DR</b>	ACT ABATE	31	Violation Inspection - PS	10/12/2018
Original Complaint: High grass/weeds						<u>Source: HUB</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189057	09/12/18	182060A21500CO	<b>8272 RAMSTONE WAY</b>	ACT ABATE	31	Violation Inspection - PS	10/08/2018
Original Complaint: Type: Property Violations - Tall Grass and Weeds						<u>Source: HUB</u>	

Description:

Lawn is over 12 inches tall and this is not the first time this is happened this year

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189103	09/12/18	16213018500	<b>417 CEDARVIEW DR</b>	ACT ABATE	31	Violation Inspection - PS	10/12/2018
Original Complaint: High grass & weeds						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189128	09/13/18	17301016000	<b>205 CEDARVIEW DR</b>	ACT ABATE	31	Violation Inspection - PS	10/05/2018
Original Complaint: Type: Property Violations - Junk and Debris						<u>Source: HUB</u>	

Description:

Dresser out near curve. Has been there for nearly a month. Double check this address. I'm not sur who's property line this is.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189531	09/17/18	16210021000	<b>532 MICHELE DR</b>	ACT ABATE	31	Violation Inspection - PS	10/16/2018
Original Complaint: Junk trash and high grass.						<u>Source: EMAIL</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189679	09/19/18	17301020500	<b>1206 WESTRIDGE CT</b>	ACT VEHROW	31	Violation Inspection CAR - PS	10/04/2018

Original Complaint: Type: Public Safety - Abandoned Vehicles  
Source: HUB

Description:  
 abandoned white SUV parked on side of road, across from this address, parked about 4 weeks. Ta  
 are out of date

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189745	09/20/18	17301002700	<b>204 CEDARCREEK PL</b>	ACT ABATE	31	Violation Inspection - PS	10/22/2018

Original Complaint: Inoperable vehicles; running a business from residence  
Source: PHONE

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189754	09/20/18	173040B00900CO	<b>6109 BLUE HOLE CT</b>	PENDING	31	Violation Inspection - PS	10/02/2018

Original Complaint: commercial vehicle at the property  
Source: PHONE

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189854	09/23/18	17301004200	<b>637 MONTE CARLO DR</b>	ACT VEHROW	31	Violation Inspection CAR - PS	10/01/2018

Original Complaint: IMV on ROW  
Source: INSPECTOR REPORTED

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189893	09/24/18	182060A35100CO	<b>8461 LAWSON DR</b>	ACT VEHROW	31	Violation Inspection CAR - PS	10/05/2018

Original Complaint: Type: Public Safety - Abandoned Vehicles  
Source: HUB

Description:  
 Vehicle sitting in front of house at the curb and has not moved for weeks. Has 2 flat tires.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189919	09/24/18	16300032100	<b>1157 BELL RD</b>	PENDING	31		

Original Complaint: Apt 208, Victoria Mayles 901-500-8822, Ceiling fell in, ongoing leak  
Source: PHONE

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189955	09/24/18	16213019900	<b>928 ILAWOOD DR</b>	ACT ABATE	31	Violation Inspection - PS	10/18/2018
Original Complaint: Permit required for detached, jtd, Taco Trk						<u>Source:</u> EMAIL	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189982	09/25/18	173090B13900CO	<b>2709 AMBER CREST CT</b>	PENDING	31	Initial Violation Inspection - PS	09/26/2018
Original Complaint: Type: Public Safety - Abandoned Vehicles						<u>Source:</u> HUB	

Description:

The car has been sitting in the same spot for 4 weeks, parked on the wrong side of the street. No one has moved the car in almost a month.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189998	09/25/18	16213016800	<b>817 ILAWOOD CT</b>	PENDING	31	Initial Violation Inspection - PS	09/26/2018
Original Complaint: High grass/weeds						<u>Source:</u> PHONE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190019	09/25/18	16205029700	<b>5418 EULALA DR</b>	PENDING	31	Initial Violation Neighborhood	09/26/2018
Original Complaint: Protective treatment. Fascia						<u>Source:</u> NEIGHBORHOOD NOTIFICATI	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190020	09/25/18	16210015700	<b>505 AMELIA CT</b>	PENDING	31	Initial Violation Neighborhood	09/26/2018
Original Complaint: High grass/weeds						<u>Source:</u> NEIGHBORHOOD NOTIFICATI	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190090	09/26/18	173040A31100CO	<b>808 OAK SPRINGS CT</b>	PENDING	31	Initial Violation Inspection - PS	09/27/2018

Original Complaint: Type: Property Violations - Junk and Debris Source: HUB

Description:  
 AFZAAL LODHI  
 808 OAK SPRINGS COURT  
 CANE RIDGE, TN 37013

The HOA has requested that the homeowner clean up this massive brush pile from behind their home. They have ignored the requests from the HOA. It has been there for well over 6 months. We informed them that brush pickup was coming and to please place it on the street for them to remove. They obviously didn't do this. We need codes to help us get this eyesore removed.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190281	09/28/18	16213007000	<b>240 CEDARCREEK DR</b>	PENDING	31	Initial Violation Inspection - PS	09/29/2018

Original Complaint: Type: Public Safety - Abandoned Vehicles Source: HUB

Description:  
 Multiple unregistered or wrong tagged vechiles in yard and street.

Additional Comments:

**Master RFS Detail Report**

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190295	09/28/18	18200012700	<b>13572 OLD HICKORY BLVD</b>	PENDING	31	Initial Violation Inspection - PS	09/29/2018

Original Complaint: Type: Property Violations - Residential Complaint Source: HUB

Description:

The new neighbors moved in next door to us at 13572 Old Hickory Blvd., in early August 2018, and started a dog training business on the property they are renting (including having a professionally-installed \$6,000 fence around part of the yard completed on 8/24/18, with the inside the double garage being converted to a kennel space with multiple dog crates). They have been keeping several dogs on the property during the training process, and in some cases intend to sell the dogs after they are trained. We know this is a violation of Codes. We often hear loud barking at all hours when the dogs are outside. We are requesting a Metro Codes official to investigate this illegal business and ultimately shut it down.

The parcel I.D. is 18200012700, and the property is owned by David and Kendra Schenkel, who are renting it to the people who have started the dog training business.

Thank you,  
 Brant and Patricia Miller  
 13566 Old Hickory Blvd.  
 Antioch, TN 37013

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189451	09/17/18	149110A08800CO	<b>1328 RICE HILL CIR</b>	ACT ABATE	32	Violation Inspection - PS	10/11/2018

Original Complaint: Type: Property Violations - Junk and Debris Source: HUB

Description:

This property has unsanitary and unsafe trash, junk and debris scattered on its lawn from a tenant that moved out. It has been there for over a week and we are afraid that it is going to attract rats or other rodents that will infect neighboring residences.

Additional Comments:

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189545	09/18/18	16300010000	<b>727 BELL RD</b>	ACT ABATE	32	Violation Inspection - PS	10/05/2018
Original Complaint: Type: Property Violations - Residential Complaint						<u>Source:</u> HUB	

Description:

Caller states the dumpsters have not been emptied in weeks. The compactors are not working and have not been for several weeks.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189663	09/19/18	16300028700	<b>5400 BELL FORGE LN E</b>	ACT ABATE	32	Violation Inspection - PS	10/16/2018
Original Complaint: High grass/weeds						<u>Source:</u> PHONE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189930	09/24/18	149110A05400CO	<b>1484 RICE HILL CIR</b>	ACT ABATE	32	Violation Inspection - PS	10/23/2018
Original Complaint: Type: Property Violations - Tall Grass and Weeds						<u>Source:</u> HUB	

Description:

The grass at this house is really tall.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190148	09/26/18	149110A05900CO	<b>1417 RICE HILL CIR</b>	PENDING	32	Initial Violation Inspection - PS	10/02/2018
Original Complaint: Type: Property Violations - Cars Parked On Lawn						<u>Source:</u> HUB	

Description:

The owners seem to be running a business and have all the work vehicles parked at the property a on the street.

Additional Comments:

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190170	09/27/18	175060A07100CO	<b>5068 PRESERVE BLVD</b>	PENDING	32	Initial Violation Inspection - PS	09/28/2018
Original Complaint: Type: Public Safety - Abandoned Vehicles						<u>Source: HUB</u>	

Description:

This abandoned motor vehicle is in an obvious state of disrepair and has been left unattended on public property for more than a month.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190177	09/27/18	162160E00300CO	<b>701 BELL TRACE CV</b>	PENDING	32	Initial Violation Inspection - PS	09/28/2018
Original Complaint: Type: Property Violations - Residential Complaint						<u>Source: HUB</u>	

Description:

Cleaning service is headquarters in this house. Workers meet here to get assignments then go out in groups in company cars to clean. they leave their personal vehicles at the house. Neighbors are tired of the extra traffic this business brings into the neighborhood!!!

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188997	09/11/18	164120A05300CO	<b>3316 WEATHERSTONE CV E</b>	ACT ABATE	33	Violation Inspection - PS	10/12/2018
Original Complaint: Type: Property Violations - Cars Parked On Lawn						<u>Source: HUB</u>	

Description:

Cars parked in yard. Dilapidated vehicles and junk in driveway. Appears to be trying to run a towing service off of their driveway. Loud and unkempt. Needs attention.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189019	09/11/18	15007041400	<b>3344 TOWNE VILLAGE RD</b>	ACT ABATE	33	Violation Inspection - PS	10/15/2018
Original Complaint: Dilapidated fence						<u>Source: PHONE</u>	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189174	09/13/18	15007024000	<b>3245 ANDERSON RD</b>	ACT ABATE	33	Violation Inspection - PS	10/05/2018
Original Complaint: High grass & weeds						<u>Source:</u> PHONE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189201	09/13/18	15003009000	<b>3308 TIMBER TRL</b>	ACT ABATE	33	Violation Inspection - PS	10/01/2018
Original Complaint: Parking in the grass						<u>Source:</u> PHONE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189440	09/17/18	16514014800	<b>4877 PEPPERTREE DR</b>	ACT ABATE	33	Violation Inspection - PS	10/02/2018
Original Complaint: bldg. permit/debris						<u>Source:</u> INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189835	09/21/18	15007034800	<b>3313 COUNTRY RIDGE DR</b>	ACT ABATE	33	Violation Inspection - PS	10/15/2018
Original Complaint: JTD, IMV, POG, HGW						<u>Source:</u> INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189836	09/21/18	150120B00800CO	<b>1501 KENTON CT</b>	ACT ABATE	33	Violation Inspection - PS	10/15/2018
Original Complaint: Type: Property Violations - Residential Complaint Description: The residents at this address have had multiple vehicles with expired tags parked on the street or in their driveway since at least March of this year. The HOA of this community has sent the owner 4 letters this year about this code violation and no action has been taken by the residents yet. On the last inspection a Pontiac Azteck and a 4 door sedan were parked on the street and a black BMW in the drive way, all with expired tags. Additional Comments:						<u>Source:</u> OTHER SOURCE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189839	09/21/18	183050A38200CO	<b>7109 SMOKEY HILL RD</b>	ACT VEHROW	33	Violation Inspection CAR - PS	10/05/2018
Original Complaint: Type: Other - Other						<u>Source:</u> HUB	

Description:

Two vehicles on the street at this address. One has tags expired on 03/18 and the other has no tags whatsoever. These have been at this location for several weeks.

Additional Comments:

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190000	09/25/18	15000020700	<b>3131 ANDERSON RD</b>	ACT ABATE	33	Violation Inspection - PS	10/18/2018
Original Complaint: Type: Property Violations - Residential Complaint						<u>Source:</u> HUB	

Description:  
Working on vehicles at house. Inoperable vehicles.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190067	09/25/18	183050A38200CO	<b>7109 SMOKEY HILL RD</b>	ACT VEHROW	33	Violation Inspection CAR - PS	10/05/2018
Original Complaint: IMV on ROW Chrysler 300 Wht						<u>Source:</u> EMAIL	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190258	09/28/18	15003008900	<b>3304 TIMBER TRL</b>	PENDING	33	Initial Violation Inspection - PS	09/29/2018
Original Complaint: Type: Property Violations - Junk and Debris						<u>Source:</u> HUB	

Description:  
The residence has trash and junk all around their shed that constantly blows into our yard.

Additional Comments:

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1190262	09/28/18	164070A15700CO	<b>1632 HIGHWATER DR</b>	ACT ABATE	33	Violation Inspection - PS	10/26/2018
Original Complaint: IMV						<u>Source:</u> INSPECTOR REPORTED	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189851	09/21/18	14603001100	<b>700 BRINDLEY DR</b>	ACT ABATE	34	Violation Inspection - PS	10/26/2018
Original Complaint: inoperable vehicles, boats parked in front yard, inoperable RV						<u>Source:</u> PHONE	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188529	09/04/18	11300006400	<b>8131 OLD CHARLOTTE PIKE</b>	ACT ABATE	35	Violation Inspection - PS	10/05/2018
Original Complaint: Inoperable vehicles on property						<u>Source:</u> Codes Online	

Master RFS Detail Report

Date Range: 09/01/2018 - 09/30/2018

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188737	09/05/18	14214004100	<b>741 HARPETH PKWY W</b>	ACT ABATE	35	Violation Inspection - PS	10/05/2018
Original Complaint: fence, imv, pool						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1188893	09/10/18	155070A01100CO	<b>7172 FORREST OAKS DR</b>	ACT ABATE	35	Violation Inspection - PS	10/12/2018
Original Complaint: May have built the fence too high						<u>Source: PHONE</u>	

<u>Incident No</u>	<u>Date</u>	<u>Map/Parcel</u>	<u>Address/Other Location</u>	<u>Status</u>	<u>District</u>	<u>NEXT ACT</u>	<u>TARGET</u>
18-1189459	09/17/18	11200007600	<b>8517 OLD CHARLOTTE PIKE</b>	ACT ABATE	35	Violation Inspection - PS	10/09/2018
Original Complaint: Type: Property Violations - Junk and Debris						<u>Source: HUB</u>	

Description:  
High grass furniture in front yard for weeks

Additional Comments: